

Middleton Environmental Inc.

Environmental Consultants and Engineers

54 George Street, Babylon, NY 11702 (631) 321-4300 • Fax (631) 321-4349 middletonenvironmental.com

Phase I Environmental Site Assessment Report

MEI Project Number 17-000



Property located at 54 George Street in Babylon, New York

Sample Date

Prepared for Sample Bank



Middleton Environmental Inc.

Environmental Consultants and Engineers

54 George Street, Babylon, NY 11702 (631) 321-4300 • Fax (631) 321-4349 middletonenvironmental.com

Sample Date

Mr. Lending Officer Sample Bank Sample Address New York, NY 10000

Re: Phase I Environmental Site Assessment Report

54 George Street in Babylon, New York 11702 MEI Project #: 17-000

In accordance with our agreement, Middleton Environmental Incorporated (MEI), has performed a Phase I Environmental Assessment of the above referenced property in accordance with ASTM E 1527-13 Scope of Work. Please find a copy of the report enclosed.

We declare that to the best of our knowledge and belief, we meet the definition of Environmental professional as defined in §312.10 of 40 CFR and, we have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property. We have developed and performed all the appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.

Thank you for choosing MEI as your consultant for this project. If you have any questions, or if we can be of additional service, please contact us at 631 321 4300.

Respectfully submitted,

Middleton Environmental Incorporated

Prepared by: Donald J. Middleton Jr.

President

Table of Contents and Report Format For Phase I Environmental Site Assessment (as per ASTM E1527-13 Protocol)

1.	Executive Summary	5
2.	Introduction	
	2.1 Purpose	6
	2.2 Scope-of-Services	6
	2.3 Assumptions and Limitations	7
	2.4 Special Terms and Conditions	7
	2.5 Data Gaps	7
	2.6 Deviations	8
	2.7 Special Terms and Conditions	8
	2.8 User Reliance	8
3.	Site Description	
	3.1 Ownership and Location	9
	3.2 Improvements	9
	3.3 Current Use of the Property	9
	3.4 Services, Utilities and Roadways	10
	3.5 Adjoining Property Usage	10
4.	User Provided Information 4.1 Environmental Pre-Survey Questionnaire. 4.2 Title Records 4.3 Environmental Liens or Activity and Use Limitations. 4.4 Specialized Knowledge. 4.5 Commonly Known or Reasonably Ascertainable Information. 4.6 Valuation Reduction for Environmental Issues. 4.7 Identification of Key Site Manager. 4.8 Reason for Performing Phase I. 4.9 Prior Environmental Reports	11 11 11 12 12 12 12 12 12
5.	Records Review 5.1 Standard Environmental Record Sources	13-17 18 19
	5.4 City Directories	20
	5.5 Vapor Encroachment Conditions	21
	5.6 Local Regulatory Agency Records	21

6.	Physical Settings	
	6.1 Topography	21
	6.2 Geology and Soils	21
	6.3 Hydrogeology and Hydrology	21
7.	Subject Property Reconnaissance	
	7.1 Methodology and Limiting Conditions	22
	7.2 Physical Observations	22-2
8.	Interviews	
	8.0 Interviews with Property Owner and/or Property Manager	25
9.	Conditions Outside the Scope of ASTM Practice E 1527-13	
	9.1 Asbestos Containing Material (ACM)	26
	9.2 Lead Based Paint	26
	9.3 Lead in Drinking Water	26
	9.4 Radon	27
	9.5 Mold	27
	9.6 Wetlands	27
10.	Findings, Opinions and Recommendations	28
11.	Signature of Environmental Professional	28
12.	Appendix	29
	12.1 Site Map	
	12.2 USGS Topographic Map	
	12.3 Site Photographs	
	12.4 Municipal Information (Assessment Department, Building Department, Housing Department)	
	12.5 Environmental Database Report and Regulatory Agency Documentation	
	12.6 Historical Research Documentation (fire insurance maps, city directories, aerial photographs, etc.)	
	12.7 Underground Storage Tank Testing and Abandonment Information	

1.0 EXECUTIVE SUMMARY

At the request of Sample Bank, Middleton Environmental Incorporated (MEI) has performed a Phase I Environmental Site Assessment (ESA) of the property located at 54 George Street in Babylon, New York, herein referred to as the Subject Property. The main objective of this ESA was to identify Recognized Environmental Conditions (RECs), Controlled Recognized Environmental Conditions (CRECs), or Historical Recognized Environmental Conditions (HRECs) in connection with the Subject Property, defined in ASTM Practice E 1527-13 as the presence or likely presence of any hazardous substances or petroleum products that indicate an existing release, a past release, or a material threat of a release. This ESA also includes a preliminary evaluation of certain potential environmental conditions that are outside the scope of ASTM Practice E 1527-13. This assessment has identified no evidence of RECs, CRECs or HRECs in connection with the Subject Property.

The Subject Property includes one (1) rectangular-shaped parcel totaling approximately 0.21 acres. The Subject Property is improved with one (1) commercial building on the Subject Property. This 3,600 square foot building has a main floor and a lower level. The main floor of the building is utilized for professional office space while the lower level contains a conference room and storage space. A review of the Village of Babylon Building Department files and Town of Babylon Department of Assessment files indicated that the building was constructed in 1930 and was originally utilized as a synagogue. The building has been recently renovated for use as an office building and the building and rear parking area occupy the majority of the parcel which is bordered by municipal walkways and right-of-ways.

Below is the Assessment Summary Table presenting our recommended actions for the Subject Property. MEI's Findings and Opinions and Recommendations for further action or investigation (if any), are presented in Section 10.0.

ASSESSMENT SUMMARY TABLE				
Assessment Component	Section(s)	Recommended Actions	Estimated Cost	
Historical Review	5.3, 5.4 & 5.5	No Further Action		
Current Occupants / Operations	3.3	No Further Action		
Hazardous Substances / Petroleum Products	7.2	No Further Action		
Drains, Sumps & Storm Water Drywells	7.2	No Further Action		
Storage Tanks	7.2	No Further Action		
PCBs	7.2	No Further Action		
Regulatory Agency / Database Review	5.1	No Further Action		
Asbestos Containing Materials	9.1	No Further Action		
Lead Based Paint	9.2	No Further Action		
Lead in Drinking Water	9.3	No Further Action		
Radon	9.4	No Further Action		
Mold	9.5	No Further Action		
Wetlands	9.6	No Further Action		

2.0 INTRODUCTION

2.1 Purpose

MEI has performed a Phase I Environmental Site Assessment (Phase I ESA) of property located at 54 George Street in Babylon, New York (fictitious Subject Property). The purpose of this Phase I Environmental Site Assessment (Phase I ESA) is to investigate and identify Recognized Environmental Conditions (RECs), Controlled Recognized Environmental Conditions (CRECs), or Historical Recognized Environmental Conditions (HRECs) associated with the Subject Property and/or surrounding property. Recognized Environmental Conditions, as defined in the ASTM Standard Practice E 1527-13, including the following:

The presence or likely presence of any hazardous substances or petroleum products on a property under conditions that indicate an existing release, a past release, or a material threat of a release of any hazardous substances or petroleum products into structures on the property or into the ground, groundwater, or surface water of the property. The term includes hazardous substances or petroleum products even under conditions in compliance with laws. The term is not intended to include de minimis conditions that generally do not present a material risk of harm to public health or the environment and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies.

For the purpose of this Phase I ESA, *recognized environmental conditions (REC's)*, may also include the presence or likely presence of other conditions as noted in the Scope of Services.

2.2 Scope of Services

This ESA was conducted utilizing a standard of good commercial and customary practice that was consistent with the ASTM Practice E 1527-13. Any significant scope-of-work additions, deletions or deviations to ASTM Practice E 1527-13 are noted below or in the corresponding sections of this report. The scope-of-work for this assessment included an evaluation of the following:

- Physical characteristics of the Subject Property through a review of referenced sources for topographic, geologic, soils and hydrologic data.
- Subject Property history through a review of referenced sources such as land deeds, fire insurance maps, city directories, aerial photographs, prior reports and interviews.
- Current Subject Property conditions, including observations and interviews regarding the following: the presence or absence of hazardous substances or petroleum products; generation, treatment, storage, or disposal of hazardous, regulated, or biomedical waste; equipment that utilizes oils which potentially contain PCBs; and storage tanks (aboveground and underground).
- Usage of surrounding area properties and the likelihood for releases of hazardous substances and petroleum products (if known and/or suspected) to migrate onto the Subject Property.
- Information in referenced environmental agency databases and local environmental records, within specified minimum search distances.
- Past ownership through a review of available prior reports and local municipal file review.
 The scope-of-work also included consideration of the following potential environmental conditions that are outside the scope of ASTM Practice E 1527-13: asbestos-containing materials (ACM), lead-based paint (LBP), lead in drinking water, radon, mold, and wetlands.

2.3 Assumptions and Limitations

There is a possibility that even with the proper application of these methodologies there may exist on the Subject Property conditions that could not be identified within the scope of the assessment or which were not reasonably identifiable from the available information. The information and conclusions contained in this report are based upon work undertaken by trained professional in accordance with generally accepted engineering and scientific practices current at the time the work was performed. MEI believes that the information obtained from the record review and the interviews concerning the Subject Property is reliable. However, MEI cannot and does not warrant or guarantee that the information provided by these other sources is accurate or complete. The methodologies of this assessment are not intended to produce all inclusive or comprehensive results, but rather to provide the User with information relating to the Subject Property. Due to the nature of this investigation and data available, MEI cannot warrant against undiscovered environmental liabilities. Should any additional information become available which differs significantly from our understanding of conditions or findings represented in this report, we request that this information be supplied to MEI so that MEI may reassess the conclusions provided in this report (if necessary).

The findings, opinions and conclusions of this report contain the limitations inherent in these methodologies that are referred to in ASTM E 1527-13. Specific limitations and exceptions to this ESA are set forth below:

Historical and environmental information pertaining to the Subject Property has been included in this report to the extent that such information is "reasonably ascertainable" as defined in the above-referenced standard practice and in accordance with the project specific timeframes.

MEI reviewed an environmental database search report. MEI's conclusions based on the search report are limited to the accuracy of that report. To the extent possible, MEI's field observations are used to verify the information or identify errors and inconsistencies in the search report regarding the listed facilities in the immediate vicinity of the Subject Property.

With respect to conditions outside the scope of the ASTM Standard, MEI's observations are limited to physical observations and a review of published data. Unless otherwise stated, no sampling for Asbestos Containing Materials, Lead Based Paint, Drinking Water, Radon, Mold or Wetlands was conducted.

2.4 Special Terms and Conditions

This Phase I Environmental Site Assessment ("the report") has been prepared to assist Sample Bank in its underwriting of a proposed mortgage loan or financing on the Subject Property. This report can be relied upon by only the parties stated in the transmittal letter at the front of this report. MEI's liability to a purchaser wishing to use this report is limited to the cost of the report. Amendments to MEI's limitations as stated herein that may occur after issuance of the report are considered to be included in this report. Payment for the report is made by, and MEI's contract and report extends to Sample Bank only, in accordance with MEI Terms and Condition and the MEI Scope of Work.

2.5 Data Gaps

Any data gaps identified herein, as defined by ASTM Practice E 1527-13 are not considered to have significantly affected the ability to identify Recognized Environmental Conditions in connection with the Subject Property and do not alter the conclusions of this report.

2.6 Deviations

No deviations from the recommended scope of ASTM Standard E 1527-13 were performed as part of this Phase I ESA with the exception of any additional services noted in Section 2.2 Scope of Services.

2.7 User Reliance

This Phase I Environmental Site Assessment Report is for the benefit of Sample Bank and this report may not be relied upon by any other person or entity without the written consent of MEI.

Only if written agreement has been executed granting the right to utilized this report, no third party which obtains all of portion of this report shall have any rights of recourse or recovery under any course of action against MEI, its officers, employees, vendors, successors or assigns.

Reliance is provided in accordance with MEI's Standard Phase I Environmental Site Assessment Contract and this report is for the benefit of Sample Bank and its successors and assigns. This report has no other purpose and may not be relied upon by any other person or entity without the written consent of MEI.

3.0 SITE DESCRIPTION

3.1 Ownership and Location

According to the Town of Babylon Department of Assessment files, the property was identified as District 102, Section 10, Block 2 Lot 24 and the Subject Property is owned by TLC Realty of Babylon LLC.

The property is located at 54 George Street in Babylon, NY. MEI did not identify any prior owners or occupants of potential environmental concern in the property records obtained from the NYC Department of Finance.

3.2 Improvements

The Subject Property includes one (1) rectangular-shaped parcel totaling approximately 0.21 acres. The Subject Property is improved with one (1) commercial building. This 3,600 square foot building has a main floor and a lower level. A review of the Village of Babylon Building Department files and Town of Babylon Department of Assessment files indicated that the building was constructed in 1930 and was originally utilized as a synagogue. The building and rear parking area occupy the majority of the parcel which is bordered by municipal walkways and right-of-ways.

3.3 Current Use of the Subject Property

At the time of inspection, the main floor of the building is utilized for professional office space while the lower level contains a conference room and storage space.

3.4 Services, Utilities and Roadways

Street Address(es): 54 George Street

City and State: Babylon, New York

County: Suffolk

Owner: TLC Realty of Babylon LLC.

Property Size: 0.21 acres

Access Roadway to site: George Street to the north of the Subject Property

Site Use: One (1) single story plus lower level commercial building

Occupants: Middleton Environmental Inc.

Electricity Provider: PSEG LI

Natural Gas Provider: National Grid

Fuel Oil Provider: N/A

Potable Water: Municipal Water Supply

Sewer Services: Municipal Sewer System

Heating System: The building is heated by a natural gas fired heating system and there are overhead

heating units inside the building.

3.5 Adjoining Properties

The current use of the adjoining properties is commercial and residential. The Subject Property borders are as follows:

North - The property is bordered to the north by George Street and a post office building.

South - The property is bordered to the south by several houses.

East - The property is bordered to the east by a multi-tenant office building.

West - The property is bordered to the west by a house.

4.0 USER PROVIDED INFORMATION

4.1 Environmental Pre-Survey Questionnaire

Pursuant to ASTM E 1527-13, MEI requested the following site information from the User of this report and from the site contact. The following section summarizes information provided by Sample Bank with regard to this Phase I Environmental Site Assessment.

ІТЕМ	PROVIDED BY USER	NOT PROVIDED BY USER	DISCUSSED BELOW	DOES NOT APPLY
4.1 Environmental Pre-survey Questionnaire		X		
4.2 Title Records		X		
4.3 Environmental Liens or Activity and Use Limitation		X		
4.4 Specialized Knowledge		X		
4.5 Commonly Known or Reasonably Ascertainable Information		X		
4.6 Valuation Reduction for Environmental Issues		X		
4.7 Identification of Key Site Manager		X		
4.8 Reason for Performing Phase 1 ESA	X			
4.9 Prior Environmental Reports		X		

4.2 Title Records

Title record information associated with the Subject Property has not been provided to MEI by Sample Bank. Land title records provide information on previous ownership of a property. Typically, deeds signifying transfer of a land parcel are recorded in county files and can be researched to determine the identity of past owners. A "chain of title" is a continuous record of ownership for a specific parcel. A 50-year chain of title search was not included in the scope of work for this assessment.

4.3 Environmental Liens or Activity and Use Limitation

The property owner/user/key site personnel did not report any Environmental Liens or Activity/Use Limitations on the site. An environmental lien search was not included in the scope of work of this assessment and therefore was not performed. However, if the findings of a lien search performed by any other party does reveal the presence of an environmental related lien on the subject property, this information should be forwarded to MEI for review, and any significant findings will be added to this assessment as an addendum to this report.

4.4 Specialized Knowledge

Sample Bank provided no specialized knowledge that is material to Recognized Environmental Conditions (RECs), Controlled Recognized Environmental Conditions (CRECs), or Historical Recognized Environmental Conditions (HRECs). MEI was not provided with or made aware of previous environmental assessments or other documentation that is material to RECs, CRECs or HRECs in connection with the Subject Property, except as presented in Section 4.3 of this report.

4.5 Commonly Known or Reasonably Ascertainable Information

Sample Bank has provided no commonly known or reasonably ascertainable information within the local community about the Subject Property that is material to Recognized Environmental Conditions in connection with the Subject Property.

4.6 Valuation Reduction for Environmental Issues

Sample Bank has provided no information regarding valuation reduction for environmental issues in connection with the Subject Property.

4.7 Identification of Key Site Manager

Sample Bank provided contact information for the Subject Property owner, manager and/or occupants. The Contact person for site access was the Property Manager.

4.8 Reason for Performing Phase I ESA Report

The purpose of this Phase I Environmental Site Assessment (ESA) was to identify existing or potential Recognized Environmental Conditions, Controlled Recognized Environmental Conditions or Historical Recognized Environmental Conditions (as defined by ASTM Standard E-1527-13) in connection with the Subject Property. This ESA was also performed to permit the User to satisfy one of the requirements to qualify for the innocent landowner, contiguous property owner, or bona fide prospective purchaser limitations on scope of Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) (42 U.S.C. §9601) liability (hereinafter, the "landowner liability protections," or "LLPs"). ASTM Standard E-1527-13 constitutes "all appropriate inquiry into the previous ownership and uses of the property consistent with good commercial or customary practice" as defined at 42 U.S.C. §9601(35)(B).

4.9 Prior Environmental Reports

No previous environmental reports were supplied with regard to the Subject Property.

5.0 RECORDS REVIEW

5.1 Standard Environmental Record Sources

Information from standard Federal and state environmental record sources was provided through FirstSearch Technology Corporation (FirstSearch). Data from governmental agency lists are updated and integrated into one database, which is updated as these data are released. This integrated database also contains postal service data in order to enhance address matching. Records from one government source are compared to records from another to clarify any address ambiguities. The demographic and geographic information available provides assistance in identifying and managing risk. The accuracy of the geocoded locations is approximately +/-300 feet.

In some cases, location information supplied by the regulatory agencies is insufficient to allow the database companies to geocode facility locations. These facilities are listed under the unmappables section within the FirstSearch report. A review of the unmappable facilities indicated that none of these facilities are within the ASTM minimum search distance from the Site.

Regulatory information from the following database sources regarding possible recognized environmental conditions, within the ASTM minimum search distance from the Site, was reviewed. Specific facilities are discussed below if determined likely that a potential recognized environmental condition has resulted at the Site from the listed facilities (see appendix 12.5 for Environmental Database Report).

The following table provides a summary of the findings of the environmental database report. Specific properties identified within the database report are further discussed below.

SUMMARY OF FEDERAL, STATE, AND TRIBAL AGENCY DATABASE FINDINGS				
Regulatory Database	Approximate Minimum Search Distance	Subject Property Listed	Off-site Listings Within Search Distance	
Federal NPL Sites	1.0 mile	No	0	
Federal Delisted NPL Sites	0.5 mile	No	0	
Federal CERCLIS Sites	0.5 mile	No	0	
Federal CERCLIS NFRAP Sites	0.5 mile	No	0	
Federal RCRA CORRACTS Sites	1.0 mile	No	0	
Federal RCRA Generators Sites	Property & Adjoining	No	0	
Federal RCRA Non-CORRACTS TSD Sites	0.5 mile	No	0	
Federal Engineering / Institutional Control Sites	Property & Adjoining	No	0	
Federal ERNS Sites	Subject Property	No	0	
State and Tribal equivalent NPL Sites	1.0 mile	No	2	
State and Tribal equivalent CERCLIS Sites	0.5 mile	No	0	
State and Tribal Leaking Storage Tank Sites	0.5 mile	No	18	
State and Tribal Spills Sites	Property & Adjoining	No	0	
State and Tribal Landfill or Solid Waste Disposal Sites	0.5 mile	No	0	
State and Tribal Registered Storage Tank Sites	Property & Adjoining	No	0	
State and Tribal Engineering / Institutional Control Sites	Property & Adjoining	No	0	
State and Tribal Voluntary Cleanup Sites	0.5 mile	No	0	
State and Tribal Brownfield Sites	0.5 mile	No	0	

• Federal National Priority List (NPL) Sites

The National Priorities List (NPL) is the Environmental Protection Agency (EPA) database of uncontrolled or abandoned hazardous waste sites identified for priority remedial actions under the Superfund Program. The Subject Property is not listed as a Federal NPL site. No Federal NPL sites are located within a mile radius of the Subject Property.

Federal Delisted National Priority List (NPL) Sites

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425(e), sites may be deleted from the NPL where no further response is appropriate. The Subject Property is not listed as a Federal Delisted NPL site. No Federal Delisted NPL sites are located within a mile radius of the Subject Property.

Federal CERCLIS Sites

The Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) list is a compilation of sites that the EPA has investigated or is currently investigating for a release or threatened release of hazardous substances. The Subject Property is not listed as a Federal CERCLIS site. No Federal CERCLIS sites are listed within a half mile radius of the Subject Property.

Federal CERCLIS NFRAP Sites

The CERCLIS No Further Remedial Action Planned (NFRAP) List is a compilation of sites that the EPA has investigated, and has determined that the facility does not pose a threat to human health or the environment. The Subject Property is not listed as a Federal CERCLIS-NFRAP site. There were no Federal CERCLIS NFRAP sites listed within a half mile radius of the Subject Property.

Federal RCRA CORRACTS Sites

RCRA Corrective Action Tracking System (CORRACTS) is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information regarding sites that generate, transport, store, treat, and/or dispose of hazardous waste as defined by RCRA. The RCRA-CORRACTS database identifies Transportation, Storage or Disposal (TSD), facilities that have conducted, or are currently conducting, corrective action(s) as regulated under RCRA. The Subject Property was not identified on the RCRA CORRACTS site list. There were no RCRA CORRACTS sites within a mile radius of the Subject Property.

Federal RCRA Hazardous Waste Generators Sites

Hazardous waste generators tracked under the Resource Conservation and Recovery Act (RCRA) are classified as either Large Quantity Generators (LQGs), Small Quantity Generators (SQGs), or Conditionally Exempt Small Quantity Generators (CESQGs). A RCRA-LQG is a facility that generates over 1,000 kilograms (Kg) of hazardous waste. A RCRA-SQG is a facility that generates between 100 Kg and 1,000 Kg of hazardous waste per month while a RCRA-CESQG generates less than 100 Kg of hazardous waste per month. The Subject Property is not listed as a Federal RCRA Hazardous Waste Generator site. None of the adjoining properties are listed as Federal RCRA Hazardous Waste Generator sites.

Federal RCRA non-CORRACTS TSD Sites

RCRA non-CORRACTS Treatment, Storage and/or Disposal (TSD) sites are required to register hazardous waste activity under the Resource Conservation and Recovery Act (RCRA). The Subject Property is not listed as a Federal RCRA non-CORRACTS TSD site. The Subject Property is not listed as a Federal RCRA non-CORRACTS TSD Site. There was one (1) Federal RCRA non-CORRACTS TSD site within a mile radius of the Subject Property (the Pfizer Inc. site listed previously).

Federal Engineering Control / Institutional Control Sites

The completion of site cleanup activities may include the implementation of engineering controls or institutional controls as part of the response action. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls. The Subject Property is not listed as a Federal Engineering Control or Institutional Control Site. There were no Federal Engineering Control or Institutional Control Sites within a half mile radius of the Subject Property.

Federal Emergency Response Notification System (ERNS) Sites

ERNS is a national database used to collect information regarding reported releases of petroleum products and/or hazardous substances. The database contains information from spill reports submitted to Federal agencies, including the EPA, the U.S. Coast Guard, the National Response Center, and the U.S. Department of Transportation. A review of this database was conducted in order to determine whether any spills or incidents involving releases of hazardous substances or petroleum products have occurred at the Subject Property. The Subject Property is not listed as a Federal ERNS site.

• State and Tribal equivalent NPL Sites

State and Tribal equivalent NPL databases were searched for sites located within 1.0 mile of the Subject Property. The Subject Property is not listed as a State and Tribal equivalent NPL Site. There were two (2) STATE National Priorities List (NPL), sites within a mile radius of the Subject Property. These sites would not have an apparent adverse impact on the Subject Property based upon the distance to the Subject Property and direction of groundwater flow.

• State and Tribal equivalent CERCLIS Sites

State and Tribal equivalent CERCLIS databases were searched for sites located within 0.5 mile of the Subject Property. The Subject Property is not listed as a State and Tribal equivalent CERCLIS Site. There were no State and Tribal equivalent CERCLIS sites within a half mile radius of the Subject Property.

• State and Tribal Leaking Storage Tank Sites

Leaking Storage Tank Sites are properties where releases of hazardous substances or petroleum products from underground storage tanks (USTs) and/or aboveground storage tanks (ASTs) have been identified and reported to state, tribal, or local agencies.

The Subject Property is not listed as a State and Tribal Leaking Storage Tank site. However, 18 sites located within 0.5 mile of the Subject Property were identified as State and Tribal Leaking Storage Tank Sites. Seventeen (17) of these sites are located greater than .125 of a mile from the Subject site. The one (1) remaining site located less than .125 of a mile from the Subject Property is located .069 of a mile northeast of the Subject Property at 123 Cooper Street. This site has been fully remediated and the NYSDEC Spill file pertaining to this incident has been closed. None of these LUST sites would have an apparent adverse impact on the Subject Property due to the distance to the Subject Property and direction of groundwater flow.

• State and Tribal Spills Sites

A review of the State and Tribal Spills database was conducted in order to determine whether any spills or incidents involving releases of hazardous substances or petroleum products have occurred at the Subject Property. The Subject Property is not listed as a State and Tribal Spills site.

State and Tribal Landfill Sites and Solid Waste Disposal Sites

The State and Tribal landfill and solid waste disposal site databases identify active or inactive landfill and transfer station facilities, as well as open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites. The Subject Property is not listed as a State and Tribal landfill and solid waste disposal site. There were no State and Tribal landfill and solid waste disposal site listed within 0.5 mile of the Subject Property.

State and Tribal Registered Storage Tank Sites

The Subject Property is not listed as a State and Tribal Registered Storage Tank site. None of the adjoining Properties were identified as a State and Tribal Registered Storage Tank site.

• State and Tribal Engineering Control / Institutional Control Sites

The completion of site cleanup activities may include the implementation of engineering controls or institutional controls as part of the response action. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls. The Subject Property is not listed as a State and Tribal Engineering Control or Institutional Control Sites. No State and Tribal Engineering Control or Institutional Control Sites are listed within 0.5 mile of the Subject Property.

• State and Tribal Voluntary Cleanup Sites

The Subject Property is not listed as a State and Tribal Voluntary Cleanup site. There were no State and Tribal Voluntary Cleanup Sites listed within 0.5 mile of the Subject Property.

• State and Tribal Brownfield Sites

The Subject Property is not listed as a State and Tribal Brownfield site. There were no State and Tribal Brownfield Site listed within 0.5 mile of the Subject Property.

5.2 Sanborn Fire Insurance Maps

Historical fire insurance maps depicting the Subject Property were reviewed and are summarized in the following table. Historical fire insurance maps depicting the past usage of the Subject Property were reviewed and are summarized in the following table:

-	FIRE INSURANCE MAP SUMMARY			
Year	Issues Noted	Observations		
1000		Subject Property: The 1902 Sanborn Map shows the Subject Property as vacant land.		
1902	No	Surrounding Area: The 1902 Sanborn Map shows the presence of houses on all sides of the Subject Property.		
1904	No	Subject Property: Conditions on the Subject Property appear to be similar to those depicted on the 1902 Sanborn Map.		
1304	140	Surrounding Area: Conditions on the surrounding properties appear to be similar to those depicted on the 1902 Sanborn Map.		
		Subject Property: Conditions on the Subject Property appear to be similar to those depicted on the 1908 Sanborn Map.		
1915	No	Surrounding Area: Conditions on the surrounding properties appear to be similar to those depicted on the 1908 Sanborn Map with the exception that the house to the north of the Subject Property has been converted for use as South Side Hospital.		
1923	No	Subject Property: Conditions on the Subject Property appear to be similar to those depicted on the 1915 Sanborn Map.		
1920		Surrounding Area: Conditions on the surrounding properties appear to be similar to those depicted on the 1915 Sanborn Map.		
		Subject Property: Conditions on the Subject Property appear to be similar to those depicted on the 1923 Sanborn Map.		
1929	No	Surrounding Area: Conditions on the surrounding properties appear to be similar to those depicted on the 1923 Sanborn Map. With the exception that the building to the north of the Subject Property is now vacant.		
	No	Subject Property: The 1943 Sanborn Map shows the presence of the existing building on the Subject Property. The building is utilized as the Beth Sholom Synagogue		
1943		Surrounding Area: Conditions on the surrounding properties appear to be similar to those depicted on the 1929 Sanborn Map with the exception that the building to the north of the Subject Property has been removed.		
		Subject Property: Conditions on the Subject Property appear to be similar to those depicted on the 1943 Sanborn Map.		
1968	No	Surrounding Area: Conditions on the surrounding properties appear to be similar to those depicted on the 1943 Sanborn Map with the exception that a post office building has been constructed to the north of the Subject Property.		

5.3 Aerial Photographs

Historical aerial photographs may be used to evaluate changes in land use and to identify visible areas of potential environmental concern. A search for historical aerial photographs depicting the Subject Property and vicinity was conducted by researching available historical aerial photographs from www.historicaerials.com and other available resources. Aerial photographs depicting the Subject Property were reviewed and are summarized in the following table:

AERIAL PHOTOGRAPH SUMMARY				
Year	Issues Noted	Observations		
1954	No	Subject Property: The 1954 photograph shows the presence of the existing building on the Subject Property.		
1904		Surrounding Area: The 1954 photograph shows the Subject Property being bordered on all sides by residential buildings.		
	No	Subject Property: Conditions on the Subject Property appear to be similar to those depicted on the 1954 photograph.		
1966		Surrounding Area: Conditions on the surrounding properties appear to be similar to those depicted on the 1954 photograph with the exception that a commercial building has been constructed to the north of the Subject Property.		
1980	NT.	Subject Property: Conditions on the Subject Property appear to be similar to those depicted on the 1954 photograph.		
1900	No	Surrounding Area: Conditions on the surrounding properties appear to be similar to those depicted on the 1966 photograph.		
2004	No	Subject Property: Conditions on the Subject Property appear to be similar to those depicted on the 1980 photograph.		
2004		Surrounding Area: Conditions on the surrounding properties appear to be similar to those depicted on the 1980 photograph.		
2013	No	Subject Property: Conditions on the Subject Property appear to be similar to those depicted on the 2004 aerial photograph.		
2010		Surrounding Area: Conditions on the surrounding properties appear to be similar to those depicted on the 2004 aerial photograph.		

5.4 City Directories

Street directories are commercial publications containing names and addresses, and in many cases, occupations of the occupants of a particular community. The directories may also contain information pertaining to business processes conducted within a community search for historical street directories was conducted by MEI and EDR. Historical street directories were reviewed and are summarized in the following table. City Directory information depicting the past usage of the Subject Property was reviewed and is summarized in the following table:

	CITY DIRECTORY SUMMARY			
Year	Occupants			
1970	St. Nicholas Church			
1975	St. Nicholas Church			
1979	St. Nicholas Church			
1982	St. Nicholas Church			
1985	St. Nicholas Church			
1992	Babylon Assembly of God Church			
1995	Babylon Assembly of God Church			
1999	Babylon Assembly of God Church			
2008	Babylon Assembly of God Church			
2008	Babylon Assembly of God Church. Gateway Life Center			
2013	Gateway Life Center			

5.5 Vapor Encroachment Conditions

All readily ascertainable information including all applicable Federal, State, Tribal and local database information, historical usage information, soil and groundwater sources and information from the site reconnaissance were reviewed in order to determine if there is a possibility of a Vapor Encroachment Condition regarding the Subject Property. Based upon the results of the site reconnaissance and review of readily ascertainable information, the Vapor Encroachment Condition survey is described below:

POTENTIAL AREA OF CONCERN	RESULT
Does the Subject Property have a current contamination concern or past contamination concern?	None identified
Does the Subject Property have a suspected contamination concern?	None identified
Does an adjacent property have a current contamination concern or past contamination concern?	None identified
Does a nearby property have a have a current contamination concern or past contamination concern which may impact the Subject Property?	None identified
Does a regional groundwater contamination concern exist beneath the Subject Property?	None identified
Does the possibility exist for a vapor intrusion on the Subject Property?	None identified

Based on these current conditions, a vapor encroachment condition (VEC) is not considered a concern with regard to the Subject Property.

5.6 Local Regulatory Agency Records

Local municipal offices consulted during the completion of this assessment included the Town of Babylon Department of Assessment, Village of Babylon Building Department and the Suffolk County Department of Health Services (SCDHS). MEI did not identify documented adverse environmental conditions, violations, or complaints associated with the Subject Property in the information provided by these agencies. Similarly, MEI did not identify records of spills or releases of hazardous substances or petroleum products having occurred at the Subject Property in the information provided by these agencies.

Town of Babylon Department of Assessment/Village of Babylon Building Department

MEI reviewed information provided by the Town of Babylon Department of Assessment and the Village of Babylon Building Department. Specific information provided by this agency includes lot sizes and dimensions, building sizes, building zoning and use, and the approximate date of construction. The information provided by this agency did not identify any conditions or reported events that would indicate the presence of a recognized environmental condition in connection with the Subject Property. A review of the Town of Babylon Department of Assessment files indicated the Subject Property was developed in 1930 and was originally utilized as a synagogue. The building was converted for office usage in 2013.

Suffolk County Department of Health Services (SCDHS)

MEI submitted a Freedom of Information Request to the SCDHS in order to determine the presence of any registered underground or aboveground storage tanks or if there were any Underground Injection Control (cesspool/storm water drywell), issues regarding the Subject Property. The file review indicated that there were no SCDHS files pertaining to the Subject Property.

6.0 PHYSICAL SETTING

6.1 Topography

The Subject Property and vicinity characteristics listed below were analyzed utilizing a current USGS 7.5 Minute Topographic Map. This information is useful in determining the grade and topography of the Subject Property. The Subject Property is located at an elevation of approximately 9 feet above mean sea level (msl). The topography of the Subject Property is relatively flat and there were no slopes, depressions or rolling hills observed on the Subject Property and slopes on the Subject Property range from 0 to 3 percent. The Subject Property has been graded for residential/commercial usage.

6.2 Geology and Soils

A review of the United States Department of Agriculture Soil Conservation Service's Soil Survey of Suffolk County indicated that the soil beneath the Subject Property is Urban Land and is characterized by a non-homogeneous distribution of soil and fill types. Excavation and backfilling for building foundations, utility conduits, subway systems and other construction results in a varied subsurface profile. In this setting, estimation of local subsurface parameters such as permeability, moisture content, and organic fraction is not feasible without site-specific testing data.

6.3 Hydrogeology and Hydrology

No natural surface water bodies were identified on or adjacent to the Subject Property. The nearest surface water body is Great South Bay.

Local groundwater gradient is expected to follow surface topography; therefore, groundwater flow near the Subject Property is expected to flow in a southerly direction. Groundwater depths and flow gradients are best evaluated by a subsurface investigation involving the installation of at least three groundwater monitoring wells and precise measurements of hydrostatic pressure. Monitoring wells were not observed on the Subject Property.

7.0 SUBJECT PROPERTY RECONNAISSANCE

The Subject Property reconnaissance was conducted by Mr. Donald J. Middleton, Jr. on sample date. Mr. Middleton was accompanied by and interviewed the Subject Property Owner.

7.1 Methodology and Limited Conditions

The Subject Property reconnaissance consisted of visual and/or physical observations of the Subject Property and improvements, adjoining properties as viewed from the Subject Property boundaries, and the surrounding area based on visual observations made from adjacent public thoroughfares. Building exteriors were observed along the perimeter from the ground, unless described otherwise. The building was fully accessible during the site inspection.

7.2 Physical Observations

<u>Underground Storage Tanks</u>

There were no oil fill ports or fuel vents for any underground storage tanks noticed on the Subject Property. A review of the Suffolk County Department of Health Services (SCDHS), Industrial Waste Systems Database did not indicate the presence of any registered underground or aboveground storage tanks on the Subject Property. A review of available Sanborn Fire Insurance Maps did not indicate the presence of any buried tanks on the Subject Property. However, the building was formerly heated by oil that was stored in a 550 gallon underground storage tank. This tank was properly abandoned and prior to abandonment, the tank was prevision tested and the tank passed the precision test (no indications of any leakage).

Aboveground Storage Tanks

MEI did not observe any aboveground storage tanks at the Subject Property.

Hazardous Substances and Petroleum Products

MEI did not observe any hazardous substances or petroleum products at the Subject Property.

Non-Hazardous Substances and Petroleum Products

MEI did not observe any non-hazardous substances or petroleum products at the Subject Property.

<u>Unidentified Substances Containers</u>

MEI did not observe any unidentified substances containers at the Subject Property.

Drains or Storm Water Drywells

MEI observed one (1) floor drain inside the basement of the building. It was reported that this floor drain leads to the municipal sewer system. MEI did not observe any signs of chemical staining in the vicinity of the floor drain. MEI did not observe any floor drains inside the other accessible areas of the building. MEI observed the presence of four (4) storm water drywells at the Subject Property and none of these drywells showed any signs of chemical or petroleum staining.

Polychlorinated Biphenyls (PCB's)

Polychlorinated biphenyls (PCBs) are a chemical component of many dielectric fluids, heat transfer fluids, hydraulic fluids, lubricating oils, paints, or coatings manufactured prior to July 2, 1979 before being banned by Congress. Equipment that may potentially contain PCBs includes electrical equipment such as transformers or capacitors or hydraulically operated equipment, such as elevators, compaction equipment, or manufacturing equipment. MEI did not observe any PCB-containing equipment at the Subject Property.

Stains or Corrosion

MEI did not observe any stains or corrosion at the Subject Property.

<u>Odors</u>

MEI did not observe any strong, pungent or noxious odors at the Subject Property.

Pools of Liquid

MEI did not observe any pools of liquid at the Subject Property.

Stressed Vegetation

MEI did not observe any stressed vegetation at the Subject Property.

Stained Soil or Pavement

MEI did not observe any stained soil or pavement at the Subject Property.

Wells

MEI did not observe any irrigation wells or groundwater monitoring wells at the Subject Property.

Sumps, Pits, Ponds or Lagoons

MEI did not observe any sumps, pits, ponds or lagoons at the Subject Property.

Waste Water

MEI did not observe any improper disposal of waste water into drains, ditches or streams at the Subject Property.

Solid Wastes Disposal

All solid wastes generated on-site are carted away by a licensed waste hauler to an approved solid waste facility and are not disposed at on-site.

8.0 INTERVIEWS

8.1 Interview With Property Owner and/or Property Manager

The property owner was interviewed during the site reconnaissance and the property owner did not indicate the presence of any environmental liens or was unaware of any contamination concerns regarding the Subject Property.

9.0 CONDITIONS OUTSIDE THE SCOPE OF ASTM PRACTICE E 1527-13

9.1 Asbestos Containing Material (ACM)

Asbestos is a term used to describe a group of six naturally occurring crystalline fiber minerals. Asbestos has excellent thermal stability, a high degree of tensile strength, and has been used extensively in the textile, insulation, and building industries, particularly as a component in fireproofing, decorative coatings, insulation materials, and as reinforcement for plaster binders in building products. Asbestos-containing building materials are generally classified as friable or non-friable. Friable ACM are those which can be crumbled, pulverized, or reduced to powder by hand pressure, or by normal use or maintenance can be expected to emit asbestos fibers into the air. Non-friable ACM is a potential concern if it is damaged by maintenance work, demolition, or other activities, at which time it may be considered friable.

It should be noted that the limited visual screening survey conducted under the scope of work for this assessment does not constitute a full asbestos inspection, in which all areas of the buildings would have been thoroughly surveyed and sampled. MEI did not observe any ACM on the heating units or any of the overhead pipes inside the building. There were no signs of ACM spray-on fireproofing noticed inside the building.

9.2 Lead Based Paint (LBP)

Use of lead in household paint was banned by the U.S. Environmental Protection Agency (EPA) effective January I, 1978. The EPA and the U.S. Department of Housing and Urban Development (HUD) consider lead based paint as containing a lead concentration equal to or greater than 1.0 milligram per square centimeter (mg/cm') or 0.5% lead by weight, as defined by Title X of the 1992 Housing and Community Development Act.

MEI observed that the painted surfaces inside the building were in excellent condition, free of obvious chipping, flaking or peeling.

9.3 Lead in Drinking Water

Lead has historically been used in pipes, solder, and brass fixtures used in water distribution systems and building plumbing systems. In 1986, the USEPA banned the use of lead at concentrations exceeding 0.2% lead in solder and 8% lead in other plumbing materials. Lead in drinking water results primarily from corrosion of lead containing materials in service lines or from corrosion of lead containing materials in building plumbing such as lead solder, brass, bronze, and other lead containing alloys. The USEPA Action Level for lead in public drinking water supplies is 0.015 parts per million (ppm) or 0.015 milligrams per liter (mg/L). MEI did not observe any brass fixtures or lead fixtures at the Subject Property.

9.4 Radon

Radon is a colorless, odorless, radioactive gas. Radon comes from the natural decay of uranium that is found in nearly all soils. Radon typically moves through the ground and into building through cracks and openings in the foundation. The USEPA has developed a "Map of Radon Zones" indicating the levels of radon concentrations from testing and aerial surveys conducted in all counties in New York State. The U.S. Environmental Protection Agency's Map of Radon Zones identified the Subject Property as a radon zone Level 3. Level 3 signifies that the average predicted radon level indoors is less than 2 pico-Curies per liter and this is the lowest level in the state. This level compares favorably with the EPA action level of 4.0 pico-Curies per liter as the guideline (it should be noted that current radon information and EPA Action Levels are designated for residential spaces only. Commercial and industrial facilities are not subject to EPA's Action Level of 4 pico-Curies per liter as the guideline and definitive information concerning radon gas in an individual building can only be obtained through long term testing).

9.5 Mold

Molds are a class of fungi, and have been found to cause a variety of health problems in humans, including allergic, toxicological, and infectious responses. Molds are decomposers of organic materials, and thrive in humid environments. As such, interior areas of buildings characterized by poor ventilation and high humidity are the most common locations of mold growth. Building materials including drywall, wallpaper, baseboards, wood framing, insulation and carpeting often play host to such growth.

As part of this assessment, MEI performed a limited visual inspection for the conspicuous presence of mold. MEI observed the accessible interior areas of the Subject Property structure(s), including interior walls and ceilings of the accessible apartment unit, the corridors of the building and the meter area in the basement of the building for the presence of conspicuous mold or observed water intrusion or accumulation. This evaluation did not include a review of pipe chases or areas behind enclosed walls and ceilings. MEI did not observe conspicuous visual or olfactory indications of the presence of mold, nor did MEI observe obvious indications of significant water damage inside the accessible building areas.

9.6 Wetlands

MEI reviewed available information regarding wetlands on the Subject Property, including National Wetlands Inventory online GIS mapping. MEI additionally made general site observations for readily observable potential wetland characteristics. MEI did not observe surface water bodies or any evidence of potential wetlands on or adjacent to the Subject Property.

10.0 FINDINGS, OPINIONS AND RECOMMENDATIONS

MEI has performed this Phase I Environmental Site Assessment of the Subject Property in conformance with the scope and limitations of ASTM Standard E 1527-13. This assessment has identified no evidence of Recognized Environmental Conditions (RECs), Controlled Recognized Environmental Conditions (CRECs), or Historical Recognized Environmental Conditions (HRECs) in connection with the Subject Property.

The site reconnaissance, interviews and review of records have not found the presence or possible presence of hazardous substances or petroleum related products in, on, or at the Subject Property due to any release to the environment; under conditions indicative of a release to the environment; or under conditions that pose a material threat of a future release to the environment.

Lastly, no conditions outside of ASTM E 1527-13 were identified in connection with the Subject Property. It is the opinion of MEI that no further testing (subsurface or otherwise), is warranted on the Subject Property.

11.0 SIGNATURE OF ENVIRONMENTAL PROFESSIONALS


This Phase I Environmental Site Assessment (ESA) Report documents the research methodology used by qualified environmental professionals of MEI to identify Recognized Environmental Conditions using the scope and limitations of ASTM Standard E 1527-13.

Middleton Environmental Incorporated


Prepared by: Donald J. Middleton Jr.

President

12.0 APPENDIX 12.1 Site Map



12.2 USGS Topographic Map




12.3 Site Photographs






HEATING UNIT



LOWER LEVEL STORAGE AREA



LOWER LEVEL OFFICE AREA



CORRIDOR AREA

FORMER UST AREA



MAIN FLOOR OFFICE AREA

12.3 Site Photographs (Borders)

The current use of the adjoining properties is commercial and residential. The Subject Property borders are as follows:


North - The property is bordered to the north by George Street and a post office building.

South - The property is bordered to the south by several houses.

East - The property is bordered to the east by a multi-tenant office building.

West - The property is bordered to the west by a house.





BORDER TO THE EAST



BORDER TO THE SOUTH



BORDER TO THE WEST

12.4 Department of Finance or Assessment Information and/or local Fire and Building Department Information



Property Detail Report

For Property Located At:

54 GEORGE ST, BABYLON, NY 11702-2806



Owner Information

Owner Name: TLC REALTY OF BABYLON LLC

Mailing Address: 17 HERZOG PL, HICKSVILLE NY 11801-2801 C019

Vesting Codes:

Location Information

Legal Description: N-GEORGE ST E-BENSON S-SANDMAN W-RAYMOND

County: SUFFOLK, NY APN: 0102-010-00-02-00-024-000

Census Tract / Block: 1246.02 / 4 Alternate APN: 472000675460
Township-Range-Sect: Subdivision:

Legal Book/Page: Map Reference: 10 /

Legal Lot: 24 Tract #:

 Legal Block:
 2
 School District:
 472001

 Market Area:
 472003
 School District Name:
 BABYLON

 Neighbor Code:
 Munic/Township:
 BABYLON VLG

Owner Transfer Information

Recording/Sale Date: I Deed Type:

Sale Price: 1st Mtg Document #:

Document #:

Last Market Sale Information

Recording/Sale Date: 05/08/2006 / 04/07/2006 1st Mtg Amount/Type:

Sale Price: 1st Mtg Int. Rate/Type: /
Sale Type: 1st Mtg Document #:

Document #: 12449-82 2nd Mtg Amount/Type: /
Deed Type: DEED (REG) 2nd Mtg Int. Rate/Type: /

Transfer Document #: Price Per SqFt:
New Construction: Multi/Split Sale:

Title Company: Lender:

Seller Name: BABYLON ASSEMBLY OF GOD

Prior Sale Information

Prior Rec/Sale Date: 01/24/1989 / 01/09/1989 Prior Lender:

Prior Sale Price: \$280,000 Prior 1st Mtg Amt/Type: \$175,000 / PRIVATE PARTY
Prior Doc Number: Prior 1st Mtg Rate/Type: /

Prior Deed Type: **DEED (REG)**

Property Characteristics

Year Built / Eff: Total Rooms/Offices Garage Area: Gross Area: Total Restrooms: Garage Capacity: **Building Area:** Roof Type: Parking Spaces: Tot Adj Area: Roof Material: Heat Type: Above Grade: Construction: Air Cond: # of Stories: Foundation: Pool: Other Improvements: Exterior wall: Quality:

Basement Area: Quality.

Site Information

Zoning: Acres: 0.21 County Use:

MULTIPLE

MULTIPLE

Lot Area: 9,148 Lot Width/Depth: 50 x 189 State Use: WOLTIPLE USE/MULTIPURPOSE (480)


Land Use: MULTIPLE USES Commercial Units: Water Type:

Site Influence: Sewer Type: Building Class:

Tax Information

Total Value: \$4,400 Assessed Year: 2015 Property Tax: \$12,808.05 Land Value: \$350 Improved %: 92% Tax Area: 472003

Improvement Value: \$4,050 Tax Year: 2015 Tax Exemption: Total Taxable Value:



12.5 Environmental Database Report and Regulatory Agency Documentation

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map.	2
Detail Map.	3
Map Findings Summary	_ 4
Map Findings	. 8
Orphan Summary	. 118
Government Records Searched/Data Currency Tracking	GR-1
GEOCHECK ADDENDUM	

GeoCheck - Not Requested

Thank you for your business.Please contact EDR at 1-800-352-0050 with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2013 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

A search of available environmental records was conducted by Environmental Data Resources, Inc (EDR). The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-05) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

54 GEORGE STREET BABYLON, NY 11702

COORDINATES

Latitude (North): 40.7004000 - 40° 42' 1.44" Longitude (West): 73.3199000 - 73° 19' 11.64"

Universal Tranverse Mercator: Zone 18 UTM X (Meters): 641943.8 UTM Y (Meters): 4506645.5

Elevation: 8 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map: 40073-F3 BAY SHORE WEST, NY

Most Recent Revision: 1979

AERIAL PHOTOGRAPHY IN THIS REPORT

Photo Year: 2011 Source: USDA

TARGET PROPERTY SEARCH RESULTS

The target property was not listed in any of the databases searched by EDR.

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records either on the target property or within the search radius around the target property for the following databases:

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list	
NPL	National Priority List

Proposed NPL Proposed National Priority List Sites

NPL LIENS..... Federal Superfund Liens

Federal Delisted NPL site list

Delisted NPL..... National Priority List Deletions

Federal CERCLIS list

FEDERAL FACILITY..... Federal Facility Site Information listing

Federal CERCLIS NFRAP site List

CERC-NFRAP..... CERCLIS No Further Remedial Action Planned

Federal RCRA CORRACTS facilities list

CORRACTS..... Corrective Action Report

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF...... RCRA - Treatment, Storage and Disposal

Federal RCRA generators list

RCRA-LQG...... RCRA - Large Quantity Generators

Federal institutional controls / engineering controls registries

US ENG CONTROLS...... Engineering Controls Sites List US INST CONTROL...... Sites with Institutional Controls

LUCIS.....Land Use Control Information System

Federal ERNS list

ERNS..... Emergency Response Notification System

State and tribal landfill and/or solid waste disposal site lists

NY SWF/LF..... Facility Register

State and tribal leaking storage tank lists

NY HIST LTANKS..... Listing of Leaking Storage Tanks

INDIAN LUST..... Leaking Underground Storage Tanks on Indian Land

State and tribal registered storage tank lists

FEMA UST..... Underground Storage Tank Listing

State and tribal institutional control / engineering control registries

NY ENG CONTROLS....... Registry of Engineering Controls NY INST CONTROL....... Registry of Institutional Controls NY RES DECL........... Restrictive Declarations Listing

State and tribal voluntary cleanup sites

NY VCP...... Voluntary Cleanup Agreements INDIAN VCP...... Voluntary Cleanup Priority Listing

State and tribal Brownfields sites

NY ERP._____ Environmental Restoration Program Listing

NY BROWNFIELDS..... Brownfields Site List

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS..... A Listing of Brownfields Sites

Local Lists of Landfill / Solid Waste Disposal Sites

DEBRIS REGION 9..... Torres Martinez Reservation Illegal Dump Site Locations

ODI...... Open Dump Inventory

NY SWRCY...... Registered Recycling Facility List

NY SWTIRE...... Registered Waste Tire Storage & Facility List

INDIAN ODI...... Report on the Status of Open Dumps on Indian Lands

Local Lists of Hazardous waste / Contaminated Sites

US HIST CDL..... National Clandestine Laboratory Register

Local Lists of Registered Storage Tanks

NY HIST UST..... Historical Petroleum Bulk Storage Database NY HIST AST..... Historical Petroleum Bulk Storage Database

Local Land Records

LIENS 2...... CERCLA Lien Information NY LIENS..... Spill Liens Information

Records of Emergency Release Reports

HMIRS..... Hazardous Materials Information Reporting System

NY Hist Spills..... SPILLS Database

Other Ascertainable Records

CONSENT...... Superfund (CERCLA) Consent Decrees

TRIS...... Toxic Chemical Release Inventory System

TSCA...... Toxic Substances Control Act

Act)/TSCA (Toxic Substances Control Act)

HIST FTTS...... FIFRA/TSCA Tracking System Administrative Case Listing

SSTS..... Section 7 Tracking Systems

ICIS..... Integrated Compliance Information System

RAATS......RCRA Administrative Action Tracking System

RMP..... Risk Management Plans

NY UIC..... Underground Injection Control Wells

NY AIRS..... Air Emissions Data

NY E DESIGNATION..... E DESIGNATION SITE LISTING

INDIAN RESERV.....Indian Reservations

SCRD DRYCLEANERS...... State Coalition for Remediation of Drycleaners Listing

NY COAL ASH..... Coal Ash Disposal Site Listing

NY Financial Assurance Information Listing

LEAD SMELTERS..... Lead Smelter Sites

2020 COR ACTION...... 2020 Corrective Action Program List

COAL ASH EPA..... Coal Combustion Residues Surface Impoundments List

PRP...... Potentially Responsible Parties

PCB TRANSFORMER....... PCB Transformer Registration Database

US FIN ASSUR..... Financial Assurance Information

EPA WATCH LIST..... EPA WATCH LIST

COAL ASH DOE..... Steam-Electric Plant Operation Data

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP..... EDR Proprietary Manufactured Gas Plants

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.

Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in bold italics are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

STANDARD ENVIRONMENTAL RECORDS

Federal RCRA generators list

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 06/18/2013 has revealed that there are 2 RCRA-SQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
MTA LIRR DEER PARK AVENUE RAIL	DEER PARK AVE 200' N GE	WSW 1/8 - 1/4 (0.161 mi.)	B9	20
DONG HAE INC - DBA WALTERS CLE	169 DEER PARK AVE	SW 1/8 - 1/4 (0.178 mi.)	C15	28

RCRA-CESQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-CESQG list, as provided by EDR, and dated 06/18/2013 has revealed that there is 1 RCRA-CESQG site within approximately 0.25 miles of the target property.

Lower Elevation	Address	Direction / Distance	Map ID	Page
BABYLON PHOTO LAB	21 COOPER ST	S 1/8 - 1/4 (0.181 mi.)	16	33

State- and tribal - equivalent CERCLIS

NY SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Environmental Conservation's Inactive Hazardous waste Disposal Sites in New York State.

A review of the NY SHWS list, as provided by EDR, and dated 05/21/2013 has revealed that there is 1 NY SHWS site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
EUGENE FRENCH CLEANERS	54 EAST MAIN STREET	SSW 1/4 - 1/2 (0.283 mi.)	G33	71
Class Code: Site is properly closed -	requires continued management.			

NY VAPOR REOPENED: "Vapor intrusion" refers to the process by which volatile chemicals move from a subsurface source into the indoor air of overlying or adjacent buildings. The subsurface source can either be contaminated groundwater or contaminated soil which releases vapors into the pore spaces in the soil. Improvements in analytical techniques and knowledge gained from site investigations in New York and other states has led to an increased awareness of soil vapor as a medium of concern and of the potential for exposures from the soil vapor intrusion pathway. Based on this additional information, New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

A review of the NY VAPOR REOPENED list, as provided by EDR, and dated 01/01/2013 has revealed that there is 1 NY VAPOR REOPENED site within approximately 1 mile of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
EUGENE DRY CLEANERS	54 EAST MAIN STREET	SSW 1/4 - 1/2 (0.283 mi.)	G34	77

State and tribal leaking storage tank lists

NY LTANKS: Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills

A review of the NY LTANKS list, as provided by EDR, and dated 05/21/2013 has revealed that there are 18 NY LTANKS sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
APARTMENT BLDG Spill Number/Closed Date: 0801274 /	123 COOPER STREET 6/3/2008	NNE 0 - 1/8 (0.069 mi.)	2	9
RELIANCE FUEL DEPOT Spill Number/Closed Date: 9609844 /	UNION BOULEVARD & RTE 2 1/21/1997	NE 1/8 - 1/4 (0.228 mi.)	E27	60
BAYVIEW REST HOME Spill Number/Closed Date: 9614539 /	143 EAST MAIN STREET 7/12/2000	S 1/8 - 1/4 (0.237 mi.)	F30	63
SIASOCO RESIDENCE Spill Number/Closed Date: 0510111 /	78 A DEER PARK AVENUE 6/27/2007	SW 1/8 - 1/4 (0.242 mi.)	31	69
KELLY RESIDENCE Spill Number/Closed Date: 9814487 /	31 HOWARD STREET 3/12/1999	NNE 1/4 - 1/2 (0.300 mi.)	35	79
BABYLON HIGH SCHOOL Spill Number/Closed Date: 8802796 /	50 RAILROAD AVE 9/1/1988	W 1/4 - 1/2 (0.333 mi.)	37	81
UNITED ARTIST MOVIE THEAT Spill Number/Closed Date: 9207227 /	34 MAIN STREET 11/26/1993	SW 1/4 - 1/2 (0.343 mi.)	H38	86
FAMILY AUTO Spill Number/Closed Date: 8600286 /	46 MONTAUK HIGHWAY 5/9/1986	SW 1/4 - 1/2 (0.353 mi.)	H39	87
ISLAND DESIGN CENTER Spill Number/Closed Date: 0703413 /	482 DEER PARK AVENUE 8/29/2007	NNW 1/4 - 1/2 (0.396 mi.)	40	88
MOBIL S/S Spill Number/Closed Date: 9002541 /	MTK HWY & EVELYN STREET 3/19/1992	ESE 1/4 - 1/2 (0.420 mi.)	I41	90
MOBIL OIL CORP SS MLM Spill Number/Closed Date: 9108945 / Spill Number/Closed Date: 8808933 / Spill Number/Closed Date: 9002602 /	409 MONTAUK HWY 12/12/1991 3/19/1992 3/19/1992	SE 1/4 - 1/2 (0.433 mi.)	I42	91

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
DELTA S/S Spill Number/Closed Date: 8802347 / Spill Number/Closed Date: 8802262 /	410 MONTAUK HWY 4/7/1995 4/7/1995	SE 1/4 - 1/2 (0.436 mi.)	143	103
ABANDONED S/S Spill Number/Closed Date: 9405859 /	425 MONTAUK HIGHWAY 7/14/2004	ESE 1/4 - 1/2 (0.451 mi.)	44	108
BERNARD GENCOGLE/SUNOCO Spill Number/Closed Date: 8606913 /	455 MONTAUK HIGHWAY 3/25/1987	ESE 1/4 - 1/2 (0.482 mi.)	47	115
Lower Elevation	Address	Direction / Distance	Map ID	Page
UNK	MAIN A GOODED			
Spill Number/Closed Date: 8701780 /	MAIN & COOPER 2/25/1998	S 1/8 - 1/4 (0.233 mi.)	28	61
Spill Number/Closed Date: 8701780 / MOBIL S/S Spill Number/Closed Date: 9108829 /	2/25/1998 MONTAUK HIGHWAY	S 1/8 - 1/4 (0.233 mi.) SE 1/4 - 1/2 (0.325 mi.)	28 36	61 80
MOBIL S/S	2/25/1998 MONTAUK HIGHWAY	,		

State and tribal registered storage tank lists

NY UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database

A review of the NY UST list, as provided by EDR, and dated 04/02/2013 has revealed that there are 8 NY UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
VILLAGE COMMON CONDOS	291 DEER PARK AVE	WNW 1/8 - 1/4 (0.130 mi.)	6	14
INTER COUNTY MOTOR COACH	243 DEER PARK AVE	W 1/8 - 1/4 (0.133 mi.)	A7	17
CASANDRA APARTMENT BLDG	240 DEER PARK AVE	W 1/8 - 1/4 (0.138 mi.)	A8	19
GAS STATION	375 DEER PARK AVE	NW 1/8 - 1/4 (0.166 mi.)	10	21
PARKING LOT	157-175 DEER PARK AVE	SW 1/8 - 1/4 (0.184 mi.)	C17	44
WOLFS CENTRAL SERVICE	47 SAMMIS AVE	WNW 1/8 - 1/4 (0.216 mi.)	D20	46
VILLAGE FUEL OIL	65 JOHN ST	NE 1/8 - 1/4 (0.223 mi.)	E23	50
Lower Elevation	Address	Direction / Distance	Map ID	Page
GARVEY ASSOCIATES	116 RTE 27 A MONTAUK HW	S 1/8 - 1/4 (0.228 mi.)	26	59

NY AST: The Aboveground Storage Tank database contains registered ASTs. The data come from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS) Database.

A review of the NY AST list, as provided by EDR, and dated 04/02/2013 has revealed that there are 4 NY AST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
VILLAGE COMMON CONDOS	291 DEER PARK AVE	WNW 1/8 - 1/4 (0.130 mi.)	6	14
INTER COUNTY MOTOR COACH	243 DEER PARK AVE	W 1/8 - 1/4 (0.133 mi.)	A7	17
WOLFS CENTRAL SERVICE	47 SAMMIS AVE	WNW 1/8 - 1/4 (0.216 mi.)	D19	46
VILLAGE FUEL OIL	65 JOHN ST	NE 1/8 - 1/4 (0.223 mi.)	E23	50

ADDITIONAL ENVIRONMENTAL RECORDS

Records of Emergency Release Reports

NY Spills: Data collected on spills reported to NYSDEC. is required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

A review of the NY Spills list, as provided by EDR, and dated 05/21/2013 has revealed that there are 3 NY Spills sites within approximately 0.125 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
ASTRO REP INC Spill Number/Closed Date: 960032	103 COOPER STREET 28 / 4/8/1996	NE 0 - 1/8 (0.030 mi.)	1	8
FEIG RESIDENCE Spill Number/Closed Date: 081026	57 JAMES STREET 65 / 2/6/2010	S 0 - 1/8 (0.080 mi.)	3	10
RESIDENCE Spill Number/Closed Date: 110745	25 JAMES STREET	SW 0 - 1/8 (0.105 mi.)	4	11

Other Ascertainable Records

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 06/18/2013 has revealed that there are 4 RCRA NonGen / NLR sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
FOUR SEASON RECREATION INC	10 JOHN ST	NNE 0 - 1/8 (0.110 mi.)	5	12
JOSEPH LALIA D.P.M	<i>421 DEER PARK AVE</i>	NNW 1/8 - 1/4 (0.222 mi.)	22	48
BLUM DWIGHT MD	51 JOHN ST	NE 1/8 - 1/4 (0.224 mi.)	E24	52
LILCO - BABYLON SUBSTATION	CEDAR ST	NNE 1/8 - 1/4 (0.226 mi.)	25	58
JOSEPH LALIA D.P.M BLUM DWIGHT MD	421 DEER PARK AVE 51 JOHN ST	NNW 1/8 - 1/4 (0.222 mi.) NE 1/8 - 1/4 (0.224 mi.)	22 E24	48 52

NY HSWDS: The List includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity The latest version of the study is frozen in time. The sites on the study will not automatically be made superfund sites, rather each site will be further evaluated for listing in the registry. So overtime they will be added to the registry or not.

A review of the NY HSWDS list, as provided by EDR, and dated 01/01/2003 has revealed that there is 1 NY HSWDS site within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
EUGENE FRENCH CLEANERS	54 EAST MAIN STREET	SSW 1/4 - 1/2 (0.283 mi.)	G33	71

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, and dated 05/01/2013 has revealed that there are 4 NY MANIFEST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page	
FOUR SEASON RECREATION INC	10 JOHN ST	NNE 0 - 1/8 (0.110 mi.)	5	12	
WALTERS CLEANERS INCORPORATED	169 DEER PARK AVENUE	SW 1/8 - 1/4 (0.178 mi.)	C14	25	
BLUM DWIGHT MD	51 JOHN ST	NE 1/8 - 1/4 (0.224 mi.)	E24	52	
Lower Elevation	Address	Direction / Distance	Map ID	Page	
BABYLON PHOTO LAB	21 COOPER ST	S 1/8 - 1/4 (0.181 mi.)	16	33	

RI MANIFEST: Hazardous waste manifest information

A review of the RI MANIFEST list, as provided by EDR, and dated 05/01/2013 has revealed that there is 1 RI MANIFEST site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
DONG HAE INC - DBA WALTERS CLE	169 DEER PARK AVE	SW 1/8 - 1/4 (0.178 mi.)	C15	28

NY DRYCLEANERS: A listing of all registered drycleaning facilities.

A review of the NY DRYCLEANERS list, as provided by EDR, and dated 04/19/2013 has revealed that there is 1 NY DRYCLEANERS site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
WALTERS CLEANERS INCORPORATED	169 DEER PARK AVENUE	SW 1/8 - 1/4 (0.178 mi.)	C14	25

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR US Hist Auto Stat: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR US Hist Auto Stat list, as provided by EDR, has revealed that there are 3 EDR US Hist Auto Stat sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page	
Not reported	47 SAMMIS AVE	WNW 1/8 - 1/4 (0.216 mi.)	D18	45	
Not reported	11 GROVE PL	SW 1/8 - 1/4 (0.222 mi.)	21	48	
Not reported	158 E MAIN ST	S 1/8 - 1/4 (0.236 mi.)	F29	63	

EDR US Hist Cleaners: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.


A review of the EDR US Hist Cleaners list, as provided by EDR, has revealed that there are 4 EDR US Hist Cleaners sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page	
Not reported	180 DEER PARK AVE	WSW 1/8 - 1/4 (0.173 mi.)	B11	22	
Not reported	12 RAILROAD AVE	W 1/8 - 1/4 (0.178 mi.)	12	23	
Not reported	169 DEER PARK AVE	SW 1/8 - 1/4 (0.178 mi.)	C13	24	
Not reported	105 E MAIN ST	SSW 1/8 - 1/4 (0.246 mi.)	32	71	

Due to poor or inadequate address information, the following sites were not mapped. Count: 46 records.

Site Name **BELL ATLANTIC-NY** RCRA NonGen / NLR, NY MANIFEST RCRA NonGen / NLR, FINDS, NY NYSDOT **MANIFEST** QUALITY CAR CARE INC NY MANIFEST **NYNEX** NY MANIFEST VICON INDUSTRIES INCORPORATED NY MANIFEST STRUTHERS ELECTRONICS CORP RCRA NonGen / NLR, FINDS, NY **MANIFEST** TYROLIT CO INC RCRA NonGen / NLR, FINDS, NY **MANIFEST** J & P COLLISION INC RCRA NonGen / NLR, FINDS, NY **MANIFEST** PHOTO REFLECTIONS RCRA NonGen / NLR, FINDS, NY **MANIFEST** STOP & SHOP PLAZA NY MANIFEST BABYLON LEAF TRANSFER STATION NY SWF/LF **GERALD WRIGHT** NY SWF/LF PLANTING FIELDS NY SWF/LF, NY UST ST. CHARLES CEMETARY NY SWF/LF **BABYLON SLF** NY SWF/LF CAYA MATERIALS OF BABYLON NY SWF/LF MEENAN OIL NY LTANKS SUBARU DEALERSHIP NY UST UNITED METHODIST CHRUCH NY UST BABYLON VILLAGE FIRE DEPT NY UST L & B LINCOLN MERCURY NY UST LONG ISLAND SAVINGS BANK NY UST **OK PETROLEUM** NY UST ANG GAS & SERVICE INC NY UST B P OIL CO S/S NY UST COMMERCIAL REALTY BLDG NY UST DESIMONE REALTY NY UST ATLANTIC BOATS NY AST SCWA WELLFIELD SUNRISE HWY NY AST BABYLON 9 HOLE / PAR 3 GOLF COURSE **FINDS** SUFFOLK COUNTY TEST WELL #43818 NY DEL SHWS **BUDGET RENT-A-CAR** NY Spills OLD FAIRCHILD COMPLEX NY Spills DEPARTMENT OF TRANSPORTATION NY Spills NY Spills UNK GILGO STATE PARK NY Spills NY Spills LILCO NY Spills UNK NY Spills SANTAPOGUE CREEK NY Spills UNK NY Spills NY Spills **UNKNOWN** EASTERN COASTAL CORP NY Spills NY Spills ROADWAY/DRAIN **UNKNOWN** NY Spills **STREAM** NY Spills

OVERVIEW MAP - 3691395.1s



August 09, 2013 12:29 pm Copyright © 2013 EDR, Inc. © 2010 Tele Atlas Rel. 07/2009.


INQUIRY#: 3691395.1s

DATE:

LAT/LONG:

40.7004 / 73.3199

DETAIL MAP - 3691395.1s



SITE NAME: 8/9/13
ADDRESS: 54 George Street
Babylon NY 11702
LAT/LONG: 40.7004 / 73.3199

CLIENT: Middleton Environmental Inc.
CONTACT: Alex
INQUIRY #: 3691395.1s
DATE: August 09, 2013 12:30 pm

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
STANDARD ENVIRONMENTA	AL RECORDS							
Federal NPL site list								
NPL Proposed NPL NPL LIENS	1.000 1.000 TP		0 0 NR	0 0 NR	0 0 NR	0 0 NR	NR NR NR	0 0 0
Federal Delisted NPL site	list							
Delisted NPL	1.000		0	0	0	0	NR	0
Federal CERCLIS list								
CERCLIS FEDERAL FACILITY	0.500 0.500		0 0	0 0	0 0	NR NR	NR NR	0 0
Federal CERCLIS NFRAP	site List							
CERC-NFRAP	0.500		0	0	0	NR	NR	0
Federal RCRA CORRACT	S facilities lis	st						
CORRACTS	1.000		0	0	0	0	NR	0
Federal RCRA non-CORR	ACTS TSD fa	acilities list						
RCRA-TSDF	0.500		0	0	0	NR	NR	0
Federal RCRA generators	ist							
RCRA-LQG RCRA-SQG RCRA-CESQG	0.250 0.250 0.250		0 0 0	0 2 1	NR NR NR	NR NR NR	NR NR NR	0 2 1
Federal institutional contre								
US ENG CONTROLS US INST CONTROL LUCIS	0.500 0.500 0.500		0 0 0	0 0 0	0 0 0	NR NR NR	NR NR NR	0 0 0
Federal ERNS list								
ERNS	TP		NR	NR	NR	NR	NR	0
State- and tribal - equivale	ent CERCLIS	;						
NY SHWS NY VAPOR REOPENED	1.000 1.000		0 0	0 0	1 1	0 0	NR NR	1 1
State and tribal landfill an solid waste disposal site								
NY SWF/LF	0.500		0	0	0	NR	NR	0
State and tribal leaking st	torage tank li	sts						
NY LTANKS NY HIST LTANKS INDIAN LUST	0.500 0.500 0.500		1 0 0	4 0 0	13 0 0	NR NR NR	NR NR NR	18 0 0

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
State and tribal register	ed storage tar	nk lists						
NY TANKS NY UST NY CBS UST NY MOSF UST NY AST NY CBS AST NY MOSF AST NY MOSF NY CBS INDIAN UST FEMA UST	0.250 0.250 0.250 0.500 0.250 0.250 0.500 0.500 0.250 0.250		0 0 0 0 0 0 0 0	0 8 0 0 4 0 0 0 0	NR NR NR 0 NR NR 0 0 NR	NR NR NR NR NR NR NR NR	NR NR NR NR NR NR NR NR NR	0 8 0 0 4 0 0 0 0
State and tribal instituti control / engineering co		s						
NY ENG CONTROLS NY INST CONTROL NY RES DECL	0.500 0.500 0.125		0 0 0	0 0 NR	0 0 NR	NR NR NR	NR NR NR	0 0 0
State and tribal volunta	ry cleanup site	es						
NY VCP INDIAN VCP	0.500 0.500		0 0	0 0	0 0	NR NR	NR NR	0 0
State and tribal Brownfi	elds sites							
NY ERP NY BROWNFIELDS	0.500 0.500		0 0	0 0	0 0	NR NR	NR NR	0 0
ADDITIONAL ENVIRONME	NTAL RECORD	<u>s</u>						
Local Brownfield lists								
US BROWNFIELDS	0.500		0	0	0	NR	NR	0
Local Lists of Landfill / Waste Disposal Sites	Solid							
DEBRIS REGION 9 ODI NY SWRCY NY SWTIRE INDIAN ODI	0.500 0.500 0.500 0.500 0.500		0 0 0 0	0 0 0 0	0 0 0 0	NR NR NR NR NR	NR NR NR NR NR	0 0 0 0
Local Lists of Hazardou Contaminated Sites	s waste/							
US CDL NY DEL SHWS US HIST CDL	TP 1.000 TP		NR 0 NR	NR 0 NR	NR 0 NR	NR 0 NR	NR NR NR	0 0 0
Local Lists of Registere	d Storage Tar	ıks						
NY HIST UST NY HIST AST	0.250 TP		0 NR	0 NR	NR NR	NR NR	NR NR	0 0

LIENS 2	Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
NY LIENS TP	Local Land Records								
HMIRS									
NY Spills	Records of Emergency I	Release Repo	rts						
RCRA NonGen / NLR 0.250 1 3 NR O DOD 1.000 0 0 0 0 0 0 NR 0 CONSENT 1.000 0 0 0 0 0 0 NR 0 ROD 1.000 0 0 0 0 0 NR NR 0 UMTRA 0.250 0 0 0 NR NR NR 0 UMTRA 0.250 0 0 0 NR NR NR NR NR NR NR	NY Spills NY Hist Spills NY SPILLS 90	0.125 0.125 0.125		3 0 0	NR NR NR	NR NR NR	NR NR NR	NR NR NR	3 0 0
DOT OPS TP NR NR NR NR NR O DOD 1.000 0 0 0 0 0 NR 0 FUDS 1.000 0 0 0 0 0 NR 0 CONSENT 1.000 0 0 0 0 0 NR 0 ROD 1.000 0 0 0 0 0 NR 0 ROD 1.000 0 0 0 0 NR NR NR 0 UMTRA 0.5500 0 0 0 NR NR <td>Other Ascertainable Rec</td> <td>ords</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>	Other Ascertainable Rec	ords							
LEAD SMELTERS TP NR NR NR NR NR NR 0 2020 COR ACTION 0.250 0 0 NR NR NR NR 0 US AIRS TP NR NR NR NR NR NR NR 0 COAL ASH EPA 0.500 0 0 NR NR NR 0 PRP TP NR NR NR NR NR NR NR 0	DOT OPS DOD FUDS CONSENT ROD UMTRA US MINES TRIS TSCA FTTS HIST FTTS SSTS ICIS PADS MLTS RADINFO FINDS RAATS RMP NY HSWDS NY UIC NY MANIFEST RI MANIFEST NY DRYCLEANERS NY SPDES NY AIRS NY E DESIGNATION INDIAN RESERV SCRD DRYCLEANERS NY COAL ASH NY Financial Assurance LEAD SMELTERS 2020 COR ACTION US AIRS COAL ASH EPA	TP 1.000 1.000 1.000 1.000 0.500 0.250 TP		NR O O O O O O R R R R R R R R R R R R R	NR 0 0 0 0 0 0 R R R R R R R R R R R R N O R 3 1 1 R R R O O O R N O N O N O O O R O O O O	NR O O O O O R R R R R R R R R R R R R R	N 0 0 0 0 R R R R R R R R R R R R R R R	N	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0

Database	Search Distance (Miles)	Target Property	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
US FIN ASSUR EPA WATCH LIST COAL ASH DOE	TP TP TP		NR NR NR	NR NR NR	NR NR NR	NR NR NR	NR NR NR	0 0 0
EDR HIGH RISK HISTORICA	L RECORDS							
EDR Exclusive Records								
EDR MGP EDR US Hist Auto Stat EDR US Hist Cleaners	1.000 0.250 0.250		0 0 0	0 3 4	0 NR NR	0 NR NR	NR NR NR	0 3 4

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

Direction Distance

Elevation Site Database(s) EPA ID Number

1 ASTRO REP INC NY Spills S102237401 NE 103 COOPER STREET N/A

BABYLON, NY

< 1/8 0.030 mi. 159 ft.

Relative: SPILLS:

Higher Facility ID: 9600328

DER Facility ID: 63505

Actual: Facility Type: ER

9 ft. Site ID: 66295

DEC Region: 1

Spill Date: 4/8/1996

Spill Number/Closed Date: 9600328 / 4/8/1996 Spill Cause: 9600328 / 4/8/1996 Equipment Failure

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.

Willing Responsible Party. Corrective action taken.

SWIS: 5220

Investigator: UNASSIGNED
Referred To: Not reported
Reported to Dept: 4/8/1996
CID: 275

Water Affected: Not reported

Spill Source: Commercial/Industrial Spill Notifier: Affected Persons Cleanup Ceased: Not reported Cleanup Meets Std: True Last Inspection: Not reported Recommended Penalty: False **UST Trust:** False Remediation Phase: Date Entered In Computer: 4/8/1996 Spill Record Last Update: 8/14/2003

Spiller Name: Not reported
Spiller Company: ASTRO REP INC
Spiller Address: 103 COOPER STREET

Spiller City,St,Zip: BABYLON, ZZ

Spiller Company: 001

Contact Name: Not reported Contact Phone: (516) 422-2500

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was

"NONE"OIL ONTO PARKING LOT OUT OF STICK LINE, SERVICE FIXED PROBLEM,

CLEANED UP AREA, NO RESPONSE NEEDED

Remarks: 1/2 gal - on pavement - all cleaned - 2nd fill on same system had a

cracked fill pipe - when main system was filled small spill out of

2nd fill

Material:

66295 Site ID: Operable Unit ID: 1031763 Operable Unit: 01 353726 Material ID: Material Code: 0001A Material Name: #2 Fuel Oil Case No.: Not reported Material FA: Petroleum Quantity:

Quantity: 1
Units: Gallons
Recovered: Yes

Resource Affected: Not reported

EDR ID Number

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

ASTRO REP INC (Continued) S102237401

Oxygenate: False

Tank Test:

APARTMENT BLDG NY LTANKS S109064311 2 N/A

NNE 123 COOPER STREET < 1/8 BABYLON, NY 11702

0.069 mi. 362 ft.

LTANKS: Relative:

Site ID: 397168 Higher

Spill Number/Closed Date: 0801274 / 6/3/2008

Actual: Spill Date: 5/1/2008 10 ft. Spill Cause: Tank Test Failure

Spill Source: Commercial/Industrial

Known release that creates potential for fire or hazard. DEC Response. Spill Class:

Willing Responsible Party. Corrective action taken.

Cleanup Ceased: Not reported Cleanup Meets Standard: False SWIS: 5220 Investigator: hmcirrit Referred To: Not reported Reported to Dept: 5/1/2008 CID: 444

Water Affected: Not reported Spill Notifier: Tank Tester Last Inspection: Not reported Recommended Penalty: False **UST Involvement:** False Remediation Phase: Date Entered In Computer: 5/1/2008 Spill Record Last Update: 3/22/2010

Spiller Name: MR RUDY MEIEROTT Spiller Company: MR RUDY MEIEROTT Spiller Address: 99 WEST FARM DRIVE Spiller City, St, Zip: MELVILLE, NY 11747

Spiller County: 001

Spiller Contact: PATRICK HALPIN- BUYER

Spiller Phone: (516) 848-0444 Spiller Extention: Not reported DEC Region: DER Facility ID: 346608

DEC Memo: 1K FUEL OIL TANK EXCAVATED, NO FUEL OIL ODORS OBSERVED IN THE SOIL AT

THE ENDPOINTS OF THE EXCAVATION, G/W ENCOUNTERED NO SHEEN/FLOATING

PRODUCT, FUEL OIL ODORS AT GW (BD)

Remarks: dry leak

Material:

397168 Site ID: Operable Unit ID: 1154124 Operable Unit: 01 Material ID: 2144921 Material Code: 0001A Material Name: #2 Fuel Oil Case No.: Not reported

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

APARTMENT BLDG (Continued)

S109064311

Material FA: Petroleum Quantity: 0 Units: Gallons Recovered: No Not reported Resource Affected: Oxygenate: False

Tank Test:

Site ID: 397168 Spill Tank Test: 2453631 Not reported Tank Number: Tank Size: 1000 Test Method: 03 Leak Rate:

Gross Fail: Not reported Modified By: Watchdog Last Modified: 5/1/2008

Test Method: Horner EZ Check I or II

FEIG RESIDENCE NY Spills S109413449 **57 JAMES STREET** South N/A

< 1/8 **BABYLON, NY** 0.080 mi.

422 ft.

SPILLS: Relative: Higher

Facility ID: 0810265 DER Facility ID: 357029 Actual: Facility Type: ER 8 ft. Site ID: 407782

DEC Region: Spill Date: 12/13/2008

Spill Number/Closed Date: 0810265 / 2/6/2010 Spill Cause: Human Error

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.

Willing Responsible Party. Corrective action taken.

SWIS: 5220 Investigator: wjgabin Referred To: Not reported Reported to Dept: 12/13/2008 Not reported CID: Water Affected: Not reported

Private Dwelling Spill Source:

Spill Notifier: Other Cleanup Ceased: Not reported Cleanup Meets Std: False Last Inspection: Not reported Recommended Penalty: False **UST Trust:** False Remediation Phase: Date Entered In Computer: 12/13/2008

Spill Record Last Update: 3/3/2010 Spiller Name: Not reported Spiller Company: landscaper Spiller Address: Not reported

Spiller City, St, Zip: NY

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

FEIG RESIDENCE (Continued)

S109413449

Spiller Company: 999 MRS. FEIG Contact Name:

Contact Phone: (631) 669-3179

DEC Memo: 12/13/08 @13:00 t/c to homeowner; broken line has been repaired by

her oil company, soil affected, cleanup procedures discussed,

homeowner's ins. company contact suggested. (VP)

Mrs. Feig had someone cleaning up her leaves and accidently took off Remarks:

the bottom of the tank which started leaking onto the ground. unknown

amount spilled out. The landscaper hit with rake.

Material:

Site ID: 407782 Operable Unit ID: 1164318 Operable Unit: 01 Material ID: 2155692 Material Code: 0001A #2 Fuel Oil Material Name: Case No.: Not reported Material FA: Petroleum Quantity: 50 Units: Gallons Not reported Recovered: Resource Affected: Not reported Oxygenate: False

Tank Test:

RESIDENCE NY Spills S111238732 SW **25 JAMES STREET** N/A **BABYLON, NY**

< 1/8 0.105 mi. 555 ft.

SPILLS: Relative:

Facility ID: 1107452 Higher DER Facility ID: 409737 Actual: Facility Type: ER 9 ft. Site ID: 455153 DEC Region:

Spill Date: 9/13/2011

Spill Number/Closed Date: 1107452 / 12/29/2011 Spill Cause: **Equipment Failure**

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.

Willing Responsible Party. Corrective action taken.

SWIS: 5220 Investigator: Unassigned Not reported Referred To: Reported to Dept: 9/13/2011 CID: Not reported Water Affected: Not reported Spill Source: Commercial Vehicle Spill Notifier: Responsible Party Cleanup Ceased: Not reported

Cleanup Meets Std: False Last Inspection: Not reported Recommended Penalty: False **UST Trust:** False

Direction Distance

Elevation Site Database(s) EPA ID Number

RESIDENCE (Continued) S111238732

Remediation Phase: 0

Date Entered In Computer: 9/13/2011
Spill Record Last Update: 12/31/2011

Spiller Name: REBECCA ELFAST

Spiller Company: LIPA
Spiller Address: Not reported

Spiller City,St,Zip: NN Spiller Company: 999

Contact Name: REBECCA ELFAST Contact Phone: (516) 545-5511

DEC Memo: 09/13/11 1425 Hrs (A): Called Elfast- a hydraulic line ruptured on

one of their vehicles, spraying fluid on the driveway, lawn, and

house.09/13/11 1425 Hrs (B): They are cleaning up at this time. DRPER NATIONAL GRID INCIDENT DESCRIPTIONWHILE REPLACING A POLE AND ASSOCIATED Y BANK, THE HYDRAULIC LINE OF A SERVICE VEHICLE FAILED AND

SPRAYED OIL ONTO A HOUSE AND LAWN, WRS CONTRACTOR

Remarks: spill to roadway and private property/clean up crew en route

Material:

Site ID: 455153 Operable Unit ID: 1205303 Operable Unit: 01 Material ID: 2202151 Material Code: 0010 Material Name: Hydraulic Oil Not reported Case No.: Material FA: Petroleum Quantity: 15 Units: Gallons Recovered: Not reported Resource Affected: Not reported False Oxygenate:

Tank Test:

5 FOUR SEASON RECREATION INC RCRA NonGen / NLR 1006810323 NNE 10 JOHN ST FINDS NYR000109975

< 1/8 BABYLON, NY 11702

581 ft.

0.110 mi.

Relative: RCRA NonGen / NLR:

Higher Date form received by agency: 01/01/2007

Facility name: FOUR SEASON RECREATION INC

Actual: Facility address: 10 JOHN ST 8 ft. BARYLON N

BABYLON, NY 117022904 EPA ID: NYR000109975

Mailing address: PO BOX 846

BABYLON, NY 11702 Contact: DONNA MAY

Contact address: PO BOX 846

BABYLON, NY 11702

Contact country: US

Contact telephone: (631) 948-7628 Contact email: Not reported

EPA Region: 02

Classification: Non-Generator

NY MANIFEST

EDR ID Number

Distance

Elevation Site Database(s) EPA ID Number

FOUR SEASON RECREATION INC (Continued)

1006810323

EDR ID Number

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: FOUR SEASON RECREATION INC

Owner/operator address: 10 JOHN ST

BABYLON, NY 11702

Owner/operator country: US

Owner/operator telephone: (691) 948-7628

Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Owner/operator name: FOUR SEASON RECREATION INC

Owner/operator address: 10 JOHN ST

BABYLON, NY 11702

Owner/operator country: US

Owner/operator telephone: (691) 948-7628
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006

Facility name: FOUR SEASON RECREATION INC

Classification: Not a generator, verified

Date form received by agency: 10/24/2002

Facility name: FOUR SEASON RECREATION INC

Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110013384621

Environmental Interest/Information System

Direction Distance

Elevation Site Database(s) EPA ID Number

FOUR SEASON RECREATION INC (Continued)

1006810323

EDR ID Number

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID: NYR000109975

Country: USA

Mailing Name: FOUR SEASONS RECREATION INC

Mailing Contact: N/S

Mailing Address: 10 W JOHN ST
Mailing Address 2: Not reported
Mailing City: BABYLON
Mailing State: NY
Mailing Zip: 11702
Mailing Zip4: Not reported
Mailing Country: USA

Mailing Phone: 631-273-6192

Document ID: NYG2716164 Manifest Status: Not reported Trans1 State ID: NYD077444263 Not reported Trans2 State ID: Generator Ship Date: 11/05/2002 Trans1 Recv Date: 11/05/2002 Trans2 Recv Date: Not reported TSD Site Recv Date: 11/06/2002 Part A Recv Date: Not reported Part B Recv Date: Not reported NYR000109975 Generator EPA ID: Trans1 EPA ID: NYD077444263 Trans2 EPA ID: Not reported TSDF ID: 40579PANY

Waste Code: D008 - LEAD 5.0 MG/L TCLP

Quantity: 00500
Units: P - Pounds
Number of Containers: 001

Container Type: DM - Metal drums, barrels

Handling Method: T Chemical, physical, or biological treatment.

Specific Gravity: 01.00 Year: 2002

6 VILLAGE COMMON CONDOS WNW 291 DEER PARK AVE 1/8-1/4 BABYLON, NY 11702

0.130 mi. 684 ft.

Relative: SUFFOLK CO. UST:

Higher Facility ID: 2579
Facility Reference #: 06632

Actual: Official Use: Removed Tank. 86

13 ft. Township: BABYLON

U003534618

N/A

NY UST

NY AST

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

VILLAGE COMMON CONDOS (Continued)

0102 010.00 002 012.000 Tax Map No:

SUFFOLK Region: Tank Count: 12 Permit to Operate: Not reported

VANTAGE PETROLEUM CORP Owner Name: Owner Address: 476 EXPRESSWAY DR S Owner City, St, Zip: MEDFORD, NY 11763

Tank ID: Tank Key: 6706 Installed: Not reported 0000004000 Capacity: Content: **GASOLINE** Date Removed: 010186 UNDER, OUT Location: Construction: STEEL Dispenser: SUCTION **GRAVITY** Fill Type:

Tank ID: 2 Tank Key: 6707 Installed: Not reported 0000004000 Capacity: GASOLINE Content: Date Removed: 010186 UNDER, OUT Location: Construction: STEEL SUCTION Dispenser: Fill Type: **GRAVITY**

Tank ID: 3 Tank Key: 6708 Installed: Not reported 0000004000 Capacity: Content: **GASOLINE** Date Removed: 010186 UNDER, OUT Location: Construction: STEEL SUCTION Dispenser: Fill Type: **GRAVITY**

Tank ID: 4 Tank Key: 6709 Installed: Not reported 000002000 Capacity: **GASOLINE** Content: 010200 Date Removed: Location: UNDER, OUT Construction: STEEL SUCTION Dispenser: Fill Type: **GRAVITY**

Tank ID: 5 U003534618

Direction Distance

Elevation Site Database(s) EPA ID Number

VILLAGE COMMON CONDOS (Continued)

U003534618

EDR ID Number

Tank Key: 6710 Installed: Not reported Capacity: 0000002000 Content: **GASOLINE** Date Removed: 010200 UNDER, OUT Location: Construction: **STEEL** SUCTION Dispenser: Fill Type: **GRAVITY**

Click this hyperlink while viewing on your computer to access 5 additional NY_UST_SUFFOLK: record(s) in the EDR Site Report.

SUFFOLK CO. AST:

Facility ID: 2579 Facility Reference #: 06632 Township: **BABYLON** Tax Map No: 0102 Tank Count: 12 SUFFOLK Region: Owner Name: Not reported Not reported Owner Address: Owner City, St, Zip: Not reported

Tank ID: 11 41453 Tank Key: Installed: Not reported Capacity: 000000550 Content: #2 FUEL OIL Date Removed: 010200 Location: ABOVE, OUT Construction: **STEEL** SUCTION Dispenser: Fill Type: **GRAVITY**

Official Use: Removed Tank. 00
Permit to Operate: Not reported

Tank ID: 12 Tank Key: 41454 Installed: Not reported Capacity: 000000550 Content: #2 FUEL OIL 010200 Date Removed: ABOVE, OUT Location: Construction: STEEL SUCTION Dispenser: Fill Type: **GRAVITY**

Official Use: Removed Tank. 00
Permit to Operate: Not reported

Direction Distance

Elevation Site Database(s) **EPA ID Number**

Α7 INTER COUNTY MOTOR COACH **NY UST** U003534712 **NY AST** West 243 DEER PARK AVE N/A

1/8-1/4 0.133 mi.

703 ft. Site 1 of 2 in cluster A

Relative: Higher

SUFFOLK CO. UST:

BABYLON, NY 11702

2828 Facility ID: Facility Reference #: 07125

Actual: 12 ft.

Official Use: Removed Tank. 83 Township: **BABYLON**

Tax Map No: 0102 010.00 002 015.001

SUFFOLK Region: Tank Count: 12

Permit to Operate: Not reported

INTER MOTOR COACH Owner Name: 243 DEER PARK AVE Owner Address:

BABYLON, NY 11702 Owner City,St,Zip:

Tank ID: Tank Key: 7578 Installed: 60 0000004000 Capacity: GASOLINE Content: Date Removed: 010183 Location: UNDER, OUT Construction: STEEL SUCTION Dispenser: Fill Type: **GRAVITY**

Tank ID: 2 Tank Key: 7579 Installed: 60

Capacity: 0000004000 Content: **DIESEL** Date Removed: 010183 Location: UNDER, OUT Construction: STEEL Dispenser: SUCTION Fill Type: **PUMPED**

Tank ID: 3 Tank Key: 7580 Installed: 83

Capacity: 0000006000 Content: DIESEL Date Removed: Not reported UNDER, OUT Location:

Construction: **FRP**

SUBMERSIBLE Dispenser: Fill Type: **GRAVITY**

Tank ID: 4 7581 Tank Key: Installed: 83

0000010000 Capacity:

EDR ID Number

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

INTER COUNTY MOTOR COACH (Continued)

U003534712

Content: DIESEL Date Removed: Not reported Location: UNDER, OUT

Construction: FRP

Dispenser: SUBMERSIBLE **PUMPED** Fill Type:

Tank ID: 5 Tank Key: 7582 Installed: 83

000000550 Capacity: Content: WASTE OIL Date Removed: Not reported UNDER, OUT Location: FRP Construction: Dispenser: SUCTION

GRAVITY

Click this hyperlink while viewing on your computer to access 3 additional NY_UST_SUFFOLK: record(s) in the EDR Site Report.

SUFFOLK CO. AST:

Fill Type:

Facility ID: 2828 Facility Reference #: 07125 **BABYLON** Township: Tax Map No: 0102 Tank Count: 12 SUFFOLK

Region:

INTER COUNTY MOTOR COACH Owner Name:

Owner Address: 243 DEER PARK AVE Owner City, St, Zip: BABYLON, NY 11702

Tank ID: 11 Tank Key: 43635 Installed: Not reported Capacity: 000000280

TRANSMISSION FLUID Content:

013106 Date Removed: ABOVE, IN Location: Construction: Not reported Dispenser: SUCTION Fill Type: **PUMPED**

Removed Tank. 06 Official Use:

Permit to Operate: 060702

Tank ID: 7 Tank Key: 42728 Installed: 2004 Capacity: 0000000280 Content: MOTOR OIL Not reported Date Removed: Location: ABOVE, IN STEEL / STEEL Construction: Dispenser: Not reported Fill Type: Not reported

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

INTER COUNTY MOTOR COACH (Continued)

U003534712

Official Use: Permitted Tank. Permit Runs Out. 09

022404 Permit to Operate:

Tank ID: 8 Tank Key: 42729 Installed: 2004 Capacity: 0000000280

Content: TRANSMISSION FLUID

Date Removed: Not reported ABOVE, IN Location: Construction: STEEL / STEEL Not reported Dispenser: Fill Type: Not reported

Official Use: Permitted Tank. Permit Runs Out. 09

Permit to Operate: 112204

Tank ID: 9 42730 Tank Key: Installed: Not reported 0000000275 Capacity: Content: #2 FUEL OIL Date Removed: Not reported ABOVE, IN Location: Construction: STEEL Dispenser: Not reported Fill Type: Not reported

Official Use: Exempt from Suffolk County Art 12 Regulation

Permit to Operate: Not reported

U003534979 **A8 CASANDRA APARTMENT BLDG** NY UST

West 240 DEER PARK AVE 1/8-1/4 BABYLON, NY 11702

0.138 mi.

729 ft. Site 2 of 2 in cluster A

Relative:

SUFFOLK CO. UST:

Facility ID: 2369 Higher Facility Reference #: 06325 Actual: Official Use: Abandoned, approved by plan review, awaiting construction for compliance inspection. 87

12 ft. Township: **BABYLON**

0102 010.00 001 017.000 Tax Map No:

Region: SUFFOLK

Tank Count:

Permit to Operate: Not reported

CASSANDRA REALTY CORP Owner Name: Owner Address: 2137 DEER PARK AVE Owner City, St, Zip: DEER PARK, NY 11729

Tank ID: Tank Key: 5791 Installed: 65

Capacity: 0000002000 Content: #2 FUEL OIL Date Removed: 010187 Location: UNDER, OUT Construction: STEEL

N/A

Direction Distance

Elevation Site Database(s) **EPA ID Number**

CASANDRA APARTMENT BLDG (Continued)

Dispenser: SUCTION **PUMPED** Fill Type:

MTA LIRR DEER PARK AVENUE RAILROAD BRIDGE **B9**

wsw DEER PARK AVE 200' N GEORGE ST

1/8-1/4 BABYLON, NY 11702

0.161 mi.

851 ft. Site 1 of 2 in cluster B

RCRA-SQG: Relative:

Date form received by agency: 03/26/2013 Higher

MTA LIRR DEER PARK AVENUE RAILROAD BRIDGE Facility name:

Actual: Facility address: DEER PARK AVE 200' N GEORGE ST 11 ft.

BABYLON, NY 11702

EPA ID: NYR000199596 94TH AVE - MC: 1944

Mailing address:

JAMAICA, NY 11435

Contact: ALBERT S ALBANO Contact address: 94TH AVE - MC: 1944

JAMAICA, NY 11435

Contact country: US

Contact telephone: (347) 494-6020

Contact email: AALBANO@LIRR.ORG

EPA Region:

Small Small Quantity Generator Classification:

Description: Handler: generates more than 100 and less than 1000 kg of hazardous

> waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of

hazardous waste at any time

Owner/Operator Summary:

MTA LONG ISLAND RAIL ROAD Owner/operator name:

SUTPHIN BLVD Owner/operator address:

JAMAICA, NY 11435

Owner/operator country: US

(718) 558-8228 Owner/operator telephone:

Legal status: State

Owner/Operator Type: Owner Owner/Op start date: 01/01/1850 Owner/Op end date: Not reported

MTA LONG ISLAND RAIL ROAD Owner/operator name:

Owner/operator address: Not reported Not reported

Owner/operator country: US Owner/operator telephone: Not reported Legal status: State

Owner/Operator Type: Operator Owner/Op start date: 01/01/1850 Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No **EDR ID Number**

U003534979

1016144379

NYR000199596

RCRA-SQG

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

MTA LIRR DEER PARK AVENUE RAILROAD BRIDGE (Continued)

1016144379

Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Hazardous Waste Summary:

Waste code: D008 LEAD Waste name:

Violation Status: No violations found

GAS STATION NY UST U003843325 10 NW **375 DEER PARK AVE** N/A

1/8-1/4 0.166 mi. 878 ft.

BABYLON, NY 11702

Relative: Higher

SUFFOLK CO. UST:

Facility ID: 2496 Facility Reference #: 06503

Actual: 13 ft.

Official Use: Removed Tank. 85

BABYLON Township:

0102 007.00 002 068.000 Tax Map No:

Region: SUFFOLK

Tank Count:

Permit to Operate: Not reported Not reported Owner Name: Owner Address: Not reported Owner City,St,Zip: Not reported

Tank ID: Tank Key: 6368 Installed: 80

Capacity: 0000010000 Content: GASOLINE Date Removed: 010185 Location: UNDER, OUT Construction: **FRP**

Dispenser: SUBMERSIBLE Fill Type: **GRAVITY**

Tank ID: 2 Tank Key: 6369 Installed: 80

0000010000 Capacity: **GASOLINE** Content: Date Removed: 010185 Location: UNDER, OUT

Construction: FRP

SUBMERSIBLE Dispenser:

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

GAS STATION (Continued) U003843325

Fill Type: **GRAVITY**

Tank ID: 3 6370 Tank Key: Installed: 80

0000010000 Capacity: **GASOLINE** Content: Date Removed: 010185 Location: UNDER, OUT

Construction: **FRP**

Dispenser: SUBMERSIBLE Fill Type: **GRAVITY**

Tank ID: 4 Tank Key: 6371 Installed: 60

000000550 Capacity: WASTE OIL Content: Date Removed: 010185 Location: UNDER, OUT Construction: STEEL Dispenser: SUCTION Fill Type: **GRAVITY**

Tank ID: 5 6372 Tank Key: Installed: Not reported Capacity: 000000550 Content: #2 FUEL OIL Date Removed: Not reported UNDER, OUT Location: Construction: STEEL Dispenser: SUCTION Fill Type: **PUMPED**

> Click this hyperlink while viewing on your computer to access additional NY_UST_SUFFOLK: detail in the EDR Site Report.

B11 EDR US Hist Cleaners 1015006313

wsw **180 DEER PARK AVE** 1/8-1/4 BABYLON, NY 11702

0.173 mi.

911 ft. Site 2 of 2 in cluster B

EDR Historical Cleaners: Relative:

Name: PARK AVENUE LAUNDROMAT Higher

Year:

Actual: Address: 180 DEER PARK AVE 11 ft.

Name: PARK AVENUE LAUNDROMAT

Year: 2000

Address: 180 DEER PARK AVE

PARK AVENUE LAUNDROMAT Name:

Year: 2001 N/A

Direction Distance

Elevation Site Database(s) EPA ID Number

(Continued) 1015006313

Address: 180 DEER PARK AVE

Name: PARK AVENUE LAUNDROMAT

Year: 2002

Address: 180 DEER PARK AVE

Name: PARK AVENUE LAUNDROMAT

Year: 2009

Address: 180 DEER PARK AVE

Name: PARK AVENUE LAUNDROMAT

Year: 2010

Address: 180 DEER PARK AVE

Name: PARK AVENUE LAUNDROMAT

Year: 2011

Address: 180 DEER PARK AVE

Name: PARK AVENUE LAUNDROMAT

Year: 2012

Address: 180 DEER PARK AVE

12 EDR US Hist Cleaners 1014980842

West 12 RAILROAD AVE 1/8-1/4 BABYLON, NY 11702 0.178 mi.

0.178 mi 938 ft.

Relative: EDR Historical Cleaners:

Higher Name: EXPRESS DRY CLEANERS

Year: 2001

Actual: Address: 12 RAILROAD AVE 12 ft.

Name: EXPRESS DRY CLEANERS

Year: 2002

Address: 12 RAILROAD AVE

Name: EXPRESS DRY CLEANERS

Year: 2003

Address: 12 RAILROAD AVE

Name: EXPRESS DRY CLEANERS

Year: 2004

Address: 12 RAILROAD AVE

Name: EXPRESS DRY CLEANERS

Year: 2006

Address: 12 RAILROAD AVE

Name: EXPRESS DRY CLEANERS

Year: 2007

Address: 12 RAILROAD AVE

Name: EXPRESS DRY CLEANERS

Year: 2008

Address: 12 RAILROAD AVE

Name: EXPRESS DRY CLEANERS

N/A

EDR ID Number

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

(Continued) 1014980842

Year: 2010

12 RAILROAD AVE Address:

EXPRESS DRY CLEANERS Name:

Year: 2011

12 RAILROAD AVE Address:

EXPRESS DRY CLEANERS Name:

Year: 2012

Address: 12 RAILROAD AVE

C13 **EDR US Hist Cleaners** 1015002855 169 DEER PARK AVE N/A

SW BABYLON, NY 11702 1/8-1/4 0.178 mi.

939 ft. Site 1 of 4 in cluster C

EDR Historical Cleaners: Relative:

Higher Name: WALTERS CLEANERS

> Year: 1999

Actual: Address: 169 DEER PARK AVE 10 ft.

WALTERS CLEANERS Name:

2001 Year:

Address: 169 DEER PARK AVE

Name: WALTERS CLEANERS

Year: 2003

Address: 169 DEER PARK AVE

Name: WALTERS CLEANERS

Year: 2004

169 DEER PARK AVE Address:

Name: WALTERS DRY CLEANERS INC

Year:

Address: 169 DEER PARK AVE

WALTERS CLEANERS INC Name:

Year: 2009

Address: 169 DEER PARK AVE

Name: WALTERS CLEANERS

2010 Year:

169 DEER PARK AVE Address:

WALTERS DRY CLEANER Name:

Year: 2011

169 DEER PARK AVE Address:

Name: WALTERS CLEANERS

Year: 2012

Address: 169 DEER PARK AVE

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

C14 WALTERS CLEANERS INCORPORATED NY MANIFEST S106434739
SW 169 DEER PARK AVENUE NY Spills N/A

169 DEER PARK AVENUE NY Spills N/A
BABYLON, NY 11702 NY DRYCLEANERS

1/8-1/4 BABY 0.178 mi.

939 ft. Site 2 of 4 in cluster C

Relative: NY MANIFEST:

Higher EPA ID: NYD981482029 Country: USA

Actual: Mailing Name: WALTERS CLEANERS INCORPORATED

10 ft. Mailing Contact: CHIANG NAM KIM

Mailing Address: 169 DEER PARK AVENUE

Mailing Address 2: Not reported
Mailing City: BABYLON
Mailing State: NY
Mailing Zip: 11702
Mailing Zip4: Not reported
Mailing Country: USA

Mailing Phone: 631-669-0838

Document ID: Not reported Manifest Status: Not reported TXR000081205 Trans1 State ID: Trans2 State ID: Not reported Generator Ship Date: 2012-09-11 2012-09-11 Trans1 Recv Date: Trans2 Recv Date: Not reported 2012-09-17 TSD Site Recy Date: Part A Recv Date: Not reported Part B Recv Date: Not reported NYD981482029 Generator EPA ID: Trans1 EPA ID: Not reported Trans2 EPA ID: Not reported TSDF ID: RID084802842 Waste Code: Not reported 390.0 Quantity: P - Pounds Units:

Number of Containers: 2.0

Container Type: DF - Fiberboard or plastic drums (glass)

Handling Method: R Material recovery of more than 75 percent of the total material.

Specific Gravity: 1.0 Year: 2012

Manifest Tracking Num: 003309265SKS

Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N

Manifest Ref Num:
Alt Fac RCRA Id:
Alt Fac Sign Date:
Mgmt Method Type Code:
Not reported
Not reported
H020

Document ID: Not reported Manifest Status: Not reported

Direction Distance Elevation

tance EDR ID Number vation Site Database(s) EPA ID Number

WALTERS CLEANERS INCORPORATED (Continued)

S106434739

Trans1 State ID: TXR000081205 Trans2 State ID: Not reported Generator Ship Date: 2012-09-11 Trans1 Recv Date: 2012-09-11 Trans2 Recv Date: Not reported 2012-09-17 TSD Site Recv Date: Part A Recv Date: Not reported Part B Recv Date: Not reported NYD981482029 Generator EPA ID: Trans1 EPA ID: Not reported Trans2 EPA ID: Not reported RID084802842 TSDF ID: Waste Code: Not reported Quantity: 390.0 Units: P - Pounds

Number of Containers: 2.0

Container Type: DF - Fiberboard or plastic drums (glass)

Handling Method: R Material recovery of more than 75 percent of the total material.

Specific Gravity: 1.0 Year: 2012

Manifest Tracking Num: 003309265SKS

Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N

Manifest Ref Num: Not reported
Alt Fac RCRA Id: Not reported
Alt Fac Sign Date: Not reported
Mgmt Method Type Code: H020

Document ID: Not reported Manifest Status: Not reported Trans1 State ID: TXR000050930 Trans2 State ID: NJD071629976 Generator Ship Date: 2011-07-25 Trans1 Recv Date: 2011-07-25 2011-07-29 Trans2 Recv Date: TSD Site Recv Date: 2011-08-02 Part A Recv Date: Not reported Part B Recv Date: Not reported Generator EPA ID: NYD981482029 Trans1 EPA ID: Not reported Trans2 EPA ID: Not reported RID084802842 TSDF ID: Waste Code: Not reported 390.0 Quantity: Units: P - Pounds

Number of Containers: 2.0

Container Type: DF - Fiberboard or plastic drums (glass)

Handling Method: R Material recovery of more than 75 percent of the total material.

Specific Gravity: 1.0 Year: 2011

Manifest Tracking Num: 002595821SKS

Direction Distance

Elevation Site Database(s) EPA ID Number

WALTERS CLEANERS INCORPORATED (Continued)

S106434739

EDR ID Number

Import Ind: N
Export Ind: N
Discr Quantity Ind: N
Discr Type Ind: N
Discr Residue Ind: N
Discr Partial Reject Ind: N
Discr Full Reject Ind: N

Manifest Ref Num:
Alt Fac RCRA Id:
Alt Fac Sign Date:
Mgmt Method Type Code:
Not reported
Not reported
Not reported
Not reported
H020

SPILLS:

 Facility ID:
 9205861

 DER Facility ID:
 199910

 Facility Type:
 ER

 Site ID:
 243381

 DEC Region:
 1

 Spill Date:
 8/20/199

Spill Date: 8/20/1992 Spill Number/Closed Date: 9205861 / 6/24/1994

Spill Cause: 9205661 / 6/24/199/

Spill Class: Possible release with minimal potential for fire or hazard or Known

release with no damage. DEC Response. Willing Responsible Party.

Corrective action taken.

SWIS: 5220
Investigator: KAKISPER
Referred To: Not reported
Reported to Dept: 8/20/1992
CID: Not reported
Water Affected: Not reported

Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: 6/24/1994

Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 8/26/1992
Spill Record Last Update: 6/27/1994
Spiller Name: Not reported

Spiller Company: WALKERS DRY CLEANERS

Spiller Address: Not reported

Spiller City,St,Zip: ZZ
Spiller Company: 001
Contact Name: Not reported
Contact Phone: Not reported

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was

"KISPERT"06/24/94: NO FURTHER ACTION REQUIRED,.10/10/95: This is

additional information about material spilled from the translation of

the old spill file: PERCHLORD ETHYLENE.

Remarks: FILTER GASKET FAILED, SPILLER CLEANED UP WITH RAGS, DRAINED REMAINING

FLUIDS INTO SAFETY CONTAINER

Material:

 Site ID:
 243381

 Operable Unit ID:
 973175

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

WALTERS CLEANERS INCORPORATED (Continued)

S106434739

Operable Unit: 01 410052 Material ID: Material Code: 0066A

Material Name: **UNKNOWN PETROLEUM**

Case No.: Not reported Material FA: Petroleum Quantity: 10 Units: Gallons Recovered: No Resource Affected: Not reported

False Oxygenate:

Tank Test:

DRYCLEANERS:

1-4720-01544 Facility ID: Phone Number: 631-669-0838 Region: Not reported Registration Effective Date: 3/17/1999 00:00:00

Inspection Date: 08JUN10 Install Date: 90/00 Drop Shop: Not reported Not reported Shutdown: Alternate Solvent: Not reported **Current Business:** Not reported

C15 **DONG HAE INC - DBA WALTERS CLEANERS** RCRA-SQG 1004756708 SW **169 DEER PARK AVE** RI MANIFEST NYD981482029

1/8-1/4 0.178 mi.

Site 3 of 4 in cluster C 939 ft.

RCRA-SQG: Relative:

Date form received by agency: 01/01/2007 Higher

BABYLON, NY 11702

Facility name: DONG HAE INC - DBA WALTERS CLEANERS

Actual: Facility address: 169 DEER PARK AVE 10 ft.

BABYLON, NY 11702 NYD981482029 EPA ID:

Mailing address: DEER PARK AVE BABYLON, NY 11702

Contact: KIM MISOOK DEER PARK AVE Contact address:

BABYLON, NY 11702

Contact country: US

(516) 669-0838 Contact telephone: Contact email: Not reported

EPA Region: 02

Classification: Small Small Quantity Generator

Description: Handler: generates more than 100 and less than 1000 kg of hazardous

> waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of

hazardous waste at any time

Owner/Operator Summary:

US AIRS

Direction Distance Elevation

e EDR ID Number on Site Database(s) EPA ID Number

DONG HAE INC - DBA WALTERS CLEANERS (Continued)

1004756708

Owner/operator name: FRANCIS GARVEY
Owner/operator address: 1801 HOUSE ARGYLE SQ

BABYLON, NY 11702

Owner/operator country: US

Owner/operator telephone: (516) 661-5300

Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: FRANCIS GARVEY
Owner/operator address: 1801 HOUSE ARGYLE SQ

BABYLON, NY 11702

Owner/operator country: US

Owner/operator telephone: (516) 661-5300
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006

Facility name: DONG HAE INC - DBA WALTERS CLEANERS Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 08/08/1995

Facility name: DONG HAE INC - DBA WALTERS CLEANERS Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

RI MANIFEST:

GEN Cert Date: 7/25/2011 Transporter Receipt Date: 7/25/2011

Number Of Containers: 2
Container Type: DF
Waste Code1: D007
Waste Code2: D029
Waste Code3: D039
Comment: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

DONG HAE INC - DBA WALTERS CLEANERS (Continued)

1004756708

EDR ID Number

Fee Exempt Code: Not reported
TSDF Name: SAFETY KLEEN
TSDF ID: RID084802842
TSDF Date: 7/29/2011
Transporter 2 Name: 7/29/2011
Transporter 2 ID: NJD071629976

Manifest Docket Number: 002595821SKS

Waste Description: TOXIC LIQUIDS ORGANIC NOS

Quantity: 390 WT/Vol Units: P Item Number: 1

Transporter Name: SAFETY KLEEN Transporter EPA ID: TXR000050930 **GEN Cert Date:** 7/25/2011 Transporter Recpt Date: 7/25/2011 Transporter 2 Recpt Date: 7/29/2011 TSDF Recpt Date: 7/29/2011 NYD981482029 EPA ID: Transporter 2 ID: NJD071629976

AIRS (AFS):

Airs Minor Details:

EPA plant ID: 110012642453

Plant name: WALTER'S CLEANERS INC
Plant address: 169 DEER PARK AVE

BABYLON, NY 117022830

County: SUFFOLK Region code: 02

Dunn & Bradst #: Not reported
Air quality cntrl region: 043
Sic code: 7216

Sic code desc: DRYCLEANING PLANTS, EXCEPT RUG

North Am. industrial classf: 812320

NAIC code description:

Default compliance status:

Default classification:

Drycleaning and Laundry Services (except Coin-Operated)

IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR

Govt facility: ALL OTHER FACILITIES NOT OWNED OR OPERATED BY A FEDERAL, STATE, OR

LOCAL GOVERNMENT

Current HPV: Not reported

Compliance and Enforcement Major Issues:

Air program: SIP SOURCE
National action type: Not reported
Date achieved: 00000
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: Not reported
Date achieved: 00000
Penalty amount: Not reported

Air program: SIP SOURCE National action type: Not reported

Direction Distance Elevation

EDR ID Number
on Site Database(s) EPA ID Number

DONG HAE INC - DBA WALTERS CLEANERS (Continued)

1004756708

Date achieved: 00000
Penalty amount: Not reported

Air program: SIP SOURCE
National action type: Not reported
Date achieved: 00000
Penalty amount: Not reported

Historical Compliance Minor Sources:

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

Hist compliance date: 1001 Air prog code hist file: 0

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

Hist compliance date: 1002 Air prog code hist file: M

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

Hist compliance date: 1003 Air prog code hist file: M

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

Hist compliance date: 1004 Air prog code hist file: M

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

Hist compliance date: 1102 Air prog code hist file: 0

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

Hist compliance date: 1103 Air prog code hist file: 0

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

Hist compliance date: 1104 Air prog code hist file: M

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

Hist compliance date: 1201 Air prog code hist file: M

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

Hist compliance date: 1203 Air prog code hist file: 0

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS Hist compliance date: 1204

Hist compliance date: 12 Air prog code hist file: 0

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

Hist compliance date: 1001 Air prog code hist file: M

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

Hist compliance date: 1002 Air prog code hist file: 0 Map ID MAP FINDINGS
Direction

Distance Elevation Site

Site Database(s) EPA ID Number

DONG HAE INC - DBA WALTERS CLEANERS (Continued)

1004756708

EDR ID Number

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

Hist compliance date: 1003 Air prog code hist file: 0

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

Hist compliance date: 1004 Air prog code hist file: 0

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

Hist compliance date: 1101 Air prog code hist file: 0

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

Hist compliance date: 110
Air prog code hist file: M

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

Hist compliance date: 1102 Air prog code hist file: M

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

Hist compliance date: 1103 Air prog code hist file: M

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

Hist compliance date: 1104 Air prog code hist file: 0

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

Hist compliance date: 1201 Air prog code hist file: 0

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

Hist compliance date: 1202 Air prog code hist file: 0

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

Hist compliance date: 1202 Air prog code hist file: M

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

Hist compliance date: 1203 Air prog code hist file: M

State compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

Hist compliance date: 1204 Air prog code hist file: M

Compliance & Violation Data by Minor Sources:
Air program code: SIP SOURCE
Plant air program pollutant: Not reported

Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR Def. poll. compliance status: IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS

Def. attainment/non attnmnt: ATTAINMENT AREA FOR GIVEN POLLUTANT

Repeat violator date: Not reported Turnover compliance: Not reported

Direction Distance

EDR ID Number Elevation Site **EPA ID Number** Database(s)

DONG HAE INC - DBA WALTERS CLEANERS (Continued)

1004756708

Air program code: MACT (SECTION 63 NESHAPS)

Plant air program pollutant: Not reported

Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS Def. poll. compliance status:

Def. attainment/non attnmnt: ATTAINMENT AREA FOR GIVEN POLLUTANT

Repeat violator date: Not reported Turnover compliance: Not reported

MACT (SECTION 63 NESHAPS) Air program code:

Plant air program pollutant: Not reported

Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS Def. poll. compliance status:

Def. attainment/non attnmnt: **UNCLASSIFIED** Repeat violator date: Not reported Turnover compliance: Not reported

MACT (SECTION 63 NESHAPS) Air program code:

Plant air program pollutant: Not reported

Default pollutant classification: POTENTIAL UNCONTROLLED EMISSIONS < 100 TONS/YEAR IN COMPLIANCE WITH PROCEDURAL REQUIREMENTS Def. poll. compliance status:

Def. attainment/non attnmnt: ATTAINMENT AREA FOR GIVEN POLLUTANT

Repeat violator date: Not reported Turnover compliance: Not reported

16 **BABYLON PHOTO LAB** South 21 COOPER ST 1/8-1/4 BABYLON, NY 11702 0.181 mi.

RCRA-CESQG 1000397453 FINDS NYD982744278 NY MANIFEST

958 ft.

RCRA-CESQG: Relative:

Date form received by agency: 01/01/2007 Lower

BABYLON PHOTO LAB Facility name: Actual: Facility address: 21 COOPER ST

6 ft. BABYLON, NY 11702

EPA ID: NYD982744278 Mailing address: COOPER ST

BABYLON, NY 11702 DAVID PIAN Contact:

COOPER ST Contact address: BABYLON, NY 11702

Contact country:

Contact telephone: (516) 661-0042 Contact email: Not reported

EPA Region:

Land type: Facility is not located on Indian land. Additional information is not known.

Classification: Conditionally Exempt Small Quantity Generator

Handler: generates 100 kg or less of hazardous waste per calendar Description:

month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of

Direction Distance Elevation

Site Database(s) EPA ID Number

BABYLON PHOTO LAB (Continued)

1000397453

EDR ID Number

any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name: DAVID PIAN

Owner/operator address: 152-39 ROOSEVELT AVE FLUSHING, NY 11354

Owner/operator country: US

Owner/operator telephone: (718) 359-3010
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: DAVID PIAN

Owner/operator address: 152-39 ROOSEVELT AVE

FLUSHING, NY 11354

Owner/operator country: US

Owner/operator telephone: (718) 359-3010

Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No No Used oil transfer facility: Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006

Facility name: BABYLON PHOTO LAB

Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 07/25/1989

Facility name: BABYLON PHOTO LAB Classification: Small Quantity Generator

Facility Has Received Notices of Violations:

Regulation violated: Not reported
Area of violation: Generators - General

Date violation determined: 08/13/1990

Direction Distance Elevation

ation Site Database(s) EPA ID Number

BABYLON PHOTO LAB (Continued)

1000397453

EDR ID Number

Date achieved compliance: 08/13/1990 Violation lead agency: State Enforcement action: Not reported Enforcement action date: Not reported Enf. disposition status: Not reported Not reported Enf. disp. status date: Not reported Enforcement lead agency: Proposed penalty amount: Not reported Final penalty amount: Not reported Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 12/03/1998

Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE

Area of violation:

Date achieved compliance:

Evaluation lead agency:

Not reported

Not reported

EPA

Evaluation date: 08/13/1990

Evaluation: NON-FINANCIAL RECORD REVIEW

Area of violation: Generators - General

Date achieved compliance: 08/13/1990 Evaluation lead agency: State

FINDS:

Registry ID: 110004432908

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID: NYD982744278

Country: USA

Mailing Name: BABYLON PHOTO
Mailing Contact: BABYLON PHOTO
Mailing Address: 260 17TH STREET
Mailing Address 2: Not reported
Mailing City: WEST BABYLON

Mailing State: NY
Mailing Zip: 11704
Mailing Zip4: 2726
Mailing Country: USA

Mailing Phone: 516-321-0564

Document ID: NYB2392344

Manifest Status: Completed copy

Trans1 State ID: HM3506

Trans2 State ID: Not reported

Generator Ship Date: 910918

Direction Distance Elevation

vation Site Database(s) EPA ID Number

BABYLON PHOTO LAB (Continued)

1000397453

EDR ID Number

 Trans1 Recv Date:
 910918

 Trans2 Recv Date:
 Not reported

 TSD Site Recv Date:
 910918

 Part A Recv Date:
 911007

 Part B Recv Date:
 910927

 Conserver FPA ID:
 NVD08274403

 Generator EPA ID:
 NYD982744278

 Trans1 EPA ID:
 NYD082785429

 Trans2 EPA ID:
 Not reported

 TSDF ID:
 NYD082785429

Waste Code: D011 - SILVER 5.0 MG/L TCLP

Quantity: 00110

Units: G - Gallons (liquids only)* (8.3 pounds)

Number of Containers: 002

Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.

Specific Gravity: 096 Year: 91

Document ID: NYB4442049 Manifest Status: Completed copy Trans1 State ID: HL4120 Trans2 State ID: Not reported Generator Ship Date: 920304 Trans1 Recv Date: 920304 Trans2 Recv Date: Not reported TSD Site Recy Date: 920304 Part A Recv Date: 920319 Part B Recv Date: 920312

 Generator EPA ID:
 NYD982744278

 Trans1 EPA ID:
 NYD082785429

 Trans2 EPA ID:
 Not reported

 TSDF ID:
 NYD082785429

Waste Code: D011 - SILVER 5.0 MG/L TCLP

Quantity: 00110

Units: G - Gallons (liquids only)* (8.3 pounds)

Number of Containers: 002

Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.

Specific Gravity: 096 Year: 92

Document ID: NJA2960806 Manifest Status: Not reported Trans1 State ID: NYR000025767 Trans2 State ID: Not reported Generator Ship Date: 05/26/1998 Trans1 Recv Date: 05/26/1998 Trans2 Recv Date: Not reported 06/04/1998 TSD Site Recv Date: Part A Recv Date: Not reported Part B Recv Date: Not reported Generator EPA ID: NYD982744278 Trans1 EPA ID: NJR000022442 Trans2 EPA ID: Not reported TSDF ID: 50163

Direction Distance

Elevation Site Database(s) **EPA ID Number**

BABYLON PHOTO LAB (Continued)

1000397453

EDR ID Number

Waste Code: D011 - SILVER 5.0 MG/L TCLP

Quantity: 00110

Units: G - Gallons (liquids only)* (8.3 pounds)

Number of Containers: 002

Container Type: DF - Fiberboard or plastic drums (glass)

Handling Method: R Material recovery of more than 75 percent of the total material.

Specific Gravity: 01.00 Year: 98

Document ID: NJA2947296 Manifest Status: Not reported NYR000025767 Trans1 State ID: Trans2 State ID: Not reported Generator Ship Date: 04/02/1998 Trans1 Recv Date: 04/02/1998 Trans2 Recy Date: Not reported TSD Site Recv Date: 04/10/1998 Part A Recv Date: Not reported Part B Recv Date: Not reported Generator EPA ID: NYD982744278 Trans1 EPA ID: NJR000022442 Trans2 EPA ID: Not reported TSDF ID: 50163

D011 - SILVER 5.0 MG/L TCLP Waste Code:

Quantity: 00110

Units: G - Gallons (liquids only)* (8.3 pounds)

Number of Containers: 002

Container Type: DF - Fiberboard or plastic drums (glass)

Handling Method: R Material recovery of more than 75 percent of the total material.

Specific Gravity: 01.00 Year: 98

Document ID: NYB4325517 Manifest Status: Completed copy Trans1 State ID: HM3506 Trans2 State ID: Not reported Generator Ship Date: 930329 Trans1 Recv Date: 930329 Trans2 Recv Date: Not reported TSD Site Recv Date: 930329 Part A Recv Date: 930409 Part B Recv Date: 930407

Generator EPA ID: NYD982744278 Trans1 EPA ID: NYD082785429 Trans2 EPA ID: Not reported TSDF ID: NYD082785429

Waste Code: D011 - SILVER 5.0 MG/L TCLP

00110 Quantity:

Units: G - Gallons (liquids only)* (8.3 pounds)

Number of Containers:

DF - Fiberboard or plastic drums (glass) Container Type: Handling Method: T Chemical, physical, or biological treatment.

Specific Gravity: 096 93 Year:

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

BABYLON PHOTO LAB (Continued)

1000397453

Document ID: NYB5094702 Manifest Status: Completed copy Trans1 State ID: XC2643 Trans2 State ID: Not reported Generator Ship Date: 940527 Trans1 Recv Date: 940527 Trans2 Recv Date: Not reported TSD Site Recy Date: 940527 Part A Recv Date: 940606 Part B Recv Date: 940608

NYD982744278 Generator EPA ID: Trans1 EPA ID: NYD981182769 Trans2 EPA ID: Not reported TSDF ID: NYD981182769

Waste Code: D011 - SILVER 5.0 MG/L TCLP

Quantity: 00110

G - Gallons (liquids only)* (8.3 pounds) Units:

Number of Containers: 002

Container Type: DF - Fiberboard or plastic drums (glass)

R Material recovery of more than 75 percent of the total material. Handling Method:

Specific Gravity: 100 Year: 94

NYA7040799 Document ID: Manifest Status: Completed copy Trans1 State ID: IA8036 Trans2 State ID: Not reported 891005 Generator Ship Date: 891005 Trans1 Recv Date: Trans2 Recv Date: Not reported TSD Site Recy Date: 891005 Part A Recv Date: 891012 Part B Recv Date: 891012

NYD982744278 Generator EPA ID: NYD082785429 Trans1 EPA ID: Trans2 EPA ID: Not reported TSDF ID: NYD082785429

D011 - SILVER 5.0 MG/L TCLP Waste Code:

Quantity: 00055

Units: G - Gallons (liquids only)* (8.3 pounds)

Number of Containers: 001

Container Type: DF - Fiberboard or plastic drums (glass) Handling Method: T Chemical, physical, or biological treatment.

Specific Gravity: 097 Year: 89

Document ID: NYH0240921 Manifest Status: Not reported NYD082785429 Trans1 State ID: Trans2 State ID: Not reported 12/17/2001 Generator Ship Date: Trans1 Recv Date: 12/17/2001 Trans2 Recy Date: Not reported 12/17/2001 TSD Site Recy Date: Part A Recv Date: Not reported

Direction Distance Elevation

nce EDR ID Number ation Site Database(s) EPA ID Number

BABYLON PHOTO LAB (Continued)

1000397453

Part B Recv Date: Not reported
Generator EPA ID: NYD982744278
Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: 6050PB

Waste Code: D011 - SILVER 5.0 MG/L TCLP

Quantity: 00055

Units: G - Gallons (liquids only)* (8.3 pounds)

Number of Containers: 001

Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.

Specific Gravity: 01.00 Year: 2001

Document ID: NYH0301824 Manifest Status: Not reported NYD082785429 Trans1 State ID: Trans2 State ID: Not reported Generator Ship Date: 07/31/2002 Trans1 Recv Date: 07/31/2002 Trans2 Recv Date: Not reported TSD Site Recy Date: 07/31/2002 Part A Recv Date: Not reported Part B Recv Date: Not reported Generator EPA ID: NYD982744278 Trans1 EPA ID: NYD082785429 Trans2 EPA ID: Not reported TSDF ID: 23138PA

Waste Code: D011 - SILVER 5.0 MG/L TCLP

Quantity: 00055

Units: G - Gallons (liquids only)* (8.3 pounds)

Number of Containers: 001

Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.

Specific Gravity: 01.00 Year: 2002

Document ID: NYH0277533 Manifest Status: Not reported Trans1 State ID: NYD082785429 Trans2 State ID: Not reported Generator Ship Date: 06/07/2002 Trans1 Recv Date: 06/07/2002 Trans2 Recv Date: Not reported TSD Site Recv Date: 06/07/2002 Part A Recv Date: Not reported Part B Recv Date: Not reported Generator EPA ID: NYD982744278 Trans1 EPA ID: NYD082785429 Trans2 EPA ID: Not reported TSDF ID: PW8913

Waste Code: D011 - SILVER 5.0 MG/L TCLP

Quantity: 00055

Units: G - Gallons (liquids only)* (8.3 pounds)

Number of Containers: 001

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

BABYLON PHOTO LAB (Continued)

1000397453

Container Type: DF - Fiberboard or plastic drums (glass) T Chemical, physical, or biological treatment. Handling Method:

Specific Gravity: 01.00 Year: 2002

Document ID: NYH0250434 Manifest Status: Not reported Trans1 State ID: NYD082785429 Trans2 State ID: Not reported Generator Ship Date: 01/24/2002 Trans1 Recv Date: 01/24/2002 Trans2 Recv Date: Not reported TSD Site Recv Date: 01/24/2002 Part A Recv Date: Not reported Part B Recv Date: Not reported NYD982744278 Generator EPA ID: Trans1 EPA ID: NYD082785429 Trans2 EPA ID: Not reported PX3640 TSDF ID:

Waste Code: D011 - SILVER 5.0 MG/L TCLP

Quantity: 00055

G - Gallons (liquids only)* (8.3 pounds) Units: Number of Containers: Container Type: DF - Fiberboard or plastic drums (glass) Handling Method: T Chemical, physical, or biological treatment.

Specific Gravity: 01.00 Year: 2002

Document ID: NYB2072448

Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC

Trans1 State ID: HL4120 Trans2 State ID: Not reported Generator Ship Date: 901112 Trans1 Recv Date: 901112 Trans2 Recv Date: Not reported TSD Site Recv Date: 901112 Part A Recv Date: 910409 Part B Recv Date: 901207

Generator EPA ID: NYD982744278 Trans1 EPA ID: NYD082785429 Trans2 EPA ID: Not reported TSDF ID: NYD082785429

Waste Code: D011 - SILVER 5.0 MG/L TCLP

Quantity: 00110

Units: G - Gallons (liquids only)* (8.3 pounds)

Number of Containers: 002

Container Type: DF - Fiberboard or plastic drums (glass) T Chemical, physical, or biological treatment. Handling Method:

Specific Gravity: 097 Year: 90

Document ID: NYB2138886

Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC

Trans1 State ID: HM3506

Direction Distance Elevation

tance EDR ID Number vation Site Database(s) EPA ID Number

BABYLON PHOTO LAB (Continued)

1000397453

Trans2 State ID: Not reported 900711 Generator Ship Date: Trans1 Recv Date: 900711 Trans2 Recv Date: Not reported TSD Site Recv Date: 900711 900809 Part A Recv Date: Part B Recv Date: 900814 Generator EPA ID: NYD982744278

Trans1 EPA ID: NYD082785429
Trans2 EPA ID: Not reported
TSDF ID: NYD082785429

Waste Code: D011 - SILVER 5.0 MG/L TCLP

Quantity: 00055

Units: G - Gallons (liquids only)* (8.3 pounds)

Number of Containers: 002

Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.

Specific Gravity: 097 Year: 90

Document ID: NYH0268119 Manifest Status: Not reported Trans1 State ID: NYD082785429 Trans2 State ID: Not reported Generator Ship Date: 04/10/2002 Trans1 Recv Date: 04/10/2002 Trans2 Recv Date: Not reported TSD Site Recv Date: 04/10/2002 Not reported Part A Recv Date: Part B Recv Date: Not reported Generator EPA ID: NYD982744278 Trans1 EPA ID: NYD082785429 Trans2 EPA ID: Not reported TSDF ID: 12210PA

Waste Code: D011 - SILVER 5.0 MG/L TCLP

Quantity: 00050

Units: G - Gallons (liquids only)* (8.3 pounds)

Number of Containers: 001

Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.

Specific Gravity: 01.00 Year: 2002

NYB4363407 Document ID: Manifest Status: Completed copy Trans1 State ID: PD9938 Trans2 State ID: Not reported Generator Ship Date: 921203 Trans1 Recv Date: 921203 Trans2 Recv Date: Not reported TSD Site Recv Date: 921203 Part A Recv Date: 921210 Part B Recv Date: 921215

Generator EPA ID: NYD982744278
Trans1 EPA ID: NYD082785429

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

BABYLON PHOTO LAB (Continued)

1000397453

Trans2 EPA ID: Not reported TSDF ID: NYD082785429

D011 - SILVER 5.0 MG/L TCLP Waste Code:

00055 Quantity:

Units: G - Gallons (liquids only)* (8.3 pounds)

Number of Containers: 001

DF - Fiberboard or plastic drums (glass) Container Type: Handling Method: T Chemical, physical, or biological treatment.

Specific Gravity: 096 Year: 92

NYH0409689 Document ID: Manifest Status: Not reported Trans1 State ID: 12210PA Trans2 State ID: Not reported Generator Ship Date: 04/16/2004 Trans1 Recv Date: 04/16/2004 Trans2 Recv Date: Not reported TSD Site Recv Date: 04/16/2004 Part A Recv Date: Not reported Part B Recv Date: Not reported Generator EPA ID: NYD982744278 Trans1 EPA ID: NYD082785429 Trans2 EPA ID: Not reported NYD082785 TSDF ID:

Waste Code: D011 - SILVER 5.0 MG/L TCLP

Quantity: 00055

Units: G - Gallons (liquids only)* (8.3 pounds)

Number of Containers: 001

DF - Fiberboard or plastic drums (glass) Container Type: Handling Method: T Chemical, physical, or biological treatment.

Specific Gravity: 01.00 Year: 2004

Document ID: NYH0393138 Manifest Status: Not reported 12210PA Trans1 State ID: Not reported Trans2 State ID: Generator Ship Date: 03/15/2004 Trans1 Recv Date: 03/15/2004 Trans2 Recv Date: Not reported TSD Site Recv Date: 03/15/2004 Part A Recv Date: Not reported Part B Recv Date: Not reported Generator EPA ID: NYD982744278 Trans1 EPA ID: NYD082785429 Trans2 EPA ID: Not reported TSDF ID: NYD082785

Waste Code: D011 - SILVER 5.0 MG/L TCLP

Quantity: 00055

G - Gallons (liquids only)* (8.3 pounds) Units:

Number of Containers:

Container Type: DF - Fiberboard or plastic drums (glass) Handling Method: T Chemical, physical, or biological treatment.

Specific Gravity: 01.00

Direction Distance Elevation

evation Site Database(s) EPA ID Number

BABYLON PHOTO LAB (Continued)

1000397453

EDR ID Number

Year: 2004

Document ID: NYB2139885

Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC

Trans1 State ID: 00000000 Trans2 State ID: 00000000 900525 Generator Ship Date: Trans1 Recv Date: 900525 Trans2 Recv Date: Not reported 900525 TSD Site Recv Date: 901023 Part A Recv Date: Part B Recv Date: 900531

 Generator EPA ID:
 NYD982744278

 Trans1 EPA ID:
 NYD082785429

 Trans2 EPA ID:
 Not reported

 TSDF ID:
 NYD082785429

Waste Code: D011 - SILVER 5.0 MG/L TCLP

Quantity: 00110

Units: G - Gallons (liquids only)* (8.3 pounds)

Number of Containers: 002

Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.

Specific Gravity: 100 Year: 90

Document ID: NYB5584509 Manifest Status: Completed copy HM3506 Trans1 State ID: Not reported Trans2 State ID: Generator Ship Date: 920715 Trans1 Recv Date: 920715 Trans2 Recv Date: Not reported TSD Site Recv Date: 920715 Part A Recv Date: Not reported Part B Recv Date: 920727 Generator EPA ID: NYD982744278 Trans1 EPA ID: NYD082785429 Trans2 EPA ID: Not reported TSDF ID: NYD082785429

Waste Code: D011 - SILVER 5.0 MG/L TCLP

Quantity: 00110

Units: G - Gallons (liquids only)* (8.3 pounds)

Number of Containers: 002

Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.

Specific Gravity: 096 Year: 92

Document ID: NYB5212368

Manifest Status: Completed copy
Trans1 State ID: HM3506
Trans2 State ID: Not reported
Generator Ship Date: 930820
Trans1 Recv Date: 930820

Direction Distance

Elevation Site Database(s) EPA ID Number

BABYLON PHOTO LAB (Continued)

1000397453

EDR ID Number

Trans2 Recv Date: Not reported 930820 TSD Site Recv Date: Part A Recv Date: 930826 Part B Recv Date: 930830 Generator EPA ID: NYD982744278 Trans1 EPA ID: NYD082785429 Trans2 EPA ID: Not reported TSDF ID: NYD082785429

Waste Code: D011 - SILVER 5.0 MG/L TCLP

Quantity: 00110

Units: G - Gallons (liquids only)* (8.3 pounds)

Number of Containers: 002

Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: T Chemical, physical, or biological treatment.

Specific Gravity: 096 Year: 93

<u>Click this hyperlink</u> while viewing on your computer to access 68 additional NY_MANIFEST: record(s) in the EDR Site Report.

C17 PARKING LOT NY UST U003844969
SW 157-175 DEER PARK AVE N/A

SW 157-175 DEER PARK AVE 1/8-1/4 BABYLON, NY 11702

0.184 mi.

973 ft. Site 4 of 4 in cluster C

Relative: SUFFOLK CO. UST:

Higher Facility ID: 15699 Facility Reference #: 15938

Actual: Official Use: Removed Tank. 01

10 ft. RARYLON

RARYLON

Township: BABYLON
Tax Map No: 0102 010.00 004 003.000

Tax Map No: 0102 010.00 Region: SUFFOLK

Tank Count: 5
Permit to Operate: Not reported

Owner Name: GARVEY PROPERTIES

Owner Address: PO BOX 788

Owner City, St, Zip: BABYLON, NY 11702

Tank ID: Tank Key: 42639 Installed: Not reported Capacity: 000000550 #2 FUEL OIL Content: Date Removed: 050301 UNDER, OUT Location: Construction: STEEL Dispenser: Not reported Fill Type: Not reported

 Tank ID:
 2

 Tank Key:
 42640

 Installed:
 Not reported

 Capacity:
 0000000550

 Content:
 #2 FUEL OIL

 Date Removed:
 050301

 Location:
 UNDER, OUT

Direction Distance

Elevation Site Database(s) EPA ID Number

PARKING LOT (Continued) U003844969

Construction: STEEL
Dispenser: Not reported
Fill Type: Not reported

Tank ID: Tank Key: 42641 Installed: Not reported Capacity: 000000550 Content: #2 FUEL OIL 050301 Date Removed: UNDER, OUT Location: Construction: STEEL Dispenser: Not reported Fill Type: Not reported

Tank ID: 4 Tank Key: 42642 Installed: Not reported 000000550 Capacity: Content: #2 FUEL OIL Date Removed: 050301 Location: UNDER, OUT Construction: STEEL Dispenser: Not reported Fill Type: Not reported

Tank ID: 5 Tank Key: 42643 Installed: Not reported 000000550 Capacity: Content: #2 FUEL OIL Date Removed: 050301 UNDER, OUT Location: Construction: STEEL Dispenser: Not reported Fill Type: Not reported

Click this hyperlink while viewing on your computer to access additional NY_UST_SUFFOLK: detail in the EDR Site Report.

D18 EDR US Hist Auto Stat 1015509964 WNW 47 SAMMIS AVE EDR US Hist Auto Stat N/A

WNW 47 SAMMIS AVE 1/8-1/4 BABYLON, NY 11702

0.216 mi.

1140 ft. Site 1 of 3 in cluster D

Relative: EDR Historical Auto Stations:

Higher Name: WOLF'S CONTROL SVCE STATION

Year: 1999

Actual: Address: 47 SAMMIS AVE

13 ft.

EDR ID Number

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

D19 **WOLFS CENTRAL SERVICE** NY AST A100265011 WNW **47 SAMMIS AVE** N/A

1/8-1/4 BABYLON, NY 11702

0.216 mi.

1140 ft. Site 2 of 3 in cluster D

Relative:

Actual:

13 ft.

SUFFOLK CO. AST:

Higher

Facility ID: 376 Facility Reference #: 10167 **BABYLON** Township: Tax Map No: 0102 Tank Count:

Region: **SUFFOLK**

WOLFS CENTRAL SERVICE Owner Name:

47 SAMMIS AVE Owner Address: Owner City, St, Zip: BABYLON, NY 11702

Tank ID: 8 1190 Tank Key: Installed: Not reported Capacity: 000000275 Content: WASTE OIL Date Removed: 062193 Location: ABOVE, OUT Construction: STEEL Dispenser: SUCTION Fill Type: **PUMPED**

Removed Tank. 91 Official Use: Permit to Operate: Not reported

Tank ID: 9 Tank Key: 1191 Installed: Not reported Capacity: 000000275 Content: #2 FUEL OIL Not reported Date Removed: ABOVE, OUT Location: STEEL Construction: Dispenser: SUCTION Fill Type: **PUMPED**

Official Use: Exempt from Suffolk County Art 12 Regulation

Permit to Operate: Not reported

D20 **WOLFS CENTRAL SERVICE**

WNW **47 SAMMIS AVE** 1/8-1/4 BABYLON, NY 11702 0.216 mi.

1140 ft. Site 3 of 3 in cluster D

SUFFOLK CO. UST: Relative:

Facility ID: Higher

376 Facility Reference #: 10167 Actual: Official Use:

Removed Tank. 86 13 ft. Township: **BABYLON**

Tax Map No: 0102 006.00 003 075.000

Region: **SUFFOLK**

Tank Count: 9

Permit to Operate: Not reported

Owner Name: WOLFS CENTRAL SERVICE NY UST U003960882 N/A

Direction Distance Elevation

stance EDR ID Number evation Site Database(s) EPA ID Number

WOLFS CENTRAL SERVICE (Continued)

U003960882

Owner Address: 47 SAMMIS AVE
Owner City,St,Zip: BABYLON, NY 11702

Tank ID: 1183 Tank Key: Installed: Not reported Capacity: 0000002000 Content: **GASOLINE** Date Removed: 010186 Location: UNDER, OUT STEEL Construction: SUCTION Dispenser: Fill Type: **GRAVITY**

2 Tank ID: Tank Key: 1184 Installed: Not reported 0000002000 Capacity: **GASOLINE** Content: Date Removed: 010183 UNDER, OUT Location: Construction: STEEL Dispenser: SUCTION Fill Type: **GRAVITY**

Tank ID: 3 Tank Key: 1185 Installed: Not reported Capacity: 0000002000 Content: GASOLINE Date Removed: 010186 Location: UNDER, OUT Construction: STEEL Dispenser: SUCTION Fill Type: **GRAVITY**

Tank ID: 4 Tank Key: 1186 Installed: Not reported 0000002000 Capacity: GASOLINE Content: Date Removed: 010186 Location: UNDER, OUT Construction: STEEL Dispenser: SUCTION Fill Type: **GRAVITY**

 Tank ID:
 5

 Tank Key:
 1187

 Installed:
 86

Capacity: 0000004000
Content: GASOLINE
Date Removed: Not reported

Direction Distance

Distance EDR ID Number
Elevation Site EPA ID Number

WOLFS CENTRAL SERVICE (Continued) U003960882

Location: UNDER, OUT

Construction: FRP

Dispenser: SUBMERSIBLE Fill Type: GRAVITY

Click this hyperlink while viewing on your computer to access 2 additional NY_UST_SUFFOLK: record(s) in the EDR Site Report.

21 EDR US Hist Auto Stat 1015150516

11 GROVE PL N/A

SW 11 GROVE PL 1/8-1/4 BABYLON, NY 11702

0.222 mi. 1174 ft.

Relative: EDR Historical Auto Stations:

Higher Name: KERR CAR TOWING

Year: 2005

Actual: Address: 11 GROVE PL 10 ft.

22 JOSEPH LALIA D.P.M RCRA NonGen / NLR 1004756503 NNW 421 DEER PARK AVE FINDS NYD110591047

NNW 421 DEER PARK AVE 1/8-1/4 BABYLON, NY 11702

0.222 mi. 1174 ft.

Relative: RCRA NonGen / NLR:

Higher Date form received by agency: 01/01/2007

Facility name: JOSEPH LALIA D.P.M

Actual: Facility address: 421 DEER PARK AVE

12 ft. BABYLON, NY 11702

EPA ID: NYD110591047
Mailing address: DEER PARK AVE

BABYLON, NY 11702

Contact: Not reported
Contact address: DEER PARK AVE

BABYLON, NY 11702

Contact country: US

Contact telephone: Not reported Contact email: Not reported

EPA Region: 02

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: JOSEPH LALIA
Owner/operator address: NOT REQUIRED

NOT REQUIRED, WY 99999

Owner/operator country: US

Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: JOSEPH LALIA
Owner/operator address: NOT REQUIRED

Elevation Site

Distance

Site Database(s) EPA ID Number

JOSEPH LALIA D.P.M (Continued)

1004756503

EDR ID Number

NOT REQUIRED, WY 99999

Owner/operator country: US

Owner/operator telephone: (212) 555-1212
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: Nο Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006

Facility name: JOSEPH LALIA D.P.M Classification: Not a generator, verified

Date form received by agency: 10/29/1993

Facility name: JOSEPH LALIA D.P.M

Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 05/17/1989

Facility name: JOSEPH LALIA D.P.M Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004380214

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

E23 **VILLAGE FUEL OIL NY UST** U003534460 NE **65 JOHN ST NY AST** N/A

1/8-1/4 BABYLON, NY 11702

0.223 mi.

1175 ft. Site 1 of 3 in cluster E

Relative: Higher

SUFFOLK CO. UST:

756 Facility ID: Facility Reference #: 01350

Actual: Official Use: 9 ft. Township:

Exempt from Suffolk County Art 12 Regulation **BABYLON**

Tax Map No: 0102 007.00 002 084.000

SUFFOLK Region: Tank Count:

Permit to Operate: Not reported

Owner Name: JOHN STREET REALTY

Owner Address: PO BOX 340

Owner City,St,Zip: BABYLON, NY 11702

Tank ID: 6 Tank Key: 2367

Not reported Installed: 0000000250 Capacity: Content: #2 FUEL OIL Date Removed: Not reported UNDER, OUT Location: Construction: STEEL Dispenser: Not reported Fill Type: Not reported

Tank ID: Tank Key: 2368 Installed: Not reported 000000250 Capacity: Content: #2 FUEL OIL Not reported Date Removed: UNDER, OUT Location: Construction: STEEL Dispenser: Not reported Fill Type: Not reported

SUFFOLK CO. AST:

Facility ID: 756 Facility Reference #: 01350 **BABYLON** Township: Tax Map No: 0102 Tank Count:

Region: SUFFOLK

Owner Name: JOHN STREET REALTY

Owner Address: PO BOX 340

BABYLON, NY 11702 Owner City,St,Zip:

Tank ID: 2362 Tank Key: Installed: 58

0000024000 Capacity: Content: #2 FUEL OIL 081794 Date Removed:

Map ID
Direction
Distance
Elevation

Elevation Site Database(s) EPA ID Number

VILLAGE FUEL OIL (Continued)

U003534460

EDR ID Number

Location: ABOVE
Construction: STEEL
Dispenser: SUBMERSIBLE

Fill Type: PUMPED
Official Use: Removed Tank. 94
Permit to Operate: Not reported

 Tank ID:
 2

 Tank Key:
 2363

 Installed:
 58

Capacity: 0000014500
Content: #2 FUEL OIL
Date Removed: 081794
Location: ABOVE
Construction: STEEL

Dispenser: SUBMERSIBLE Fill Type: PUMPED

Official Use: Removed Tank. 94
Permit to Operate: Not reported

Tank ID: 3
Tank Key: 2364
Installed: 68

Capacity: 0000017500
Content: #2 FUEL OIL
Date Removed: 081794
Location: ABOVE
Construction: STEEL
Dispenser: OTHER
Fill Type: PUMPED

Official Use: Removed Tank. 94
Permit to Operate: Not reported

Tank ID: 4 Tank Key: 2366 Not reported Installed: 0000000275 Capacity: Content: WASTE OIL Date Removed: 090694 Location: ABOVE, IN Construction: STEEL SUCTION Dispenser: Fill Type: Not reported Official Use: Removed Tank. 94 Permit to Operate: Not reported

Tank ID: 5
Tank Key: 2365
Installed: Not reported
Capacity: 0000000275
Content: #2 FUEL OIL
Date Removed: 081794
Location: ABOVE, OUT

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

VILLAGE FUEL OIL (Continued)

U003534460

Construction: STEEL Not reported Dispenser: Fill Type: Not reported Official Use: Removed Tank. 94 Permit to Operate: Not reported

> Click this hyperlink while viewing on your computer to access additional NY_AST_SUFFOLK: detail in the EDR Site Report.

BLUM DWIGHT MD E24 RCRA NonGen / NLR 1000234869 51 JOHN ST NYD986874360 ΝE **FINDS**

1/8-1/4 **BABYLON, NY** NY MANIFEST

0.224 mi.

1185 ft. Site 2 of 3 in cluster E

Relative: Date form received by agency: 01/01/2007 Higher

RCRA NonGen / NLR:

Facility name: BLUM DWIGHT MD Actual: Facility address: 51 JOHN ST

9 ft. BABYLON, NY 11702

EPA ID: NYD986874360 Mailing address:

JOHN ST

BABYLON, NY 11702 Not reported

Contact: Contact address: JOHN ST

BABYLON, NY 11702

Contact country: US

Contact telephone: Not reported Not reported Contact email:

EPA Region: 02

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: **DWIGHT BLUM MD** Owner/operator address: NOT REQUIRED

NOT REQUIRED, WY 99999

Owner/operator country: US

(212) 555-1212 Owner/operator telephone: Legal status: Private

Owner/Operator Type: Operator Owner/Op start date: Not reported Owner/Op end date: Not reported

Owner/operator name: **DWIGHT BLUM MD** Owner/operator address: NOT REQUIRED

NOT REQUIRED, WY 99999

Owner/operator country: US

Owner/operator telephone: (212) 555-1212 Legal status: Private Owner/Operator Type: Owner Owner/Op start date: Not reported Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No

Direction Distance

Elevation Site Database(s) EPA ID Number

BLUM DWIGHT MD (Continued)

1000234869

EDR ID Number

Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006

Facility name: BLUM DWIGHT MD
Classification: Not a generator, verified

Date form received by agency: 07/08/1999

Facility name: BLUM DWIGHT MD
Classification: Not a generator, verified

Date form received by agency: 08/29/1988

Facility name: BLUM DWIGHT MD
Classification: Large Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004437752

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

NY MANIFEST:

EPA ID: NYD986874360

Country: USA

Mailing Name: DWIGHT BLUM M.D. Mailing Contact: DWIGHT BLUM M.D. Mailing Address: 51 JOHN STREET Mailing Address 2: Not reported BABYLON Mailing City: Mailing State: NY Mailing Zip: 11702 Mailing Zip4: Not reported Mailing Country: **USA**

Mailing Phone: 516-422-6600

Direction Distance

Elevation Site Database(s) EPA ID Number

BLUM DWIGHT MD (Continued)

1000234869

EDR ID Number

Document ID: NYB4620573 Manifest Status: Completed copy Trans1 State ID: GE9561 Trans2 State ID: Not reported Generator Ship Date: 920527 Trans1 Recv Date: 920527 Trans2 Recv Date: Not reported TSD Site Recy Date: 920527 Part A Recv Date: Not reported Part B Recv Date: 920615 NYD986874360 Generator EPA ID:

 Generator EPA ID.
 NYD96674360

 Trans1 EPA ID:
 NYD981182769

 Trans2 EPA ID:
 Not reported

 TSDF ID:
 NYD981182769

Waste Code: D011 - SILVER 5.0 MG/L TCLP

Quantity: 00100

Units: G - Gallons (liquids only)* (8.3 pounds)

Number of Containers: 002

Container Type: DF - Fiberboard or plastic drums (glass)

Handling Method: R Material recovery of more than 75 percent of the total material.

Specific Gravity: 100 Year: 92

Document ID: NYB2029995 Manifest Status: Completed copy Trans1 State ID: 00000000 Trans2 State ID: 00000000 Generator Ship Date: 900913 Trans1 Recv Date: 900913 Trans2 Recv Date: Not reported TSD Site Recy Date: 900913 Part A Recv Date: 901003 Part B Recv Date: 900920

 Generator EPA ID:
 NYD986874360

 Trans1 EPA ID:
 NYD981182769

 Trans2 EPA ID:
 Not reported

 TSDF ID:
 NYD981182769

Waste Code: D011 - SILVER 5.0 MG/L TCLP

Quantity: 00110

Units: G - Gallons (liquids only)* (8.3 pounds)

Number of Containers: 002

Container Type: DF - Fiberboard or plastic drums (glass)

Handling Method: R Material recovery of more than 75 percent of the total material.

Specific Gravity: 100 Year: 90

Document ID: NYB2227707 Manifest Status: Completed copy GE9561 Trans1 State ID: Trans2 State ID: Not reported Generator Ship Date: 920108 Trans1 Recv Date: 920108 Trans2 Recy Date: Not reported 920108 TSD Site Recy Date: Part A Recv Date: 920121

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

BLUM DWIGHT MD (Continued)

1000234869

Part B Recv Date: 920127

NYD986874360 Generator EPA ID: NYD981182769 Trans1 EPA ID: Trans2 EPA ID: Not reported TSDF ID: NYD981182769

D011 - SILVER 5.0 MG/L TCLP Waste Code:

00055 Quantity:

Units: G - Gallons (liquids only)* (8.3 pounds)

Number of Containers: 001

Container Type: DF - Fiberboard or plastic drums (glass)

Handling Method: R Material recovery of more than 75 percent of the total material.

Specific Gravity: 100 Year: 92

Document ID: NYA8178714 Completed copy Manifest Status:

GE9561 Trans1 State ID: Trans2 State ID: Not reported 891030 Generator Ship Date: Trans1 Recv Date: 891030 Trans2 Recv Date: Not reported TSD Site Recy Date: 891030 Part A Recv Date: 891102 Part B Recv Date: 891114

Generator EPA ID: NYD986874360 Trans1 EPA ID: NYD981182769 Trans2 EPA ID: Not reported TSDF ID: NYD981182769

Waste Code: D011 - SILVER 5.0 MG/L TCLP

Quantity: 00110

Units: G - Gallons (liquids only)* (8.3 pounds)

Number of Containers:

Container Type: DF - Fiberboard or plastic drums (glass)

R Material recovery of more than 75 percent of the total material. Handling Method:

Specific Gravity: 100 89 Year:

Document ID: NYB2878812 Manifest Status: Completed copy

Trans1 State ID: GE9561 Trans2 State ID: Not reported Generator Ship Date: 910805 Trans1 Recv Date: 910805 Trans2 Recv Date: Not reported TSD Site Recv Date: 910805 Part A Recv Date: 910814 Part B Recv Date: 910822

Generator EPA ID: NYD986874360 Trans1 EPA ID: NYD981182769 Trans2 EPA ID: Not reported TSDF ID: NYD981182769

Waste Code: D011 - SILVER 5.0 MG/L TCLP

Quantity: 00090

G - Gallons (liquids only)* (8.3 pounds) Units:

Number of Containers: 002

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

BLUM DWIGHT MD (Continued)

1000234869

Container Type: DF - Fiberboard or plastic drums (glass)

R Material recovery of more than 75 percent of the total material. Handling Method:

Specific Gravity: 100 Year: 91

Document ID: NYB2042073

Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC

Trans1 State ID: GE9561 Trans2 State ID: Not reported Generator Ship Date: 901210 Trans1 Recv Date: 901210 Trans2 Recv Date: Not reported TSD Site Recv Date: 901210 Part A Recv Date: 910111 Part B Recv Date: 910115 NYD986874360 Generator EPA ID: Trans1 EPA ID:

NYD981182769 Trans2 EPA ID: Not reported TSDF ID: NYD981182769

Waste Code: D011 - SILVER 5.0 MG/L TCLP

Quantity: 00055

Units: G - Gallons (liquids only)* (8.3 pounds) Number of Containers: Container Type: DF - Fiberboard or plastic drums (glass)

Handling Method: R Material recovery of more than 75 percent of the total material.

Specific Gravity: 100 Year: 90

Document ID: NYA7127964

Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC

Trans1 State ID: 00000000 Trans2 State ID: 00000000 881212 Generator Ship Date: Trans1 Recv Date: 881212 Trans2 Recv Date: Not reported TSD Site Recv Date: 881212 Part A Recv Date: 890130 Part B Recv Date: 881220

Generator EPA ID: NYD986874360 Trans1 EPA ID: NYD981182769 Trans2 EPA ID: Not reported TSDF ID: NYD981182769

Waste Code: D011 - SILVER 5.0 MG/L TCLP

Quantity: 00055

Units: G - Gallons (liquids only)* (8.3 pounds)

Number of Containers: 001

Container Type: DF - Fiberboard or plastic drums (glass) T Chemical, physical, or biological treatment. Handling Method:

Specific Gravity: 100 Year: 88

Document ID: NYA7054344 Completed copy Manifest Status: Trans1 State ID: 00000000

Direction Distance

Elevation Site Database(s) EPA ID Number

BLUM DWIGHT MD (Continued)

1000234869

EDR ID Number

 Trans2 State ID:
 000000000

 Generator Ship Date:
 890317

 Trans1 Recv Date:
 890317

 Trans2 Recv Date:
 Not reported

 TSD Site Recv Date:
 890317

 Part A Recv Date:
 890322

 Part B Recv Date:
 890328

 Generator EPA ID:
 NYD986874360

 Trans1 EPA ID:
 NYD981182769

 Trans2 EPA ID:
 Not reported

 TSDF ID:
 NYD981182769

Waste Code: D011 - SILVER 5.0 MG/L TCLP

Quantity: 00055

Units: G - Gallons (liquids only)* (8.3 pounds)

Number of Containers: 001

Container Type: DM - Metal drums, barrels

Handling Method: T Chemical, physical, or biological treatment.

Specific Gravity: 100 Year: 89

Document ID: NYB2118006

Manifest Status: Completed after the designated time period for a TSDF to get a copy to the DEC

Trans1 State ID: 00000000 Trans2 State ID: 00000000 Generator Ship Date: 900226 Trans1 Recy Date: 900226 Trans2 Recv Date: Not reported TSD Site Recv Date: 900226 Part A Recv Date: 900424 Part B Recv Date: 900312

 Generator EPA ID:
 NYD986874360

 Trans1 EPA ID:
 NYD981182769

 Trans2 EPA ID:
 Not reported

 TSDF ID:
 NYD981182769

Waste Code: D011 - SILVER 5.0 MG/L TCLP

Quantity: 00055

Units: G - Gallons (liquids only)* (8.3 pounds)

Number of Containers: 001

Container Type: DF - Fiberboard or plastic drums (glass)

Handling Method: R Material recovery of more than 75 percent of the total material.

Specific Gravity: 100 Year: 90

Document ID: NYB2287098 Manifest Status: Completed copy Trans1 State ID: GE9561 Trans2 State ID: Not reported Generator Ship Date: 910315 910315 Trans1 Recv Date: Trans2 Recv Date: Not reported TSD Site Recv Date: 910315 Part A Recv Date: 910322 Part B Recv Date: 910329

Generator EPA ID: NYD986874360
Trans1 EPA ID: NYD981182769

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

BLUM DWIGHT MD (Continued)

1000234869

Trans2 EPA ID: Not reported TSDF ID: NYD981182769

D011 - SILVER 5.0 MG/L TCLP Waste Code:

Quantity: 00055

Units: G - Gallons (liquids only)* (8.3 pounds)

Number of Containers:

Container Type: DF - Fiberboard or plastic drums (glass)

Handling Method: R Material recovery of more than 75 percent of the total material.

Specific Gravity: 100 Year: 91

25 **LILCO - BABYLON SUBSTATION** RCRA NonGen / NLR 1000174778

FINDS NYD986889749

NNE **CEDAR ST** 1/8-1/4 **BABYLON, NY**

0.226 mi. 1193 ft.

RCRA NonGen / NLR: Relative:

Higher Date form received by agency: 01/01/2007

LILCO - BABYLON SUBSTATION Facility name:

Actual: Facility address: CEDAR ST 13 ft.

BABYLON, NY 11702

EPA ID: NYD986889749 WALT WHITMAN RD Mailing address:

MELVILLE, NY 11747

Contact: Not reported

Contact address: WALT WHITMAN RD

MELVILLE, NY 11747

Contact country: US

Contact telephone: Not reported Contact email: Not reported

EPA Region: 02

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

LONG ISLAND LIGHTING CO Owner/operator name:

Owner/operator address: **NOT REQUIRED**

NOT REQUIRED, WY 99999

Owner/operator country: US

Owner/operator telephone: (212) 555-1212 Legal status: Private Owner/Operator Type: Owner Owner/Op start date: Not reported Owner/Op end date: Not reported

Owner/operator name: LONG ISLAND LIGHTING CO

Owner/operator address: NOT REQUIRED

NOT REQUIRED, WY 99999

Owner/operator country:

(212) 555-1212 Owner/operator telephone: Legal status: Private Owner/Operator Type: Operator Owner/Op start date: Not reported Owner/Op end date: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

LILCO - BABYLON SUBSTATION (Continued)

1000174778

EDR ID Number

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: Nο Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006

Facility name: LILCO - BABYLON SUBSTATION

Classification: Not a generator, verified

Date form received by agency: 07/08/1999

Facility name: LILCO - BABYLON SUBSTATION

Classification: Not a generator, verified

Date form received by agency: 01/31/1990

Facility name: LILCO - BABYLON SUBSTATION Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110008037418

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

corrective action activities required under RCRA.

26 GARVEY ASSOCIATES NY UST U003535507

South 116 RTE 27 A MONTAUK HWY MAIN

1/8-1/4 BABYLON, NY 11702

0.228 mi. 1204 ft.

Relative: SUFFOLK CO. UST:

Lower Facility ID: 814
Facility Reference #: 14270

Actual: Official Use: Abandoned, approved by plan review, awaiting construction for compliance inspection. 98

6 ft. Township: BABYLON

Tax Map No: 0102 014.00 001 004.000

N/A

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

GARVEY ASSOCIATES (Continued)

U003535507

Region: SUFFOLK

Tank Count: 2

Permit to Operate: Not reported

Owner Name: GARVEY ASSOCIATES

Owner Address: P O BOX 788

Owner City,St,Zip: BABYLON, NY 11702

Tank ID: Tank Key: 2452 Installed: Not reported 0000001000 Capacity: Content: #2 FUEL OIL Date Removed: 012198 Location: UNDER, OUT Construction: STEEL SUCTION Dispenser: Fill Type: **GRAVITY**

Tank ID: 2
Tank Key: 2453
Installed: Not reported

 Capacity:
 0000001000

 Content:
 #2 FUEL OIL

 Date Removed:
 012198

 Location:
 UNDER, OUT

 Construction:
 STEEL

 Dispenser:
 SUCTION

 Fill Type:
 PUMPED

E27 RELIANCE FUEL DEPOT NY LTANKS

NE UNION BOULEVARD & RTE 231 1/8-1/4 WEST ISLIP, NY

0.228 mi.

1206 ft. Site 3 of 3 in cluster E

Relative: LTANKS:

Higher Site ID: 83999

Spill Number/Closed Date: 9609844 / 1/21/1997

Actual: Spill Date: 11/6/1996

9 ft. Spill Cause: Tank Test Failure

Spill Source: Major Facility > 400,000 gal

Spill Class: Known release that creates potential for fire or hazard. DEC Response.

Willing Responsible Party. Corrective action taken.

Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 5200
Investigator: T/T/F
Referred To: Not reported
Reported to Dept: 11/6/1996
CID: 266

Water Affected: Not reported
Spill Notifier: Tank Tester
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0

Date Entered In Computer: 11/6/1996

S102447935

N/A

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

RELIANCE FUEL DEPOT (Continued)

S102447935

Spill Record Last Update: 1/22/1997 Spiller Name: RICHARD ROSE Spiller Company: RELIANCE FUEL OIL Spiller Address: 77 SOUTH STREET Spiller City, St, Zip: PATCHOGUE, NY 11772-

Spiller County: 001

Spiller Contact: Not reported Spiller Phone: Not reported Spiller Extention: Not reported

DEC Region: DER Facility ID: 77275 DEC Memo: Not reported

FAILED ULLAGE PORTION OF TEST. ENTIRE SITE BEING REMEDIATED IN Remarks:

> PREPARATION FOR SALE. TANK HASN'T BEEN USED SINCE THE 80'S. TEST PERFORMED ON BEHALF OF EMCON, RICH CALOGERO, (201) 512-5700.

Material:

Site ID: 83999 Operable Unit ID: 1037784 Operable Unit: 01 Material ID: 342056 Material Code: 0001A Material Name: #2 Fuel Oil Case No.: Not reported Material FA: Petroleum Quantity: Gallons Units: Recovered: No

Resource Affected: Not reported Oxygenate: False

Tank Test:

Site ID: 83999 Spill Tank Test: 1544867 Tank Number: Not reported Tank Size: 1000 Test Method: 09 Leak Rate: 0 Gross Fail: F Modified By: Spills Last Modified: 10/1/2004

Test Method: VPLT (NDE) plus UTS-4T/U3 Ullage

NY LTANKS S105054259 28 UNK

MAIN & COOPER South

1/8-1/4 **BABYLON, NY**

0.233 mi. 1231 ft.

LTANKS: Relative:

230975 Site ID: Lower

Spill Number/Closed Date: 8701780 / 2/25/1998

Actual: Spill Date: 5/27/1987 5 ft. Spill Cause: Tank Failure

Spill Source: **Gasoline Station**

Known release that creates potential for fire or hazard. DEC Response. Spill Class:

N/A

Direction Distance

Elevation Site Database(s) EPA ID Number

UNK (Continued) \$105054259

Willing Responsible Party. Corrective action taken.

Cleanup Ceased: Not reported

Cleanup Meets Standard: True SWIS: 5220 Investigator: MIRZA Referred To: Not reported 5/27/1987 Reported to Dept: CID: Not reported Water Affected: Not reported Spill Notifier: DEC Last Inspection: Not reported Recommended Penalty: False **UST Involvement:** True Remediation Phase:

Date Entered In Computer: 6/8/1987 Spill Record Last Update: 2/26/1998 Spiller Name: Not reported

Spiller Company: UNK

Spiller Address: Not reported
Spiller City,St,Zip: ***UPDATE***, ZZ

Spiller County: 999

Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 1

DER Facility ID: 190343

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was

"MIRZA WELL" //: COULD NOT EXCAVATE-REQUEST SITE WELLS.

Remarks: 4-2K STEEL TANKS FOUND ON OLD PROPERTY/OLD GAS SMELL IN LIQUID

FLOATING ON GW

Material:

230975 Site ID: Operable Unit ID: 906232 Operable Unit: 01 Material ID: 471681 Material Code: 0009 Material Name: Gasoline Case No.: Not reported Material FA: Petroleum Quantity:

Quantity: 0
Units: Gallons
Recovered: No

Resource Affected: Not reported Oxygenate: False

Oxygenate. Talso

Tank Test:

EDR ID Number

Direction Distance

Elevation Site Database(s) **EPA ID Number**

F29 **EDR US Hist Auto Stat** 1015249553

N/A

EDR ID Number

1/8-1/4 BABYLON, NY 11702

158 E MAIN ST

0.236 mi.

South

1248 ft. Site 1 of 2 in cluster F

EDR Historical Auto Stations: Relative:

MONTROSE AUTOMOTIVE REBUILDERS INCORPORATED Higher Name:

Year: 1999

Actual: Address: 158 E MAIN ST

8 ft.

Name: MONTROSE AUTOMOTIVE REBUILDERS INCORPORATED

2000 Year:

158 E MAIN ST Address:

Name: MONTROSE AUTOMOTIVE REBUILDERS

Year:

Address: 158 E MAIN ST

Name: MONTROSE AUTOMOTIVE REBUILDERS INC

Year: 2002

158 E MAIN ST Address:

Name: MONTROSE AUTOMOTIVE REBUILDERS

Year:

Address: 158 E MAIN ST

Name: MONTROSE AUTOMOTIVE REBUILDERS INC

Year: 2007 Address: 158 E MAIN ST

MONTROSE AUTOMOTIVE REBUILDERS INC Name:

Year: 2008

Address: 158 E MAIN ST

Name: MONTROSE AUTOMOTIVE REBUILDERS

2009 Year:

158 E MAIN ST Address:

F30 **NY LTANKS** S102140765 **BAYVIEW REST HOME NY Spills** South **143 EAST MAIN STREET** N/A

1/8-1/4 **BABYLON, NY**

0.237 mi.

1249 ft. Site 2 of 2 in cluster F

LTANKS: Relative:

Site ID: 82838 Higher

Spill Number/Closed Date: 9614539 / 7/12/2000 Actual:

Spill Date: 3/17/1997 8 ft. Spill Cause: Tank Failure

Spill Source: Institutional, Educational, Gov., Other

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.

Willing Responsible Party. Corrective action taken.

Cleanup Ceased: Not reported Cleanup Meets Standard: True SWIS: 5220 Investigator: **GIBBONS** Not reported Referred To:

3/17/1997 Reported to Dept: CID: 369

Direction Distance

Elevation Site Database(s) EPA ID Number

BAYVIEW REST HOME (Continued)

S102140765

EDR ID Number

Water Affected: Not reported
Spill Notifier: Local Agency
Last Inspection: Not reported
Recommended Penalty: False
UST Involvement: False
Remediation Phase: 0
Date Entered In Computer: 3/17/1997
Spill Record Last Update: 7/13/2000
Spiller Name: Not reported

Spiller Company: BAYVIEW ADULT HOME Spiller Address: 143 EAST MAIN STREET

Spiller City, St, Zip: BABYLON, NY

Spiller County: 001 Spiller Contact: IRA

Spiller Phone: (516) 661-3292
Spiller Extention: Not reported
DEC Region: 1

DER Facility ID: 76310
DEC Memo: Not reported

Remarks: tank with lots of holes-has been removed from ground

Material:

Site ID: 82838 Operable Unit ID: 1045912 Operable Unit: 01 Material ID: 339646 Material Code: 0001A Material Name: #2 Fuel Oil Case No.: Not reported Petroleum Material FA: Quantity: 0 Units: Gallons Recovered: No

Resource Affected: Not reported Oxygenate: False

Tank Test:

SPILLS:

 Facility ID:
 9507126

 DER Facility ID:
 76310

 Facility Type:
 ER

 Site ID:
 82836

 DEC Region:
 1

Spill Date: 9/11/1995

Spill Number/Closed Date: 9507126 / 8/7/1996 Spill Cause: Equipment Failure

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.

Willing Responsible Party. Corrective action taken.

SWIS: 5220
Investigator: BPAUSTIN
Referred To: Not reported
Reported to Dept: 9/12/1995
CID: Not reported
Water Affected: Not reported

Direction Distance

Elevation Site Database(s) EPA ID Number

BAYVIEW REST HOME (Continued)

S102140765

EDR ID Number

Spill Source: Institutional, Educational, Gov., Other

Spill Notifier:
Cleanup Ceased:
Cleanup Meets Std:
Last Inspection:
Recommended Penalty:
UST Trust:
Remediation Phase:
Date Entered In Computer:
Other
Not reported
False
False
False
9/13/1995

Date Entered In Computer: 9/13/1995
Spill Record Last Update: 8/7/1996
Spiller Name: Not reported

Spiller Company: BAYVIEW REST HOME Spiller Address: 143 EAST MAIN STREET

Spiller City, St, Zip: BABYLON, ZZ

Spiller Company: 001

Contact Name: Not reported Contact Phone: Not reported

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was

"AUSTIN"NO FLOOR DRAINS AFFECTED. ON CONCRETE FLOOR, COMPLETELY

CLEANED UP

Remarks: FAULTY FILTER CAUSED SPILL

Material:

Site ID: 82836 Operable Unit ID: 1021953 Operable Unit: 01 Material ID: 361552 Material Code: 0001A Material Name: #2 Fuel Oil Case No.: Not reported Petroleum Material FA: Quantity: 5 Units: Gallons Recovered: No

Resource Affected: Not reported Oxygenate: False

Tank Test:

 Facility ID:
 0102332

 DER Facility ID:
 76310

 Facility Type:
 ER

 Site ID:
 82833

 DEC Region:
 1

 Spill Date:
 6/1/2001

Spill Number/Closed Date: 0102332 / 3/27/2002

Spill Cause: Unknown

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.

Willing Responsible Party. Corrective action taken.

SWIS: 5220

Investigator: UNASSIGNED
Referred To: Not reported
Reported to Dept: 6/1/2001
CID: 323
Water Affected: Net reported

Water Affected: Not reported
Spill Source: Commercial Vehicle

Direction Distance

Elevation Site Database(s) **EPA ID Number**

BAYVIEW REST HOME (Continued)

S102140765

EDR ID Number

Spill Notifier: Responsible Party Cleanup Ceased: Not reported Cleanup Meets Std: True Last Inspection: Not reported Recommended Penalty: False **UST Trust:** False Remediation Phase: 0 Date Entered In Computer: 6/1/2001 Spill Record Last Update: 10/14/2009 Spiller Name: **CALLER**

Spiller Address: 5560 58TH STREET Spiller City, St, Zip: MASPETH, NY -

Spiller Company:

Spiller Company:

JESSICA RUSS Contact Name: Contact Phone: (516) 349-4116

DEC Memo: 12:35 TELECON PETRO OIL DEPT, A REP IS ENROUTE TO ASSESS. WILL CALL

> WITH UPDATE12:45 TELECON CALLER, SLIGHT OVERFILL, ESTIMATES ONE CUP SPRAYED ON BLDG, DRIVER REMOVED TWO SHOVEL OF SOIL, BLDG TO BE CLEANED

Not reported

PETRO

driver was filling second fill and oil came out of the first fill. Remarks:

Material:

Site ID: 82833 Operable Unit ID: 841104 Operable Unit: 01 Material ID: 534447 Material Code: 0001A Material Name: #2 Fuel Oil Case No.: Not reported Petroleum Material FA: Quantity: Units: Gallons Recovered: Yes

Not reported Resource Affected: Oxygenate: False

Tank Test:

Facility ID: 9802521 DER Facility ID: 76310 Facility Type: ER 82839 Site ID: DEC Region: Spill Date: 5/27/1998

Spill Number/Closed Date: 9802521 / 6/5/1998

Spill Cause: Other

Spill Class: Known release that creates potential for fire or hazard. DEC Response.

Willing Responsible Party. Corrective action taken.

SWIS: 5220 Investigator: **MJDARCAN** Not reported Referred To: 5/27/1998 Reported to Dept: CID: 365

Water Affected: Not reported Spill Source: Private Dwelling

Direction Distance

Elevation Site Database(s) EPA ID Number

BAYVIEW REST HOME (Continued)

S102140765

EDR ID Number

Spill Notifier: Other Cleanup Ceased: Not reported Cleanup Meets Std: True Last Inspection: Not reported Recommended Penalty: False **UST Trust:** False Remediation Phase: 0 Date Entered In Computer: 5/27/1998

Spill Record Last Update: 10/5/2012
Spiller Name: BAY VIEW R

Spiller Name: BAY VIEW REST HOME
Spiller Company: BAYVIEW REST HOME
Spiller Address: 143 EAST MAIN STREET

Spiller City,St,Zip: BABYLON, NY

Spiller Company: 001

Contact Name: BAY VIEW REST HOME

Contact Phone: (661) 661-3292

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was

"DARCANGELO"TELECON WITH GREG COLLINS (ANS) INSTALLING 2-275 GAL BASEMENT TANKS. TESTED EXISTING LINES FROM 1K UST OUTSIDE BASEMENT WALL. LINES FAILED TEST. EXPOSED LINES FOUND CONTAMINATED SOIL, SATURATED, PRODUCT IN TRENCH, DID NOT CONTINUE TO GW. NO OFFICIALS FROM REST HOME ON SITE. EXCAVATION IS 2' DEEP AND SECURE IN BASEMENT. PREVIOUS PROBLEM WITH 1K TANK REMOVED 4 MONTHS AGO BELIEVES SOME

CONTAMINATION WAS STILL IN GROUNDNO CLEANUP REQUIRED.

CALLER FOUND A LINE FAILURE

Material:

Remarks:

82839 Site ID: Operable Unit ID: 1060509 Operable Unit: 01 Material ID: 320845 Material Code: 0001A Material Name: #2 Fuel Oil Case No.: Not reported Petroleum Material FA: Quantity: Units: Gallons Recovered: No Not reported Resource Affected: Oxygenate: False

Tank Test:

 Facility ID:
 8911699

 DER Facility ID:
 76310

 Facility Type:
 ER

 Site ID:
 82835

 DEC Region:
 1

 Spill Date:
 3/12/1990

Spill Number/Closed Date: 8911699 / 3/22/1991

Spill Cause: Other
Spill Class: Not reported
SWIS: 5220
Investigator: JEHAAS
Referred To: Not reported
Reported to Dept: 3/12/1990

Direction Distance

Elevation Site Database(s) EPA ID Number

BAYVIEW REST HOME (Continued)

S102140765

EDR ID Number

CID: Not reported Water Affected: Not reported

Spill Source: Institutional, Educational, Gov., Other

Spill Notifier: Responsible Party Cleanup Ceased: 3/22/1991 Cleanup Meets Std: True Last Inspection: Not reported Recommended Penalty: False **UST Trust:** False Remediation Phase: 3/14/1990 Date Entered In Computer: Spill Record Last Update: 7/1/1997

Spiller Name: Not reported
Spiller Company: BAYVIEW REST HOME

Spiller Address: Not reported

Spiller City,St,Zip: ZZ Spiller Company: 001

Contact Name: Not reported Contact Phone: Not reported

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was

"HAAS WELL"03/22/91: DISSOLVED DATA INDICATES NO PETROLEUM

CONTAMINATION.NO FURTHER ACTION REQUIRED.

Remarks: TANK REMOVAL. U/G F/O TANK REMOVED TODAY BY RELIANCE, SOIL

CONTAMINATION ENCOUNTERED

Material:

Site ID: 82835 Operable Unit ID: 938521 Operable Unit: 01 Material ID: 441207 0001A Material Code: Material Name: #2 Fuel Oil Case No.: Not reported Material FA: Petroleum Quantity: 0 Gallons Units: Recovered: No Not reported Resource Affected:

Resource Affected: Not reported Oxygenate: False

Tank Test:

 Facility ID:
 9611754

 DER Facility ID:
 76310

 Facility Type:
 ER

 Site ID:
 82837

 DEC Region:
 1

 Spill Date:
 12/27/1996

Spill Number/Closed Date: 9611754 / 12/30/1996

Spill Cause: Human Error

Spill Class: Possible release with minimal potential for fire or hazard or Known

release with no damage. DEC Response. Willing Responsible Party.

Corrective action taken.

SWIS: 5220

Investigator: UNASSIGNED Referred To: UNASSIGNED

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

BAYVIEW REST HOME (Continued)

S102140765

Reported to Dept: 12/27/1996 CID: 311 Water Affected: Not reported Spill Source: Tank Truck Spill Notifier: Affected Persons Cleanup Ceased: Not reported Cleanup Meets Std: True Last Inspection: Not reported

Recommended Penalty: False **UST Trust:** False Remediation Phase: 0

Date Entered In Computer: 12/27/1996 Spill Record Last Update: 6/8/1998 Spiller Name: UNK

Spiller Company: **BAYVIEW REST HOME** Spiller Address: 143 EAST MAIN STREET

Spiller City, St, Zip: BABYLON, NY

Spiller Company: 001

Contact Name: **BAYVIEW REST HOME**

(516) 661-3292 Contact Phone: DEC Memo: Not reported

CALLER STATES REST HOME REQUESTED 200 GALLONS AND AFTER ABOUT Remarks:

90GALLONS, PRODUCT CAME OUT OF VENT.

Material:

Site ID: 82837 1043050 Operable Unit ID: Operable Unit: 01 Material ID: 340408 Material Code: 0001A Material Name: #2 Fuel Oil Case No.: Not reported Material FA: Petroleum Quantity: Gallons Units: Recovered: Yes Resource Affected: Not reported

Oxygenate:

False

Tank Test:

Click this hyperlink while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

SIASOCO RESIDENCE NY LTANKS 31 S107489224 SW **78 A DEER PARK AVENUE** N/A

1/8-1/4 **BABYLON, NY**

0.242 mi. 1279 ft.

LTANKS: Relative:

356020 Site ID: Higher

Spill Number/Closed Date: 0510111 / 6/27/2007

Actual: Spill Date: 11/25/2005 10 ft. Spill Cause: Tank Failure Spill Source: Private Dwelling

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.

Direction Distance

Elevation Site Database(s) EPA ID Number

SIASOCO RESIDENCE (Continued)

S107489224

EDR ID Number

Willing Responsible Party. Corrective action taken.

Cleanup Ceased: Not reported
Cleanup Meets Standard: False
SWIS: 5220
Investigator: WXPRZYLO
Referred To: Not reported
Reported to Dept: 11/25/2005
CID: 444

Water Affected: Not reported
Spill Notifier: Fire Department
Last Inspection: Not reported
Recommended Penalty: False

UST Involvement: False Remediation Phase: 6

Date Entered In Computer: 11/25/2005
Spill Record Last Update: 6/29/2007
Spiller Name: MR SIASOCO
Spiller Company: UNKNOWN
Spiller Address: Not reported

Spiller City,St,Zip: NY Spiller County: 001

Spiller Contact:
Spiller Phone:
Spiller Extention:
DEC Region:

BABYLON FIRE
(631) 226-1216
Not reported
1

DER Facility ID: 306082

DEC Memo: 11/25 12:00 CALLED DISPATCHER, OBTAINED CHIEF'S NUMBER11/25 12:00

CALLED ASST CHIEF CARDALI, A/G 275 GAL TANK RUSTED, LAST DELIVERY WAS SUPPOSEDLY 43 GAL IN OCTOBER, GAUGE SHOWS ~7/8 FULL, FD PLUGGED LEAK, SPILLAGE ON GROUND, SOME SOAKED INTO GROUND, SOME ABSORBED WITH SPEEDI DRI, LANDLORD(MR SIASOCO) ENROUTE, PERILLO BROTHERS, OIL CO ENROUTE 516-678-3400, REQUESTED HE HAVE LANDLORD CALL DEC12:10 TRIED LANDLORDS PHONE, BUSY SIGNAL12:15 CALLED SIASOCO, HE IS ENROUTE, ASKED WIFE TO HAVE HIM CALL DEC, 14:35 CALLED SIASOCO, WIFE GAVE HUSBANDS CEALL14:35 CALLED CELL, LEFT MESSAGE15:40 MR SIASOCO CALLED,

TANK STILL HAD OVER 200 GALS, DOUBTS 40 GAL SPILLED, OIL CO

TRANSFERRED TO TEMP TANK, DISCUSSED CLEANUP16:20 FAXED LETTER,

INSTRUCTIONS, CONTRACTOR NAMESAPPROX 750 LBS OF CONTAMINATED SOIL HAS BEEN REMOVED, GW MONITORING FOR FREE PRODUCT PROVIDED FOR ONE YEAR

PERIOD. APPROX 500 GALS OF OIL CONTAMINATED WATER PUMPED. NO RECURRENCE OF PRODUCT OBSERVED, NO FURTHER ACTION REQUIRED (VP)

Remarks: LEAKING TANK AT THE ADDRESS ABOVE: FIRE DEPT ON SCENE:

Material:

Site ID: 356020 Operable Unit ID: 1113346 Operable Unit: 01 2103407 Material ID: Material Code: 0001A Material Name: #2 Fuel Oil Not reported Case No.: Material FA: Petroleum Quantity: 40 Units: Gallons Recovered: No

Resource Affected: Not reported Oxygenate: False

Direction Distance

Elevation Site Database(s) **EPA ID Number**

SIASOCO RESIDENCE (Continued)

S107489224

EDR ID Number

Tank Test:

32 **EDR US Hist Cleaners** 1014971080

SSW 105 E MAIN ST N/A

1/8-1/4 BABYLON, NY 11702

0.246 mi. 1298 ft.

EDR Historical Cleaners: Relative:

Name: OAK NECK CLEANERS Higher

Year:

Actual: Address: 105 E MAIN ST

8 ft.

OAK NECK CLEANERS Name:

Year: 2011

Address: 105 E MAIN ST

OAK NECK CLEANERS Name:

Year: 2012

Address: 105 E MAIN ST

G33 **EUGENE FRENCH CLEANERS** NY SHWS S108146489 N/A

SSW **54 EAST MAIN STREET** NY HSWDS 1/4-1/2 BABYLON, NY NY MANIFEST **NY Spills**

0.283 mi.

1493 ft. Site 1 of 2 in cluster G

SHWS: Relative:

Program: HW Higher Site Code: 58035

Actual: SITE IS PROPERLY CLOSED - REQUIRES CONTINUED MANAGEMENT Classification:

9 ft. Region:

Acres: 1.000 HW Code: 152157 Record Add: 11/18/1999 Record Upd: 04/11/2012 Updated By: **JBSWARTO**

1

Site Description: Eugene's Dry Cleaners is located in an urban portion of Suffolk

County, NY. The site is located at 54 East Main Street in Babylon. The main site feature is a large masonry building with a basement located along Main Street. The former dry cleaner occupied the one-story structure on the eastern side of the building from 1989 to 1999 and is currently occupied by a nail salon. The adjoining three-story structure is used for commercial businesses on the first floor and apartments on the upper levels. A garage and an asphalt covered parking area are located behind the structure. The site is zoned for commercial use and the properties in the vicinity of the site are zoned for commercial or community services. The nearest

residential area is approximately 380 feet to the south.

Contamination at the site is attributable to the former dry cleaner operations. In June 1994, initial investigations were conducted with a focused Remedial Investigation performed in July 1998. In October 1998, an Interim Remedial Measure (IRM) consisting of power washing the basement and removing three cubic yards of soil and water from the sump. On December 1, 2000, a "no further action" Record Map ID
Direction
Distance

Elevation

MAP FINDINGS

Site EDR ID Number

Database(s) EPA ID Number

EUGENE FRENCH CLEANERS (Continued)

S108146489

of Decision (ROD) was issued for the site. Long term monitoring indicated a continuing decline in contaminant concentrations in groundwater. Soil vapor investigations were conducted in April 2006 and December 2007, which lead to the installation of sub-slab depressurization systems at an adjacent property in June 2009 and at the site in September 2010. Site geology primarily consists of two feet of silty sand grading to medium to coarse sand and gravel. Groundwater ranges between 6 and 9 feet below ground surface and flows to the south-southwest.

Env Problem:

Based upon investigations conducted to date, the primary contaminant of concern is tetrachloroethene (PCE) within the soil, groundwater and soil vapor in the vicinity of the basement sump, which is located towards the southeastern portion of the site. Sporadic detections of PCE breakdown products have been detected. Soil: In December 2007, PCE soil concentrations exceeded unrestricted soil cleanup objectives, 1.3 parts per million (ppm), with a maximum concentration of 2.4 ppm at a depth of 3 feet below ground surface within the alley. Groundwater: In September 2011, PCE groundwater concentrations exceed groundwater standards, 5 parts per billion (ppb), with a maximum concentration of 29 ppb approximately 100 feet south of the impacted sump. PCE was detected slightly above groundwater standards approximately 250 feet south of the sump. Soil Vapor: In December 2007, sub-slab soil vapor samples detected up to 6,500 micrograms per cubic meter (ug/m3) beneath the on-site building. In December 2007, soil vapor samples detected PCE up to 48,000 ug/m3 in the alley. In March 2009, PCE was detected up to 3,400 ug/m3 beneath an adjacent

Health Problem:

No one will come into contact with contaminated sediments as they were removed from the on-site sump. People are not drinking the contaminated groundwater because the area is served by public water supply that is not affected by this contamination. Also, they are not coming into contact with the groundwater unless they dig below the ground surface. Volatile organic compounds in the groundwater or soil may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. Soil vapor intrusion sampling indicated impacts to indoor air quality. It is limited to the on-site building and one off-site building and sub-slab depressurization systems (a system that ventilates/removes vapors from beneath the building) were installed in both buildings and are operating effectively to prevent migration of contaminants via soil vapor intrusion.

Dump: False
Structure: True
Lagoon: False
Landfill: False
Pond: False
Disp Start: unknown
Disp Term: 1994

Lat/Long: 40:41:47:0 / 73:19:21:0

Dell: False

Record Add: 11/18/1999 12:00:00 PM Record Upd: 1/20/2011 11:15:00 AM

Updated By: BFJANKAU

Own Op: Document Repository

Sub Type: NNN

Direction Distance Elevation

evation Site Database(s) EPA ID Number

EUGENE FRENCH CLEANERS (Continued)

Owner Name: Not reported

Owner Company: BABYLON PUBLIC LIBRARY
Owner Address: 24 SOUTH CARLL AVE

Owner Addr2: Not reported

Owner City,St,Zip: BABYLON, NY 11702
Owner Country: United States of America
Own Op: On-Site Operator

Sub Type: NNN

Owner Name: Mr. Hai Chung Lee

Owner Company: Yuni Nails

Owner Address: 54 East Main Street
Owner Addr2: Not reported
Owner City,St,Zip: Babylon, NY 11702
Owner Country: United States of America

Own Op: Owner Sub Type: NNN

Owner Name: MR. JUDGE MANNING

Owner Company: EXECUTOR OF SAM CANTOR'S ESTATE

Owner Address: 18 MECHANIC STREET

Owner Addr2: Not reported
Owner City,St,Zip: AMENIA, NY 12501
Owner Country: United States of America

HW Code: 152157
Waste Type: ACETONE
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152157

Waste Type: TETRACHLOROETHYLENE (PCE)

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152157

Waste Type: TETRACHLOROETHYLENE (PCE)

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152157

Waste Type: TETRACHLOROETHYLENE (F002 WASTE)

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152157

Waste Type: TRICHLOROETHENE (TCE)

Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152157

Waste Type: XYLENE (MIXED)
Waste Quantity: UNKNOWN
Waste Code: Not reported
HW Code: 152157

Waste Type: DICHLOROETHYLENE

Waste Quantity: UNKNOWN
Waste Code: Not reported
Crossref ID: Not reported
Cross Ref Type Code: Not reported
Cross Ref Type: Not reported
Record Added Date: Not reported
Record Updated: Not reported
Updated By: UNKNOWN
Not reported
Not reported
Not reported

S108146489

EDR ID Number

Distance Elevation

EDR ID Number
tion Site Database(s) EPA ID Number

EUGENE FRENCH CLEANERS (Continued)

S108146489

HSWDS:

Facility ID: Not reported

Region: 1
Facility Status: None
Owner Type: Puplic

Owner: M. O'Shea Trust
Owner Address: 55 Crescent Ave
Owner Phone: Unknown
Operator Type: Puplic

Operator: Donald Gottwald
Operator: Donald Gottwald
Operator Phone: (516)661-2604

EPA ID: N

Registry: Not on NYS Registry of Inactive Haz Waste Disposal Sites

Registry Site ID: None RCRA Permitted: No Site Code: Spill

Owner City State: Babylon, NY 11702 Operator City State: Babylon, NY 11702

Quadrange: Unknown Latitude: Unknown Longitude: Unknown Acres: 1.00 Operator Date: Unknown Close Date: Unknown Completed: 5-sampl Active: Yes PCB's Disposed: No Pesticides Disposed: No Metals Disposed: No Asbestos Disposed: No

Volatile Organic Compounds Disposed: Yes Semi Volatile Organic Compounds Disposed: No

Analytical Info Exists for Air: Not reported Analytical Info Exists for Ground: Groundwater Analytical Info Exists for Surface: Not reported Analytical Info Exists for Sediments: Sediment Analytical Info Exists for Surface: Surface Soil Analytical Info Exists for Substance: Not reported Not reported Analytical Info Exists for Waste: Not reported Analytical Info Exists for Leachate: Analytical Info Exists for EP Toxicity: Not reported Analytical Info Exists for TCLP: Not reported

Threat to Environment/Public Health: Environmental/Public

Surface Water Contamination: Unknown Surface Water Body Class: Unknown Groundwater Contamination: Yes Groundwater Classification: SoleSource **Drinking Water Contamination:** Unknown Drinking Water Supply is Active: Unknown Any Known Fish or Wildlife: No Hazardous Exposure: Unknown Site Has Controlled Acess: No Ambient Air Contamination: Unknown Direct Contact: No EPA Hazardous Ranking System Score: Unknown

Inventory:

Direction Distance

Elevation Site Database(s) EPA ID Number

EUGENE FRENCH CLEANERS (Continued)

S108146489

EDR ID Number

Nefrap: Not reported Mailing: Not reported Tax Map No: Not reported

Qualify: 0

Next Action: Not reported Not reported Agencies: Not reported Air: Not reported Building: Site Desc: Not reported Drink: Not reported Not reported Eptox: Not reported Fish: Not reported Ground: Ground Desc: Not reported Not reported Hazardous Threat: Not reported Haz Threat Desc: Leachate: Not reported Not reported Preparer: Sediment: Not reported Not reported Soil: Surface: Not reported Not reported Status: Surface Soil: Not reported Surface: Not reported TCLP: Not reported Waste: Not reported

NY MANIFEST:

EPA ID: NYD981083231

Country: USA

Mailing Name: EUGENE FRENCH
Mailing Contact: EUGENE FRENCH
Mailing Address: 54 EAST MAIN STREET

Mailing Address 2: Not reported
Mailing City: BABYLON
Mailing State: NY
Mailing Zip: 11702
Mailing Zip4: Not reported
Mailing Country: USA
Mailing Phone: 516-661-2604

NY MANIFEST:

No Manifest Records Available

SPILLS:

 Facility ID:
 9311297

 DER Facility ID:
 176265

 Facility Type:
 ER

 Site ID:
 212755

 DEC Region:
 1

Spill Date: 12/17/1993

Spill Number/Closed Date: 9311297 / 5/22/2000

Spill Cause: Deliberate

Spill Class: Known release that creates potential for fire or hazard. DEC Response.

Willing Responsible Party. Corrective action taken.

SWIS: 5220

Direction Distance

Elevation Site Database(s) EPA ID Number

EUGENE FRENCH CLEANERS (Continued)

S108146489

EDR ID Number

Investigator: WJPARISH
Referred To: Not reported
Reported to Dept: 12/17/1993
CID: Not reported
Water Affected: Not reported

Spill Source: Commercial/Industrial
Spill Notifier: Police Department
Cleanup Ceased: Not reported
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False

Date Entered In Computer: 12/21/1993
Spill Record Last Update: 5/22/2000
Spiller Name: DONALD

Spiller Company: EUGENE FRENCH CLEANERS
Spiller Address: 54 EAST MAIN STREET

0

Spiller City, St, Zip: BABYLON, NY

Spiller Company: 001

Remediation Phase:

Contact Name: Not reported Contact Phone: Not reported

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was

"PARISH"10/10/95: This is additional information about material spilled from the translation of the old spill file: POSS DRY CLEANING

FL.REFERRED TO HAZ WASTE, SITE # 152157

Remarks: OWNER PUMPING OUT BASEMENT TO PARKING LOT, OIL AND WATER & CHEMICAL

ODOR IN AREA, SCDH & ADA NOTIFIED

Material:

212755 Site ID: Operable Unit ID: 993176 Operable Unit: 01 Material ID: 390337 Material Code: 0001A #2 Fuel Oil Material Name: Case No.: Not reported Material FA: Petroleum Quantity: 0 Units: Gallons Recovered: No Resource Affected: Not reported Oxygenate: False

Tank Test:

 Facility ID:
 9512630

 DER Facility ID:
 176265

 Facility Type:
 ER

 Site ID:
 212756

 DEC Region:
 1

 Spill Date:
 1/10/1996

Spill Number/Closed Date: 9512630 / 5/22/2000 Spill Cause: Equipment Failure

Spill Class: Known release that creates potential for fire or hazard. DEC Response.

Willing Responsible Party. Corrective action taken.

Direction Distance

Elevation Site Database(s) **EPA ID Number**

EUGENE FRENCH CLEANERS (Continued)

S108146489

EDR ID Number

SWIS: 5220 Investigator: **WJPARISH** Referred To: Not reported Reported to Dept: 1/10/1996 CID: 196

Water Affected: Not reported Spill Source: Commercial/Industrial Spill Notifier: Affected Persons Cleanup Ceased: Not reported Cleanup Meets Std: True

Not reported Last Inspection: Recommended Penalty: False **UST Trust:** False Remediation Phase: Date Entered In Computer: 1/10/1996 Spill Record Last Update: 5/22/2000 Spiller Name: MR GOTTWALD Spiller Company: STATE UTILITIES Spiller Address: Not reported LINDENHURST, NY Spiller City, St, Zip:

Spiller Company: 001

MR GOTTWALD Contact Name: Contact Phone: (516) 661-2604

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was

"PARISH"ALSO SEE 95-12641SITE REFERRED TO HWR SITE #152157

Remarks: oil co. on scene and was making delivery when the oil tank splitand at this point 200 gals could have spilled in basement.process of

clean up at this time. oil co is state utility

Material:

Site ID: 212756 Operable Unit ID: 1023728 Operable Unit: 01 Material ID: 356376 Material Code: 0002A Material Name: #4 Fuel Oil Case No.: Not reported Material FA: Petroleum Quantity: 200 Gallons Units: Recovered: No Resource Affected: Not reported

Tank Test:

Oxygenate:

NY VAPOR REOPENED G34 **EUGENE DRY CLEANERS**

False

ssw **54 EAST MAIN STREET** 1/4-1/2 **BABYLON (V), NY**

0.283 mi.

Relative:

1493 ft. Site 2 of 2 in cluster G VAPOR REOPENED:

Site Code: Higher

Facility Status: Complete (Mitigate)

Actual: 9 ft.

S102236559

N/A

NY Spills

Direction Distance

Elevation Site Database(s) EPA ID Number

EUGENE DRY CLEANERS (Continued)

S102236559

EDR ID Number

SPILLS:

 Facility ID:
 9512641

 DER Facility ID:
 281879

 Facility Type:
 ER

 Site ID:
 212757

 DEC Region:
 1

Spill Date: 1/10/1996

Spill Number/Closed Date: 9512641 / 4/7/1997 Spill Cause: Equipment Failure

Spill Class: Known release that creates potential for fire or hazard. DEC Response.

Willing Responsible Party. Corrective action taken.

SWIS: 5200

Investigator: ACLAMANN
Referred To: Not reported
Reported to Dept: 1/11/1996
CID: 297
Water Affected: Not reported

Spill Source: Commercial/Industrial

Spill Notifier: Commercial/Industria
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported

Cleanup Meets Std: True

Last Inspection: Not reported Recommended Penalty: False UST Trust: False Remediation Phase: 0 Date Entered In Computer: 1/11/1996 Spill Record Last Update: 8/12/2003

Spiller Name: DONALD GOTTWALD
Spiller Company: DONALD GOTTWALD
Spiller Address: 54 EAST MAIN STREET
Spiller City,St,Zip: BABYLON VILLAGE, NY 11702-

Spiller Company: 001

Contact Name: RAYMOND YOUNG Contact Phone: (516) 226-2380

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was

"LAMANNO"ALSO SEE 95-12630 DUPLICATE REPORT, ALSO SEE 95-12630 FOR

INFORMATION

Remarks: DRIVER WAS MAKING AN OIL DELIVERY AND WHILE FILLING A 275 GAL OIL

TANK IN THE BASEMENT OF THE BUSINESS, THE TANK SPLIT AND APPROX 100 GALS OF #2 FUEL OIL SPILLED ONTO A CEMENT FLOOR - MOST OF THE SPILL WAS CLEANED UP WITH SPEEDY DRY, PADS AND ALSO PUMPED OIL OUT OF THE TANK ITSELF - ALL SPEEDY DRY AND PADS HAVE BEEN PLACED IN 55GAL DRUMS - COMPLAINANT NEEDS A CALL BACK BECAUSE HE DOES NOT KNOW WHAT TO DO

WITH THE 55 GAL DRUMS OF CLEANING AGENTS

Material:

Site ID: 212757 Operable Unit ID: 1026981 Operable Unit: 01 Material ID: 556557 Material Code: 0001A Material Name: #2 Fuel Oil Case No.: Not reported Material FA: Petroleum Quantity: 100 Gallons Units: Recovered: No

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

EUGENE DRY CLEANERS (Continued)

Resource Affected: Not reported Oxygenate: False

Tank Test:

35 **KELLY RESIDENCE NY LTANKS** S103824464 N/A

NNE 31 HOWARD STREET 1/4-1/2 BABYLON, NY

0.300 mi. 1583 ft.

LTANKS: Relative:

Higher Site ID: 135498

Spill Number/Closed Date: 9814487 / 3/12/1999

Actual: Spill Date: 3/3/1999 11 ft. Spill Cause: Tank Overfill Spill Source: Private Dwelling

> Spill Class: Known release with minimal potential for fire or hazard. DEC Response.

> > Willing Responsible Party. Corrective action taken.

Cleanup Ceased: Not reported Cleanup Meets Standard: True SWIS: 5220 Investigator: **HMCIRRIT** Referred To: Not reported Reported to Dept: 3/4/1999 CID: 382

Water Affected: Not reported Spill Notifier: Responsible Party Last Inspection: Not reported Recommended Penalty: False **UST Involvement:** False Remediation Phase: Date Entered In Computer: 3/4/1999 Spill Record Last Update: 3/16/1999 Spiller Name: JODY KELLY Spiller Company: **KELLY RESIDENCE** Spiller Address: 31 HOWARD STREET

Spiller City, St, Zip: BABYLON, NY

Spiller County:

Spiller Contact: JODY KELLY Spiller Phone: (516) 587-7670 Spiller Extention: Not reported DEC Region:

DER Facility ID: 116348

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was

"CIRRITO"ABANDON LINE COMING OUT OF TOP OF TANK, HIGH TANK LEVEL CAUSED FUEL TO SIPHON THROUGH LINE AND SPILL ONTO FLOOR. NO SPILL OUT OF VENT. DELIVERY WAS BY PETES FUEL IN HOLBROOK, SPILL WAS CLEANED UP YESTERDAY BY APPLYING BAGS 11 BAGS OF SPEEDI DRI, MATERIAL IN PLASTIC BAGS, NO FLOOR DRAINS IN BASEMENT, NO SUMPS BUT SOME CRACKS, STRONG ODORS IN BASEMENT. CONTACTED HOMEOWNERS INSURANCE LIBERTY MUTUALSPILL TO BASEMENT FLOOR ONLY, CLEANED UP BY HOMEOWNER SPEEDI DRI PROPERLY

DISPOSED COPY OF DISPOSAL MANIFEST

Remarks: APPARENTLY TANK WAS OVERFILLED BY OIL COMPANY AND LANDED ON BASEMENT

FLOOR. OWNER PUT ABSORBANTS DOWN ON SPILL AND WILL BE CLEANING UP.

S102236559

Direction Distance

Elevation Site Database(s) **EPA ID Number**

KELLY RESIDENCE (Continued)

S103824464

EDR ID Number

Material:

Site ID: 135498 1072059 Operable Unit ID: Operable Unit: 01 Material ID: 569266 Material Code: 0001A #2 Fuel Oil Material Name: Case No.: Not reported Material FA: Petroleum Quantity: 125 Units: Gallons No Recovered: Not reported Resource Affected:

Oxygenate: False

Tank Test:

MOBIL S/S **NY LTANKS** S100177103 36 SE **MONTAUK HIGHWAY** N/A

1/4-1/2 WEST ISLIP, NY

0.325 mi. 1714 ft.

LTANKS: Relative:

Site ID: 227939 Lower Spill Number/Closed Date: 9108829 / 2/14/1992

Actual: Spill Date: 11/18/1991

5 ft. Spill Cause: Tank Test Failure Spill Source: **Gasoline Station**

> Spill Class: Known release that creates potential for fire or hazard. DEC Response.

> > Willing Responsible Party. Corrective action taken.

Cleanup Ceased: 2/14/1992 Cleanup Meets Standard: True SWIS: 5228

Investigator: T/T/F Referred To: Not reported 11/18/1991 Reported to Dept: CID: Not reported Water Affected: Not reported Spill Notifier: Tank Tester Last Inspection: Not reported Recommended Penalty: False **UST Involvement:** True

Remediation Phase: Date Entered In Computer: 11/25/1991 Spill Record Last Update: 11/14/2006 Spiller Name: Not reported Spiller Company: MOBIL S/S Spiller Address: Not reported

Spiller City,St,Zip: ΖZ Spiller County: 001

Spiller Contact: Not reported Spiller Phone: Not reported Spiller Extention: Not reported

DEC Region: DER Facility ID: 323257

Direction Distance

Elevation Site Database(s) EPA ID Number

MOBIL S/S (Continued) S100177103

DEC Memo: Not reported

Remarks: 10K FAILED AT -0.035 PETROTITE SYSTEM,

Material:

Site ID: 227939 Operable Unit ID: 962864 Operable Unit: 01 Material ID: 420939 Material Code: 0009 Material Name: Gasoline Not reported Case No.: Material FA: Petroleum Quantity: 0 Units: Gallons Recovered: No Resource Affected: Not reported

Resource Affected: Not reported Oxygenate: False

Tank Test:

Site ID:227939Spill Tank Test:1539321Tank Number:Not reported

Tank Size: 0
Test Method: 00
Leak Rate: 0

Gross Fail: Not reported Modified By: Spills
Last Modified: 10/1/2004
Test Method: Unknown

37 BABYLON HIGH SCHOOL RCRA-CESQG 1000790666
West 50 RAILROAD AVE FINDS NYD987021524

1/4-1/2 BABYLON, NY NY LTANKS
0.333 mi. NY MANIFEST
1757 ft.

Relative: RCRA-CESQG:

Higher Date form received by agency: 01/01/2007

Facility name: BABYLON HIGH SCHOOL

Actual: Facility address: 50 RAILROAD AVE

11 ft. BABYLON, NY 11702

EPA ID: NYD987021524

Mailing address: MAIN ST - NY POWER AUTH

WHITE PLAINS, NY 10601

Contact: Not reported

Contact address: MAIN ST - NY POWER AUTH

WHITE PLAINS, NY 10601

Contact country: US

Contact telephone: Not reported Contact email: Not reported

EPA Region: 02

Classification: Conditionally Exempt Small Quantity Generator

Description: Handler: generates 100 kg or less of hazardous waste per calendar

month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous

EDR ID Number

Direction Distance Elevation

Site Database(s) EPA ID Number

BABYLON HIGH SCHOOL (Continued)

1000790666

EDR ID Number

waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name: BABYLON SCHOOL DIST

Owner/operator address: 171 RALPH AVE

BABYLON, NY 11702

Owner/operator country: US

Owner/operator telephone: (516) 661-5810
Legal status: Municipal
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: BABYLON SCHOOL DIST

Owner/operator address: 171 RALPH AVE

BABYLON, NY 11702

Owner/operator country: US

Owner/operator telephone: (516) 661-5810
Legal status: Municipal
Owner/Operator Type: Operator

Owner/Op start date: Not reported Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: Nο Furnace exemption: No Used oil fuel burner: No Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006

Facility name: BABYLON HIGH SCHOOL

Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 12/07/1994

Facility name: BABYLON HIGH SCHOOL

Direction Distance

Elevation Site Database(s) **EPA ID Number**

BABYLON HIGH SCHOOL (Continued)

1000790666

EDR ID Number

Classification: Not a generator, verified

Date form received by agency: 11/16/1992

BABYLON HIGH SCHOOL Facility name: Classification: **Small Quantity Generator**

Violation Status: No violations found

FINDS:

Registry ID: 110004497697

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

LTANKS:

Site ID: 105450

Spill Number/Closed Date: 8802796 / 9/1/1988

Spill Date: 6/28/1988 Spill Cause: Tank Test Failure

Spill Source: Institutional, Educational, Gov., Other Spill Class: Not reported

Cleanup Ceased: 9/1/1988 Cleanup Meets Standard: True SWIS: 5220 **KDGOERTZ** Investigator: Not reported Referred To: Reported to Dept: 6/28/1988 CID: Not reported Water Affected: Not reported Spill Notifier: Tank Tester Last Inspection: Not reported Recommended Penalty: False **UST Involvement:** False Remediation Phase: O Date Entered In Computer: 6/29/1988 Spill Record Last Update: 6/15/2006

Spiller Name: Not reported Spiller Company: **BABYLON SCHOOL DISTRICT**

Spiller Address: 50 RAILROAD AVENUE

Spiller City, St, Zip: BABYLON, NY

Spiller County: Spiller Contact: Not reported Spiller Phone: Not reported Spiller Extention: Not reported

DEC Region: DER Facility ID: 93018

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

BABYLON HIGH SCHOOL (Continued)

1000790666

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was

"GOERTZ FD"09/01/88: BAIN RETESTED SYSTEM AFTER REPLACING VENT SUCTION & RETURN LINES & SYSTEM PASSED. DEC NOT PRESENT DURING

RETEST. FILE HAS BEEN DESTROYED ACCORDING TO STATE ARCHIVE AND RECORD

ADMINISTRATOR RETENTION/DISPOSAL PROCEDURES

10K FAILED AT -.398 GPH. BAINE IND TESTER. INITIAL SYSTEM TEST. WILL Remarks:

RETEST TANK ALONE

Material:

Site ID: 105450 Operable Unit ID: 918101 Operable Unit: 01 Material ID: 559553 Material Code: 0001A #2 Fuel Oil Material Name: Not reported Case No.: Petroleum Material FA:

Quantity: Units: Gallons Recovered: No Not reported Resource Affected:

Oxygenate: False

Tank Test:

Site ID: 105450 Spill Tank Test: 1534202 Tank Number: Not reported

Tank Size: 0 Test Method: 00 Leak Rate: 0

Gross Fail: Not reported Modified By: Spills 10/1/2004 Last Modified: Test Method: Unknown

NY MANIFEST:

EPA ID: NYD987021524

Country: USA

Mailing Name: **BABYLON HIGH SCHOOL**

Mailing Contact:

Mailing Address: 50 RAILROAD AVE Mailing Address 2: Not reported Mailing City: BABYLON Mailing State: NY Mailing Zip: 11702 Mailing Zip4: Not reported

Mailing Country: USA

Mailing Phone: 631-893-7929

Document ID: NYG3946284 Manifest Status: Not reported MAD985286988 Trans1 State ID: Trans2 State ID: Not reported Generator Ship Date: 10/21/2003

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

BABYLON HIGH SCHOOL (Continued)

1000790666

Trans1 Recv Date: 10/21/2003 Not reported Trans2 Recv Date: TSD Site Recv Date: 10/23/2003 Part A Recv Date: Not reported Part B Recv Date: Not reported NYD987021524 Generator EPA ID: Trans1 EPA ID: NYD077444263 Trans2 EPA ID: Not reported TSDF ID: MAJ84959

Waste Code: D009 - MERCURY 0.2 MG/L TCLP

Quantity: 00010 P - Pounds Units: Number of Containers: 001

Container Type: DF - Fiberboard or plastic drums (glass)

Handling Method: R Material recovery of more than 75 percent of the total material.

Specific Gravity:

Waste Code: D001 - NON-LISTED IGNITABLE WASTES

00010 Quantity: Units: P - Pounds

Number of Containers: 001

Container Type: DF - Fiberboard or plastic drums (glass) Handling Method: B Incineration, heat recovery, burning.

Specific Gravity: 01.00

Waste Code: D008 - LEAD 5.0 MG/L TCLP

Quantity: 00010 Units: P - Pounds Number of Containers: 001

Container Type: DF - Fiberboard or plastic drums (glass) Handling Method: T Chemical, physical, or biological treatment.

Specific Gravity: 01.00

Waste Code: D003 - NON-LISTED REACTIVE WASTES

Quantity: 00010 P - Pounds Units: Number of Containers: 001

DF - Fiberboard or plastic drums (glass) Container Type: Handling Method: B Incineration, heat recovery, burning.

Specific Gravity: 01.00 Year: 2003

Document ID: NYG3946284 Manifest Status: Not reported Trans1 State ID: MAD985286988 Trans2 State ID: Not reported Generator Ship Date: 10/21/2003 Trans1 Recv Date: 10/21/2003 Trans2 Recv Date: Not reported TSD Site Recv Date: 10/23/2003 Part A Recv Date: Not reported Part B Recv Date: Not reported NYD987021524 Generator EPA ID: Trans1 EPA ID: NYD077444263 Trans2 EPA ID: Not reported TSDF ID: MAJ84959

Waste Code: D002 - NON-LISTED CORROSIVE WASTES

00050 Quantity: Units: P - Pounds

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EPA ID Number

BABYLON HIGH SCHOOL (Continued)

1000790666

Number of Containers: 001

Container Type: DF - Fiberboard or plastic drums (glass)
Handling Method: B Incineration, heat recovery, burning.

Specific Gravity: 01.00 Year: 2003

H38 UNITED ARTIST MOVIE THEAT NY LTANKS S100494047 SW 34 MAIN STREET N/A

SW 34 MAIN STREET 1/4-1/2 BABYLON, NY

0.343 mi.

1813 ft. Site 1 of 2 in cluster H

Relative: LTANKS:

Higher Site ID: 211824 Spill Number/Closed Date: 9207227 / 11/26/1993

Actual: Spill Date: 7/8/1992

9 ft. Spill Cause: Tank Test Failure Spill Source: Commercial/Industrial

Spill Class: No spill occured. (Not Possible)

11/26/1993 Cleanup Ceased: Cleanup Meets Standard: True SWIS: 5220 Investigator: T/T/F Referred To: Not reported Reported to Dept: 9/22/1992 CID: Not reported Water Affected: Not reported Spill Notifier: Tank Tester Last Inspection: Not reported Recommended Penalty: False **UST Involvement:** False

Remediation Phase: 0
Date Entered In Computer: 9/23/1992
Spill Record Last Update: 11/29/1993
Spiller Name: Not reported

Spiller Company: UNITED ARTIST MOVIE THEAT Spiller Address: 1400 OLD COUNTRY ROAD

Spiller City,St,Zip: WESTBURY, NY

Spiller County: 001

Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported

DEC Region: 1
DER Facility ID: 175539
DEC Memo: Not reported

Remarks: 1500 FAILED GROSS PETROTITE TEST, TYREE TESTER, COULD NOT COMPLETE

TEST DUE TO VENT LINE

Material:

Site ID: 211824 Operable Unit ID: 970858 Operable Unit: 01 Material ID: 567433 Material Code: 0001A Material Name: #2 Fuel Oil Case No.: Not reported Petroleum Material FA:

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

UNITED ARTIST MOVIE THEAT (Continued)

S100494047

N/A

Quantity: 0 Gallons Units: Recovered: No Resource Affected: Not reported Oxygenate: False

Tank Test:

Site ID: 211824 Spill Tank Test: 1540608 Tank Number: Not reported

Tank Size: 0 Test Method: 00 Leak Rate: 0

Gross Fail: Not reported Modified By: Spills 10/1/2004 Last Modified: Test Method: Unknown

H39 **FAMILY AUTO** NY LTANKS S100148427

46 MONTAUK HIGHWAY SW

1/4-1/2 **BABYLON, NY**

0.353 mi.

1863 ft. Site 2 of 2 in cluster H

LTANKS: Relative:

Site ID: 237968 Higher

Spill Number/Closed Date: 8600286 / 5/9/1986 Actual: Spill Date: 4/10/1986

9 ft. Tank Test Failure Spill Cause: Spill Source: Gasoline Station

Spill Class: Not reported Cleanup Ceased: 5/9/1986 Cleanup Meets Standard: True SWIS: 5220 Investigator: **CXONEILL** Referred To: Not reported Reported to Dept: 4/11/1986 CID: Not reported Water Affected: Not reported Spill Notifier: Tank Tester Last Inspection: Not reported Recommended Penalty: False **UST Involvement:** True Remediation Phase:

Date Entered In Computer: 5/1/1986 Spill Record Last Update: 2/27/2006 Spiller Name: Not reported Spiller Company: **FAMILY AUTO**

Spiller Address: **46 MONTAUK HIGHWAY**

Spiller City, St, Zip: BABYLON, NY

Spiller County: 001

Spiller Contact: Not reported Spiller Phone: Not reported Spiller Extention: Not reported

DEC Region: DER Facility ID: 195997

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

FAMILY AUTO (Continued) S100148427

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was

> "O'NEILL FD" / / : TANK PASSED RETEST 4/21/86,AFTER LOCATING A STICK LINE OPENING WHICH NOBODY KNEW ABOUT AT TIME OF INITIAL TEST. FILE HAS BEEN DESTROYED ACCORDING TO STATE ARCHIVE AND RECORD

ADMINISTRATOR RETENTION/DISPOSAL PROCEDURES

Remarks: 1-5K FAILED AT -.308

Material:

Site ID: 237968 Operable Unit ID: 898220 Operable Unit: 01 Material ID: 480459 Material Code: 0009 Material Name: Gasoline Not reported Case No.: Petroleum Material FA: Quantity: 0 Units: Gallons Recovered: No

Resource Affected: Not reported Oxygenate: False

Tank Test:

Site ID: 237968 Spill Tank Test: 1529849 Tank Number: Not reported

Tank Size: 0 Test Method: 00 Leak Rate: 0

Gross Fail: Not reported Modified By: Spills Last Modified: 10/1/2004 Test Method: Unknown

40 **ISLAND DESIGN CENTER NY LTANKS** S108638372 NNW **482 DEER PARK AVENUE** N/A

1/4-1/2 **DIX HILLS, NY** 0.396 mi.

2091 ft.

LTANKS: Relative:

Site ID: 383336 Higher

Spill Number/Closed Date: 0703413 / 8/29/2007

Actual: Spill Date: 6/23/2007 14 ft. Spill Cause: Tank Test Failure Spill Source: Commercial/Industrial

> Spill Class: Known release that creates potential for fire or hazard. DEC Response.

> > Willing Responsible Party. Corrective action taken.

Cleanup Ceased: Not reported Cleanup Meets Standard: False SWIS: 5226 Investigator: hmcirrit Referred To: Not reported Reported to Dept: 6/23/2007 CID: 74

Water Affected: Not reported

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

ISLAND DESIGN CENTER (Continued)

S108638372

Spill Notifier: Other Not reported Last Inspection: Recommended Penalty: False **UST Involvement:** False Remediation Phase: Date Entered In Computer: 6/25/2007 Spill Record Last Update: 9/4/2007

Spiller Name: ANTHONY NATALE Spiller Company: ISLAND DESIGN CENTER Spiller Address: 482 DEER PARK AVE

Spiller City, St, Zip: DIX HILLS, NY

Spiller County: 001

Spiller Contact: DANIELLE CRANMER Spiller Phone: (631) 499-2222 Spiller Extention: Not reported

DEC Region:

DER Facility ID: 332797

DEC Memo: PLUGGED OLD REMOTE FILL PORT, NO CONTAMINATION REPORTED, PASSED RETEST

Not reported

Remarks: tank test failure

Material:

Site ID: 383336 Operable Unit ID: 1140691 Operable Unit: 01 Material ID: 2130780 Material Code: 0001A Material Name: #2 Fuel Oil Case No.: Not reported Material FA: Petroleum Quantity: Not reported Units: Gallons Recovered: No

Resource Affected: Not reported Oxygenate: False

Tank Test:

Site ID: 383336 Spill Tank Test: 1550935 Tank Number: 001 Tank Size: 550 Test Method: 03 Leak Rate: 0 Gross Fail:

Modified By: Watchdog Last Modified: 6/25/2007

Test Method: Horner EZ Check I or II

Direction Distance

Distance EDR ID Number
Elevation Site EPA ID Number

I41 MOBIL S/S NY LTANKS S105054282
ESE MTK HWY & EVELYN STREET N/A

ESE MTK HWY & EVELYN STREET 1/4-1/2 WEST ISLIP, NY

0.420 mi.

2219 ft. Site 1 of 3 in cluster I

Relative: LTANKS:

Higher Site ID: 233830

Spill Source:

Spill Number/Closed Date: 9002541 / 3/19/1992

Gasoline Station

Actual: Spill Date: 6/5/1990 9 ft. Spill Cause: Tank Test Failure

Spill Class: Known release that creates potential for fire or hazard. DEC Response.

Willing Responsible Party. Corrective action taken.

Cleanup Ceased: 3/19/1992 Cleanup Meets Standard: True SWIS: 5200 Investigator: **AYLEUNG** Referred To: Not reported Reported to Dept: 6/5/1990 CID: Not reported Water Affected: Not reported Spill Notifier: Tank Tester Last Inspection: Not reported Recommended Penalty: False **UST Involvement:** True Remediation Phase: Date Entered In Computer: 6/7/1990 Spill Record Last Update: 11/5/1992 Spiller Name: Not reported

Spiller Name:

Spiller Company:

Spiller Address:

Spiller City, St, Zip:

Not reported

Not reported

Not reported

ZZ

Spiller County: 001
Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported

DEC Region: 1
DER Facility ID: 192663

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was

"LEUNG/PARISH"03/19/92: PASSED RETEST 7/26/90.

Remarks: PETROTITE SYSTEMS TEST, 10K FAILED GROSS LEAK. LEAK LOCATED IN

SUBMERSIBLE PUMP IN TANK #1 EAST.

Material:

Site ID: 233830 Operable Unit ID: 942395 Operable Unit: 01 Material ID: 554560 0009 Material Code: Material Name: Gasoline Case No.: Not reported Material FA: Petroleum Quantity: Units: Gallons Recovered: No

Resource Affected: Not reported Oxygenate: False

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

MOBIL S/S (Continued) S105054282

Tank Test:

233830 Site ID: Spill Tank Test: 1537153 Not reported Tank Number:

Tank Size: Test Method: 00 Leak Rate: 0

Gross Fail: Not reported Modified By: Spills Last Modified: 10/1/2004 Test Method: Unknown

142 MOBIL OIL CORP SS MLM RCRA NonGen / NLR 1000457364 SE **409 MONTAUK HWY FINDS** NYD986914588

1/4-1/2 WEST ISLIP, NY 11795 0.433 mi.

NY MANIFEST 2286 ft. Site 2 of 3 in cluster I **NY Spills NY SPDES**

Relative:

RCRA NonGen / NLR: Higher

Date form received by agency: 01/01/2007 Actual: MOBIL OIL CORP SS MLM Facility name:

8 ft. Facility address: **409 MONTAUK HWY**

WEST ISLIP, NY 11795

EPA ID: NYD986914588 Mailing address: DOUGHTY BLVD

INWOOD, NY 11696

Contact: Not reported Contact address: DOUGHTY BLVD

INWOOD, NY 11696

Contact country: US

Contact telephone: Not reported Contact email: Not reported

EPA Region:

Classification: Non-Generator

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: MOBIL OIL CORP - MKTG ENVIRON

Owner/operator address: 3225 GALLOWS RD

FAIRFAX, VA 22037

Owner/operator country: US

(703) 849-3330 Owner/operator telephone: Legal status: Private Owner/Operator Type: Owner

Owner/Op start date: Not reported Owner/Op end date: Not reported

Owner/operator name: MOBIL OIL CORP - MKTG ENVIRON

3225 GALLOWS RD Owner/operator address: FAIRFAX, VA 22037

Owner/operator country: US

Owner/operator telephone: (703) 849-3330 Legal status: Private

Owner/Operator Type: Operator Owner/Op start date: Not reported **NY LTANKS**

Direction Distance

Elevation Site Database(s) EPA ID Number

MOBIL OIL CORP SS MLM (Continued)

1000457364

EDR ID Number

Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No Mixed waste (haz. and radioactive): No Recycler of hazardous waste: No Transporter of hazardous waste: No Treater, storer or disposer of HW: No Underground injection activity: No On-site burner exemption: No Furnace exemption: No Used oil fuel burner: Nο Used oil processor: No User oil refiner: No Used oil fuel marketer to burner: No Used oil Specification marketer: No Used oil transfer facility: No Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006

Facility name: MOBIL OIL CORP SS MLM Classification: Not a generator, verified

Date form received by agency: 04/19/1995

Facility name: MOBIL OIL CORP SS MLM Classification: Not a generator, verified

Date form received by agency: 10/01/1990

Facility name: MOBIL OIL CORP SS MLM Classification: Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110004453626

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

corrective action activities required under RCRA.

LTANKS:

Site ID: 89023

Spill Number/Closed Date: 9108945 / 12/12/1991

Spill Date: 11/21/1991
Spill Cause: Tank Test Failure
Spill Source: Gasoline Station
Spill Class: Not reported
Cleanup Ceased: 12/12/1991
Cleanup Meets Standard: True

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

MOBIL OIL CORP SS MLM (Continued)

1000457364

SWIS: 5200 Investigator: T/T/F Referred To: Not reported Reported to Dept: 11/21/1991 CID: Not reported Water Affected: Not reported Spill Notifier: Responsible Party Last Inspection: Not reported Recommended Penalty: False

0 Remediation Phase: Date Entered In Computer: 11/26/1991 Spill Record Last Update: 12/13/1991 Spiller Name: Not reported Spiller Company: MOBIL OIL CORP Spiller Address: Not reported

True

Spiller City,St,Zip: ZZ Spiller County: 001

UST Involvement:

Spiller Contact: Not reported Spiller Phone: Not reported Spiller Extention: Not reported DEC Region: 1

DER Facility ID: 81356 DEC Memo: Not reported

LINE TEST, ISLAND PUMP AND TANK TESTER. WILL PUT HELIUM IN LINE Remarks:

Material:

Site ID: 89023 Operable Unit ID: 959109 Operable Unit: 01 Material ID: 417612 Material Code: 0009 Material Name: Gasoline Not reported Case No.: Petroleum Material FA: Quantity: 0 Units: Gallons Recovered: No Resource Affected: Not reported

Tank Test:

Oxygenate:

Site ID: 89023 Spill Tank Test: 1539331 Tank Number: Not reported

False

Tank Size: 0 Test Method: 00 Leak Rate: 0

Gross Fail: Not reported Modified By: Spills 10/1/2004 Last Modified: Test Method: Unknown

Site ID: 89018

Spill Number/Closed Date: 8808933 / 3/19/1992

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

MOBIL OIL CORP SS MLM (Continued)

1000457364

Spill Date: 2/15/1989 Spill Cause: Tank Test Failure Spill Source: Gasoline Station

Spill Class: Known release that creates potential for fire or hazard. DEC Response.

Willing Responsible Party. Corrective action taken.

Cleanup Ceased: 3/19/1992 Cleanup Meets Standard: True SWIS: 5228 Investigator: **AYLEUNG** Referred To: Not reported 2/15/1989 Reported to Dept: CID: Not reported Not reported Water Affected: Spill Notifier: Tank Tester Last Inspection: Not reported Recommended Penalty: False **UST Involvement:** True Remediation Phase: Date Entered In Computer: 2/17/1989 Spill Record Last Update: 4/14/2009 Spiller Name: Not reported Spiller Company: MOBIL

Spiller Address: Not reported Spiller City, St, Zip: ΖZ

Spiller County: 001

Spiller Contact: Not reported Spiller Phone: Not reported Spiller Extention: Not reported

DEC Region: DER Facility ID: 321149

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was

"LEUNG"WILL INVESTIGATE03/19/92: PASSED RETEST 3/8/89 SEE ALSO

90-02602 SAME TANK, ACTIVE RECOVERY SPILL 90-01895.

Remarks: F&N TESTER. TANK FAILED AT -. 308 GPH.

Material:

Site ID: 89018 Operable Unit ID: 924843 Operable Unit: 01 Material ID: 453689 Material Code: 0009 Material Name: Gasoline Case No.: Not reported Material FA: Petroleum Quantity: Units: Gallons Recovered: No

Resource Affected: Not reported Oxygenate: False

Tank Test:

89018 Site ID: 1535180 Spill Tank Test: Tank Number: Not reported

Tank Size: Test Method: 00

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

MOBIL OIL CORP SS MLM (Continued)

1000457364

Leak Rate: 0

Gross Fail: Not reported Modified By: Spills Last Modified: 10/1/2004 Test Method: Unknown

89020 Site ID:

Spill Number/Closed Date: 9002602 / 3/19/1992

6/6/1990 Spill Date: Spill Cause: Tank Test Failure Spill Source: **Gasoline Station**

Spill Class: Known release that creates potential for fire or hazard. DEC Response.

Willing Responsible Party. Corrective action taken.

Cleanup Ceased: 3/19/1992 Cleanup Meets Standard: True SWIS: 5228 **WJPARISH** Investigator: Referred To: Not reported Reported to Dept: 6/6/1990 CID: Not reported Water Affected: Not reported Spill Notifier: Tank Tester Last Inspection: Not reported Recommended Penalty: False **UST Involvement:** True Remediation Phase: 0 Date Entered In Computer: 6/8/1990 Spill Record Last Update: 7/2/2009 TOM WELSON Spiller Name: Spiller Company: MOBIL S/S

Spiller City, St, Zip: ZZ Spiller County: 001

Spiller Address:

Spiller Contact: Not reported Spiller Phone: Not reported Spiller Extention: Not reported

DEC Region: DER Facility ID: 321149

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was

"PARISH/LEUNG"03/19/92: SEE ALSO 88-08933, SAME TANK PASSED RETEST

Not reported

Remarks: 6K FAILED AT -0.093. ISLAND PUMP & TANK TESTER

Material:

89020 Site ID: Operable Unit ID: 940610 Operable Unit: 01 437343 Material ID: Material Code: 0009 Material Name: Gasoline Case No.: Not reported Material FA: Petroleum Quantity: 0 Units: Gallons Recovered: No

Not reported Resource Affected:

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

MOBIL OIL CORP SS MLM (Continued)

1000457364

Oxygenate: False

Tank Test:

Site ID: 89020 1537159 Spill Tank Test: Not reported Tank Number:

Tank Size: Test Method: 00 Leak Rate: 0

Gross Fail: Not reported Modified By: Spills 10/1/2004 Last Modified: Test Method: Unknown

NY MANIFEST:

EPA ID: NYD986914588

Country: USA

Mailing Name: MOBIL WALSUNS

Mailing Contact: **ANDY**

409 MONTAUK HIGHWAY Mailing Address:

Mailing Address 2: Not reported Mailing City: WEST ISLIP Mailing State: NY Mailing Zip: 11795 Mailing Zip4: Not reported

Mailing Country: USA

516-422-3133 Mailing Phone:

Document ID: PAC6823611 Completed copy Manifest Status: Trans1 State ID: PAAH0172 Trans2 State ID: Not reported Generator Ship Date: 920214 Trans1 Recv Date: 920214 Trans2 Recv Date: Not reported 920220 TSD Site Recv Date: Part A Recv Date: Not reported 920304 Part B Recv Date:

Generator EPA ID: NYD986914588 Trans1 EPA ID: ILD051060408 Trans2 EPA ID: Not reported TSDF ID: PAD987266715

Waste Code: D008 - LEAD 5.0 MG/L TCLP

Quantity: 00150

Units: G - Gallons (liquids only)* (8.3 pounds)

Number of Containers: 001

Container Type: TT - Cargo tank, tank trucks

Handling Method: T Chemical, physical, or biological treatment.

Specific Gravity: 100 92 Year:

SPILLS:

Facility ID: 9804217 DER Facility ID: 321149

Direction Distance

Elevation Site Database(s) EPA ID Number

MOBIL OIL CORP SS MLM (Continued)

1000457364

EDR ID Number

 Facility Type:
 ER

 Site ID:
 89025

 DEC Region:
 1

 Spill Date:
 7/3/1998

Spill Number/Closed Date: 9804217 / 4/30/1999

Spill Cause: Other

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.

Willing Responsible Party. Corrective action taken.

SWIS: 5228
Investigator: DONOVAN
Referred To: Not reported
Reported to Dept: 7/3/1998
CID: 370

Water Affected: Not reported
Spill Source: Private Dwelling

Spill Notifier: DEC Cleanup Ceased: Not reported Cleanup Meets Std: True Last Inspection: Not reported Recommended Penalty: False **UST Trust:** False Remediation Phase: 0 Date Entered In Computer: 7/3/1998 Spill Record Last Update: 12/28/2012

Spiller Name: DEBBIE MATTHEWS
Spiller Company: MATTHEWS RESIDENCE
Spiller Address: 409 MONTAUK HIGHWAY
Spiller City,St,Zip: EAST MORICHES, ZZ

Spiller Company: 001

Contact Name: DEBBIE MATTHEWS

Contact Phone: Not reported

DEC Memo: TELECON LAPINSKI, WILL ADVISE SPILLER TO CONTACT SPILLS OFFICECLEANUP

COMPLETE, 4 TONS OF SOIL TAKEN TO AB OIL

Remarks: following up tip complaint - resident working on cars oil saturated

soil

No

Material:

89025 Site ID: Operable Unit ID: 1065075 Operable Unit: 01 Material ID: 318936 Material Code: 0015 Material Name: Motor Oil Case No.: Not reported Material FA: Petroleum Quantity: Gallons Units:

Resource Affected: Not reported Oxygenate: False

Tank Test:

Recovered:

Facility ID: 9405681
DER Facility ID: 81356
Facility Type: ER

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

MOBIL OIL CORP SS MLM (Continued)

1000457364

Site ID: 89024 DEC Region: Spill Date: 7/26/1994

Spill Number/Closed Date: 9405681 / 11/1/1994 Spill Cause: **Human Error**

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.

Willing Responsible Party. Corrective action taken.

SWIS: 5200 Investigator: **RDDECAND** Referred To: Not reported Reported to Dept: 7/26/1994 Not reported CID: Water Affected: Not reported Spill Source: Gasoline Station Spill Notifier: Affected Persons Cleanup Ceased: 11/1/1994 Cleanup Meets Std: True Last Inspection: Not reported

Recommended Penalty: False **UST Trust:** False Remediation Phase: O

Date Entered In Computer: 7/28/1994 Spill Record Last Update: 11/26/2002 Spiller Name: Not reported Spiller Company: CUSTOMER Spiller Address: Not reported

Spiller City, St, Zip: NY Spiller Company: 999

Contact Name: Not reported Contact Phone: Not reported

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was

"DECANDIA"11/01/94: SMALL SPILL CLEANED UP BY ATTENDANT.

Remarks: AT MOBIL S/S, CUSTOMER DROVE OFF WITH HOSE IN TANK, CLEANED UP WITH

SPEEDI DRI, CONTRACTOR WILL FIX PUMP,

Material:

89024 Site ID: Operable Unit ID: 999993 Operable Unit: 01 Material ID: 558728 Material Code: 0009 Material Name: Gasoline Case No.: Not reported Material FA: Petroleum

Quantity: Units: Gallons Recovered: No

Resource Affected: Not reported

Oxygenate: False

Tank Test:

Facility ID: 0402543 DER Facility ID: 321149 Facility Type: ER Site ID: 89016

Direction Distance

Elevation Site Database(s) EPA ID Number

MOBIL OIL CORP SS MLM (Continued)

1000457364

EDR ID Number

DEC Region:

Spill Date: 6/8/2004

Spill Number/Closed Date: 0402543 / 2/22/2010

Spill Cause: Unknown

Spill Class: Known release that creates potential for fire or hazard. DEC Response.

Willing Responsible Party. Corrective action taken.

SWIS: 5228
Investigator: caengelh
Referred To: Not reported
Reported to Dept: 6/8/2004
CID: 403

Water Affected: Not reported Spill Source: Gasoline Station

Spill Notifier: Other Cleanup Ceased: Not reported Cleanup Meets Std: False Last Inspection: Not reported Recommended Penalty: False **UST Trust:** False Remediation Phase: O Date Entered In Computer: 6/8/2004 Spill Record Last Update: 2/24/2010

Spiller Name: CHRISTINE CAMARDELLA

Spiller Company: MOBIL

Spiller Address: 409 MONTAUK HIGHWAY

Spiller City,St,Zip: WEST ISLIP, NY

Spiller Company: 001

Contact Name: CHRISTINE CAMARDELLA

Contact Phone: (631) 285-6684

DEC Memo: ***SEE ALSO 8805757 & 9001845 HERE*** DRPrior to Sept, 2004 data

translation this spill Lead_DEC Field was "ENGELHARDT"SAME AS CLOSED SPILL 93-13226, SAME AS SPILL #88-01895 KY ACTIVE WELL SITE6/15/01

TELECON WITH CHRISTINE CAMARDELLA, 0.01 FOOT PRODUCT IN ON EOT HE TWO

MW'S GOING TO PERFORM TIGHTNESS TESTINGHANDLING UNDER 88-05757

Remarks: never had product before already an active case # for this site.

Material:

Site ID: 89016 884214 Operable Unit ID: Operable Unit: 01 Material ID: 490159 Material Code: 0009 Material Name: Gasoline Case No.: Not reported Material FA: Petroleum Quantity:

Units: Gallons
Recovered: No
Recovered: No

Resource Affected: Not reported Oxygenate: False

Tank Test:

Facility ID: 9103380
DER Facility ID: 81356
Facility Type: ER

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

MOBIL OIL CORP SS MLM (Continued)

1000457364

Site ID: 89021 DEC Region:

Spill Date: 6/24/1991

Spill Number/Closed Date: 9103380 / 1/13/1992 Spill Cause: Other Spill Class: Not reported

SWIS: 5200 KAKISPER Investigator: Referred To: Not reported Reported to Dept: 6/24/1991 Not reported CID: Water Affected: Not reported

Spill Source: Commercial/Industrial

Spill Notifier: DEC Cleanup Ceased: 1/13/1992 Cleanup Meets Std: True Last Inspection: Not reported Recommended Penalty: False **UST Trust:** False Remediation Phase: O Date Entered In Computer: 6/27/1991

Spill Record Last Update: 1/14/1992 Spiller Name: Not reported Spiller Company: MOBIL OIL Spiller Address: Not reported

Spiller City,St,Zip: ZZ Spiller Company: 001

Contact Name: Not reported Contact Phone: Not reported

Prior to Sept, 2004 data translation this spill Lead_DEC Field was DEC Memo:

"KISPERT"01/13/92: CLOSED, W/O & F/O TANKS REMOVED ONLY 6/91 & 7/91,

SEE 90-01895 FOR DETAILS, REMEDIATION SITE.

Remarks: SITE HAS ACTIVE REMEDIATION PROJECT GOING . TANK REMOVED, 2 HOLES IN

BOTTOM, 20 YDS SOIL STOCKPILED

Material:

89021 Site ID: Operable Unit ID: 954184 Operable Unit: 01 425822 Material ID: Material Code: 0001A #2 Fuel Oil Material Name: Case No.: Not reported Material FA: Petroleum Quantity:

Units: Gallons Recovered: No

Resource Affected: Not reported Oxygenate: False

Tank Test:

Facility ID: 9001845 DER Facility ID: 407357 Facility Type: ER Site ID: 89019

Direction Distance

Elevation Site Database(s) **EPA ID Number**

MOBIL OIL CORP SS MLM (Continued)

1000457364

EDR ID Number

DEC Region:

Spill Date: 5/17/1990

Spill Number/Closed Date: 9001845 / Not Reported

Spill Cause: Unknown

Spill Class: Known release that creates potential for fire or hazard. DEC Response.

Willing Responsible Party. Corrective action taken.

SWIS: 5228 Investigator: caengelh Referred To: Not reported 5/17/1990 Reported to Dept: Not reported CID: Water Affected: Not reported Spill Source: Gasoline Station Spill Notifier: Responsible Party Cleanup Ceased: Not reported Cleanup Meets Std: False Last Inspection: Not reported Recommended Penalty: False **UST Trust:** False Remediation Phase: 5 Date Entered In Computer: 5/22/1990 Spill Record Last Update: 8/13/2011 Spiller Name: Not reported Spiller Company: **MOBIL**

Spiller Address: Not reported

Spiller City,St,Zip: ZZ Spiller Company: 001

Contact Name: Not reported Not reported Contact Phone:

SEE ALSO 8805757 & 0402543 HERE DRPrior to Sept, 2004 data DEC Memo:

translation this spill Lead_DEC Field was "YAGER WELL"IN LOG BOOK AND

3-FOLDER FILES AS 90-01895.2/9/05 FILE REASSIGNED

MGR FOUND GAS IN 2 MONITORING WELLS.MOBIL IS PUMPING OUT & WILL

INVESTIGATE

Material:

Remarks:

89019 Site ID: Operable Unit ID: 941701 Operable Unit: 01 Material ID: 436626 Material Code: 0009 Material Name: Gasoline Case No.: Not reported Material FA: Petroleum Quantity: 0 Units: Gallons Recovered: No

Resource Affected: Not reported False Oxygenate:

Tank Test:

Click this hyperlink while viewing on your computer to access additional NY_SPILL: detail in the EDR Site Report.

Direction Distance Elevation

Site Database(s) **EPA ID Number**

MOBIL OIL CORP SS MLM (Continued)

1000457364

EDR ID Number

SPDES:

Permit Number: NY0225550

State-Region:

Expiration Date: 03/01/2002 **Current Major Minor Status:** Minor Primary Facility SIC Code: 4959

State Water Body Name: SAMPAWAM'S CK

Limit Set Status Flag: Active

Total Actual Average Flow(MGD): Not reported Total App Design Flow(MGD): Not reported UDF1: Not reported 40.7 / -73.308333 Lat/Long: TIM DOUTHIT DMR Cognizant Official: UDF2: 001701

UDF3:

FIPS County Code: NY103

Non-Gov Permit Affiliation Type Desc: **DMR Mailing Address** Non-Gov Permit Org Formal Name: LAND TECH REMEDIAL

Non-Gov Permit Street Address: MOBIL S/S 17 Non-Gov Permit Supplemental Location: 31 DUBON COURT Non-Gov Permit City: **FARMINGDALE**

NY Non-Gov Permit State Code: Non-Gov Permit Zip Code: 11735

Non-Gov Facility Affiliation Type Desc: Mailing Address Non-Gov Facility Org Formal Name: MOBIL OIL CORP Non-Gov Facility Street Address: MOBIL S/S 17 Non-Gov Facility Supplemental Location: 409 MONTAUK HWY

WEST ISLIP Non-Gov Facility City:

Non-Gov Facility State Code: NY Non-Gov Facility Zip Code: 11795

State Water Body: 02030202070

UDF2: 001701 UDF3: NY103 FIPS County Code:

DMR Mailing Address Non-Gov Permit Affiliation Type Desc: Non-Gov Permit Org Formal Name: LAND TECH REMEDIAL

Non-Gov Permit Street Address: MOBIL S/S 17 Non-Gov Permit Supplemental Location: 31 DUBON COURT Non-Gov Permit City: **FARMINGDALE**

Non-Gov Permit State Code: NY Non-Gov Permit Zip Code: 11735 Non-Gov Facility Affiliation Type Desc: Owner

Non-Gov Facility Org Formal Name: MOBIL OIL CORP Non-Gov Facility Street Address: MOBIL S/S 17 Non-Gov Facility Supplemental Location: 464 DOUGHTY BLVD

Non-Gov Facility City: **INWOOD** Non-Gov Facility State Code: NY Non-Gov Facility Zip Code: 11696 State Water Body: 02030202070

UDF2: 001701

UDF3:

FIPS County Code: NY103

Direction Distance

EDR ID Number Elevation Site **EPA ID Number** Database(s)

MOBIL OIL CORP SS MLM (Continued)

1000457364

Non-Gov Permit Affiliation Type Desc: Permittee MOBIL OIL CORP Non-Gov Permit Org Formal Name: Non-Gov Permit Street Address: 464 DOUGHTY BLVD

Non-Gov Permit Supplemental Location: Not reported Non-Gov Permit City: **INWOOD** NY Non-Gov Permit State Code: Non-Gov Permit Zip Code: 11696 Non-Gov Facility Affiliation Type Desc: Mailing Address

Non-Gov Facility Org Formal Name: MOBIL OIL CORP Non-Gov Facility Street Address: MOBIL S/S 17 Non-Gov Facility Supplemental Location: 409 MONTAUK HWY

Non-Gov Facility City: WEST ISLIP Non-Gov Facility State Code: NY Non-Gov Facility Zip Code: 11795 State Water Body: 02030202070

UDF2: 001701 UDF3:

FIPS County Code: NY103

Non-Gov Permit Affiliation Type Desc: Permittee Non-Gov Permit Org Formal Name: MOBIL OIL CORP Non-Gov Permit Street Address: 464 DOUGHTY BLVD

Non-Gov Permit Supplemental Location: Not reported Non-Gov Permit City: **INWOOD** Non-Gov Permit State Code: NY Non-Gov Permit Zip Code: 11696 Non-Gov Facility Affiliation Type Desc: Owner

Non-Gov Facility Org Formal Name: MOBIL OIL CORP Non-Gov Facility Street Address: MOBIL S/S 17 Non-Gov Facility Supplemental Location: 464 DOUGHTY BLVD

Non-Gov Facility City: INWOOD Non-Gov Facility State Code: Non-Gov Facility Zip Code: 11696 02030202070 State Water Body:

143 **DELTA S/S NY LTANKS** S100149940 **NY MANIFEST** SE **410 MONTAUK HWY** N/A

1/4-1/2 WEST ISLIP, NY

0.436 mi.

2304 ft. Site 3 of 3 in cluster I

LTANKS: Relative:

Site ID: 181673 Higher

Actual: Spill Date: 6/14/1988 8 ft. Spill Cause: Tank Test Failure

Spill Source: **Gasoline Station**

Spill Number/Closed Date: 8802347 / 4/7/1995

Spill Class: Known release that creates potential for fire or hazard. DEC Response.

Willing Responsible Party. Corrective action taken.

Cleanup Ceased: 4/7/1995 Cleanup Meets Standard: True SWIS: 5228 T/T/F Investigator:

Referred To: Not reported Reported to Dept: 6/15/1988 CID: Not reported Water Affected: Not reported Spill Notifier: Tank Tester

NY Spills

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

DELTA S/S (Continued) S100149940

Last Inspection: Not reported Recommended Penalty: False **UST Involvement:** True Remediation Phase: 0 Date Entered In Computer: 6/24/1988 3/14/2009 Spill Record Last Update: Spiller Name: Not reported Spiller Company: **GULF**

Spiller Address: 410 MONTAUK HIGHWAY

Spiller City, St, Zip: WEST ISLIP, NY

Spiller County: 001

Spiller Contact: Not reported Spiller Phone: Not reported Spiller Extention: Not reported

DEC Region: DER Facility ID: 360043

DEC Memo: GULF DIVISION OF CUMBERLAND FARMS348 ALLENS AVEPROVIDENCE, RI

02909POSSIBLE RETEST OF 88-02262, ALTHOUGH SCHDS INDICATES THIS TO BE

TANK #1, AND 88-02262 TO BE TANK #3, ALL TANKS RMEOVED 7/10/90,

CONTAMINATION ENCOUNTERED DURING DEWATERING HANDLED UNDER 90-03946

Remarks: 8K FAILED AT -.077 GPH F&N TESTER.

Material:

Site ID: 181673 Operable Unit ID: 917674 Operable Unit: 01 Material ID: 457918 Material Code: 0009 Material Name: Gasoline Not reported Case No.: Material FA: Petroleum Quantity: 0 Units: Gallons Recovered: No

Resource Affected: Not reported Oxygenate: False

Tank Test:

181673 Site ID: Spill Tank Test: 1534121 Tank Number: Not reported

Tank Size: Test Method: 00 Leak Rate: 0

Gross Fail: Not reported Modified By: Spills 10/1/2004 Last Modified: Test Method: Unknown

Site ID: 181672

Spill Number/Closed Date: 8802262 / 4/7/1995

Spill Date: 6/9/1988 Spill Cause: Tank Test Failure Spill Source: Gasoline Station

Spill Class: Known release that creates potential for fire or hazard. DEC Response.

Direction Distance

Elevation Site Database(s) **EPA ID Number**

DELTA S/S (Continued) S100149940

Willing Responsible Party. Corrective action taken.

Cleanup Ceased: 4/7/1995 Cleanup Meets Standard: True SWIS: 5228 Investigator: T/T/F Referred To: Not reported 6/13/1988 Reported to Dept: CID: Not reported Water Affected: Not reported Spill Notifier: Tank Tester Last Inspection: Not reported False Recommended Penalty: **UST Involvement:** True Remediation Phase: Date Entered In Computer: 6/24/1988 Spill Record Last Update: 3/14/2009

Spiller Name: Not reported Spiller Company: WEST ISLIP GULF Spiller Address: Not reported Spiller City, St, Zip: PROVIDENCE, RI

Spiller County: 001

Spiller Contact: Not reported Spiller Phone: Not reported Spiller Extention: Not reported DEC Region:

DER Facility ID: 360043

DEC Memo: TANK ALONE FAILED 6/14/88, TANK REMOVED 7/10/90, CONTAMINATION

ENCOUNTERED DURING DEWATERING HANDLED UNDER SPILL 90-03946

Remarks: 8K FAILED PETROTITE TEST WITH GROSS LEAK. F&N EXPOSED TANK TOP ON

6/10 AND DID NOT FIND A LEAK. F&N TO TEST TANK ALONE

Material:

Site ID: 181672 Operable Unit ID: 919582 Operable Unit: 01 Material ID: 461387 Material Code: 0009 Material Name: Gasoline Case No.: Not reported Material FA: Petroleum

Quantity: Units: Gallons Recovered: Resource Affected: Not reported

Oxygenate: False

Tank Test:

Site ID: 181672 Spill Tank Test: 1534094 Tank Number: Not reported

Tank Size: 00 Test Method: Leak Rate: 0

Gross Fail: Not reported Modified By: Spills Last Modified: 10/1/2004

EDR ID Number

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

DELTA S/S (Continued) S100149940

Test Method: Unknown

NY MANIFEST:

EPA ID: NYD986909513

Country: USA

Mailing Name: **CUMBERLAND FARMS** Mailing Contact: **CUMBERLAND FARMS** Mailing Address: 348 ALLEN AVENUE

Mailing Address 2: Not reported **PROVIDENCE** Mailing City:

Mailing State: RΙ Mailing Zip: 02904 Mailing Zip4: Not reported Mailing Country: **USA**

Mailing Phone: 000-000-0000

NY MANIFEST:

No Manifest Records Available

SPILLS:

Facility ID: 1007231 DER Facility ID: 360043 Facility Type: ER Site ID: 440627 DEC Region:

Spill Date: 10/5/2010

Spill Number/Closed Date: 1007231 / 7/12/2011

Spill Cause: Other

Spill Class: Known release that creates potential for fire or hazard. DEC Response.

Willing Responsible Party. Corrective action taken.

SWIS: 5228 Investigator: wxprzylo Referred To: Not reported Reported to Dept: 10/5/2010 CID: Not reported Water Affected: Not reported Spill Source: Gasoline Station

Spill Notifier: Other Cleanup Ceased: Not reported Cleanup Meets Std: False Last Inspection: Not reported Recommended Penalty: False **UST Trust**: False Remediation Phase: 0 Date Entered In Computer: 10/5/2010 Spill Record Last Update: 8/1/2011

Spiller Name: FIRE CHIEF ON THE SCENE

Spiller Company: **GAS STATION**

Spiller Address: 410 MONTAUK HIGHWAY

Spiller City, St, Zip: WEST ISLIP, NY

Spiller Company: 999

Contact Name: FIRE CHIEF ON THE SCENE

Contact Phone: (631) 661-6440

DEC Memo: 10/05/10 @20:15 VP responded, NA contacted. (VP) Remarks: Caller reporting a fire at a gas station- Extingushing agent on

Direction Distance

Elevation Site Database(s) EPA ID Number

DELTA S/S (Continued) S100149940

ground. RESPONSE REQUESTED

Material:

 Site ID:
 440627

 Operable Unit ID:
 1191236

 Operable Unit:
 01

 Material ID:
 2186357

 Material Code:
 0981A

FIRE RUNOFF Material Name: Case No.: Not reported Material FA: Other Not reported Quantity: Gallons Units: Not reported Recovered: Resource Affected: Not reported Oxygenate: False

Tank Test:

 Facility ID:
 0651347

 DER Facility ID:
 321939

 Facility Type:
 ER

 Site ID:
 372207

 DEC Region:
 1

 Spill Date:
 10/19/2006

Spill Number/Closed Date: 0651347 / 12/1/2011

Spill Cause: Other

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.

Unknown Responsible Party. Corrective action taken. (ISR)

SWIS: 5228
Investigator: dhraymon
Referred To: Not reported
Reported to Dept: 10/19/2006
CID: Not reported
Water Affected: Not reported
Spill Source: Gasoline Station

Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0

Date Entered In Computer: 10/19/2006 Spill Record Last Update: 3/13/2012 Spiller Name: Not reported Spiller Company: Not reported Spiller Address: Not reported Spiller City, St, Zip: Not reported Spiller Company: Not reported Contact Name: Not reported Contact Phone: Not reported

DEC Memo: 10/20/06: Tormey left message- wants an inspection MONDAY.

KY10/23/06: As per Tormey-THEY DID NOT REMOVE ANY CONTAMINATED SOIL, AND 'THE WATER IN THE EXCAVATION 10/19 WAS MOST LIKELY RAINWATER, AS THE EXCAVATION IS 8FT DEEP, AND HE BELIEVES GROUNDWATER IS 10FT

EDR ID Number

Direction Distance

Elevation Site Database(s) EPA ID Number

DELTA S/S (Continued) S100149940

DEEP.' THERE WAS NO FLOATING PRODUCT. (KS)DEC inspected the site and confirmed the presence of contaminated soil. THIS SOIL WAS EXCAVATED INTO GROUNDWATER BUT NOT ALL OF IT COULD BE REMOVED DUE TO THE EXCAVATION'S PROXIMITY TO THE BUILDING ON ONE SIDE AND THE PROPERTY

LINE AND A LARGE TREE ON THE OTHER SIDE. Three monitoring wells were

installed and monitored but no floating product was observed. DR
Remarks: Caller was removing one 550 gallon waste oil tank and encountered

contaminated soil. He says they are in to groundwater. Told him that we have no staff available, and he said he can leave the hole opened for an inspection tomorrow. Also removed a 550 #2 oil tank that was

ok'd by SCDHS. -KY

Material:

Tank Test:

WEST ISLIP, NY

44 ABANDONED S/S NY LTANKS S104782619 ESE 425 MONTAUK HIGHWAY N/A

1/4-1/2 0.451 mi. 2381 ft.

Relative: LTANKS:

Higher Site ID: 125966

Spill Number/Closed Date: 9405859 / 7/14/2004

 Actual:
 Spill Date:
 7/27/1994

 8 ft.
 Spill Cause:
 Tank Failure

Spill Source: Commercial/Industrial

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.

Willing Responsible Party. Corrective action taken.

Cleanup Ceased: Not reported
Cleanup Meets Standard: True
SWIS: 5200
Investigator: RDDECAND

Referred To: Not reported Reported to Dept: 7/27/1994 CID: Not reported Water Affected: Not reported Spill Notifier: Citizen Last Inspection: Not reported Recommended Penalty: False **UST Involvement:** True Remediation Phase: Date Entered In Computer: 8/1/1994 Spill Record Last Update: 7/14/2004 Not reported Spiller Name:

Spiller Company: UNK
Spiller Address: Not reported
Spiller City,St,Zip: ***UPDATE***, ZZ

Spiller County: 999

Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported

DEC Region: 1

DER Facility ID: 108937

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was

"DECANDIA"CONTAMINATED SOIL EXCAVATED

EDR ID Number

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

ABANDONED S/S (Continued)

S104782619

AT ABANDONED S/S, CONT SOIL FOUND DURING DRYWELL INSTALLATIONS, OLD Remarks:

S/S TANKS PULLED IN EARLY 80'S, WELLS ON SITE FROM ADJACENT SPILLS

Material:

Site ID: 125966 Operable Unit ID: 1003235 Operable Unit: 01 Material ID: 382433 Material Code: 0009 Material Name: Gasoline Case No.: Not reported Material FA: Petroleum Quantity: 0 Units: Gallons Recovered: No Resource Affected: Not reported

Oxygenate: False

Tank Test:

APARTMENT HOUSE NY LTANKS \$104516005 45 **15-17 HEWLETT COURT** N/A

SSW 1/4-1/2 **BABYLON, NY**

0.462 mi. 2437 ft.

LTANKS: Relative:

Site ID: 266800 Lower

Spill Number/Closed Date: 9908946 / 12/3/1999

Actual: Spill Date: 10/22/1999 7 ft. Spill Cause: Tank Test Failure Spill Source: Commercial/Industrial

Spill Class: Known release that creates potential for fire or hazard. DEC Response.

Willing Responsible Party. Corrective action taken.

Cleanup Ceased: Not reported Cleanup Meets Standard: True SWIS: 5220 Investigator: T/T/F Referred To: Not reported Reported to Dept: 10/22/1999 CID: 199

Water Affected: Not reported Spill Notifier: Tank Tester Last Inspection: Not reported Recommended Penalty: False **UST Involvement:** False Remediation Phase: 0 Date Entered In Computer: 10/22/1999

Spill Record Last Update: 7/7/2010 Spiller Name: Not reported

Spiller Company: **APARTMENT HOUSE** Spiller Address: 15-17 HEWLETT COURT Spiller City, St, Zip: BABYLON, NY 11702-

Spiller County: 001

JOHN LEDDY Spiller Contact: Spiller Phone: (516) 321-4670

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

APARTMENT HOUSE (Continued)

S104516005

Spiller Extention: Not reported

DEC Region:

DER Facility ID: 217318

DEC Memo: FITTINGS ON LINES REPLACED, NO CONTAMINATION REPORTED, TANK PASSED

RETESTOWNER: JOHN & DIANE ALLISON, SNOVER & CO 193 EAST MAIN ST,

BABYLON NY 11702 661-2500 JERRY SNOVER

Remarks: small apt. house - tank is an unregulated tank

Material:

Site ID: 266800 Operable Unit ID: 1087629 Operable Unit: 01 Material ID: 298042 Material Code: 0001A #2 Fuel Oil Material Name: Case No.: Not reported Petroleum Material FA: Quantity: Units: Gallons Recovered: No

Not reported Resource Affected:

Oxygenate: False

Tank Test:

Site ID: 266800 Spill Tank Test: 1547770 Tank Number: Tank Size: 1000 Test Method: 03 Leak Rate: 0

Gross Fail: Not reported Modified By: Spills Last Modified: 10/1/2004

Horner EZ Check I or II Test Method:

NY LTANKS S105999052 46 **BABYLON VILLAGE HALL** SW **153 WEST MAIN STREET NY Spills** N/A

1/4-1/2 **BABYLON, NY**

0.464 mi. 2450 ft.

LTANKS: Relative: Site ID: Lower

Spill Number/Closed Date: 0301933 / 12/1/2011

Actual: Spill Date: 5/23/2003 7 ft. Tank Test Failure Spill Cause:

Spill Source: Institutional, Educational, Gov., Other

276855

Spill Class: Known release that creates potential for fire or hazard. DEC Response.

Willing Responsible Party. Corrective action taken.

Cleanup Ceased: Not reported Cleanup Meets Standard: False

SWIS: 5220 Investigator: **DHRAYMON** Not reported Referred To: 5/23/2003 Reported to Dept: CID: 199

TC3691395.1s Page 110

Direction Distance Elevation

evation Site Database(s) EPA ID Number

BABYLON VILLAGE HALL (Continued)

S105999052

EDR ID Number

Water Affected: Not reported Spill Notifier: Tank Tester Last Inspection: Not reported Recommended Penalty: False **UST Involvement:** False Remediation Phase: Date Entered In Computer: 5/23/2003 Spill Record Last Update: 3/13/2012 SKIP GARDINER Spiller Name: Spiller Company: AMBULANCE GARAGE

Spiller City, St, Zip: BABYLON, ZZ

Spiller County: 001

Spiller Contact: SKIP GARDINER
Spiller Phone: (631) 669-4878
Spiller Extention: Not reported

DEC Region:

Spiller Address:

DER Facility ID: 225075

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was

153 WEST MAIN STREET

"RAYMOND"5/4/04 FILE REASSIGNED***THIS FACILITY IS THE VILLAGE HALL;
THE FIRE DEPARTMENT AND AMBULANCE SERVICE ARE ON THE NORTHEAST SIDE
OF THE BUILDING AND THE DEPARTMENT OF PUBLIC WORKS IS ON THE
NORTH/NORTHWEST SIDE*** DR***THERE IS A POND A FEW HUNDRED FEET DUE
WEST*** DR***KY HAD 9500219 AND DR HAD 0511121 (BOTH TANK REMOVALS)

ON THE WEST SIDE OF THIS FACILITY*** DR The tank was removed under DEC and Suffolk County Health Department oversight. THE CONCRETE TANK

MAT WAS FOUND TO SIT DIRECTLY ON THE FIBERGLASS TANK RATHER THAN ON "PEA GRAVEL", AND F&N SAID THEY HAD BEEN TOLD THE PAD SAGGED WHEN THE FIRE DEPARTMENT PARKED A TRUCK OVER THE TANK. THE TANK WAS IN A "L-SHAPED" CORNER OF THE BUILDING IMMEDIATELY IN FRONT OF THE BAYS FOR THE FIRE DEPARTMENT AND AMBULANCE. Staining was noted on the TOP

of the tank when it was uncovered, and the tank was partially in

groundwater. THERE WAS A SHEEN (BUT NO FLOATING PRODUCT) PRESENT WHEN GROUNDWATER WAS INITIALLY EXPOSED, BUT UPON DISTURBING THE SOIL

UNDERNEATH THE GROUNDWATER, SOME PETROLEUM ROSE TO THE SURFACE AND FLOATED ON THE GROUNWATER. THE SOURCE OF THIS PETROLEUM WAS UNKNOWN.

DEC discussed the situation with the Mayor and F&N, and it was

decided that DUE TO THE TANK LOCATION, NO SOIL WOULD BE EXCAVATED BUT IT WOULD BE AGITATED IN ORDER TO RELEASE AS MUCH PETROLEUM AS POSSIBLE, WHICH WOULD THEN BE VACUUMED OFF THE WATER. THIS WAS REPEATED FOUR TIMES, UNTIL FURTHER SUCH AGITATION DID NOT RELEASE ANY ADDITIONAL PETROLEUM. A HAND BORING ON THE SOUTH (DOWNGRADIENT) SIDE OF THE EXCAVATION DID NOT REVEAL ANY PETROLEUM. FOUR SIDEWALL soil

samples, ONE BOTTOM soil sample, and one groundwater sample were

taken. Analyses for Volatile Organic Compounds (VOCs) and

SemiVolatile Organic Compounds (SVOCs) FOUND VOCS AND SVOCS IN THE SOIL, BUT ONLY A TRACE OF FIVE VOCS AND ONE SVOC IN THE GROUNDWATER.

Based upon factors such as the lack of floating product, the location of the contamination, groundwater flow direction (toward the south), and the presence of public water, no further action was required at

the time. DR

Remarks: tank located in the ambulance garage - getting prices to dig uptank

at this time

Material:

Site ID: 276855 Operable Unit ID: 869926

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

BABYLON VILLAGE HALL (Continued)

S105999052

Operable Unit: 01 Material ID: 506418 Material Code: 0001A Material Name: #2 Fuel Oil Case No.: Not reported Material FA: Petroleum 0 Quantity: Units: Gallons Recovered: No

Resource Affected: Not reported Oxygenate: False

Tank Test:

276855 Site ID: Spill Tank Test: 1528404 Tank Number: Tank Size: 2000 Test Method: 03 Leak Rate: 0

Gross Fail: Not reported Modified By: Spills 10/1/2004 Last Modified:

Test Method: Horner EZ Check I or II

SPILLS:

Facility ID: 1003299 DER Facility ID: 225075 Facility Type: ER Site ID: 436515 DEC Region: Spill Date: 6/24/2010

Spill Number/Closed Date: 1003299 / 6/25/2010

Spill Cause: Unknown

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.

Willing Responsible Party. Corrective action taken.

SWIS: 5220 Investigator: Unassigned Not reported Referred To: Reported to Dept: 6/24/2010 CID: Not reported Water Affected: Not reported Spill Source: Unknown Spill Notifier: Other Cleanup Ceased: Not reported Cleanup Meets Std: False Last Inspection: Not reported Recommended Penalty: False **UST Trust:** False Remediation Phase: 0 Date Entered In Computer: 6/24/2010 12/23/2010 Spill Record Last Update: Spiller Name: Not reported Spiller Company: **UNKNOWN** Spiller Address: Not reported

Spiller City, St, Zip: NY

Direction Distance

Elevation Site Database(s) EPA ID Number

BABYLON VILLAGE HALL (Continued)

S105999052

EDR ID Number

Spiller Company: 999
Contact Name: UNKNOWN
Contact Phone: Not reported

DEC Memo: ECO GARRIGAN INSPECTED, NO OIL FOUND6/25/10 15:40 JP CALLED MAYORS

OFFICE, SPOKE WITH MAYOR, ECO GARRIGAN AT SITE EARLIER TODAY, NO OIL

FOUND (JP)

Remarks: Caller claims there is oil all over the roadway in front of the

village hall/some of the oil is going into the storm drains

Material:

 Site ID:
 436515

 Operable Unit ID:
 1187211

 Operable Unit:
 01

 Material ID:
 2182091

 Material Code:
 0066A

Material Name: UNKNOWN PETROLEUM

Case No.:

Material FA:

Quantity:

Units:

Recovered:

Resource Affected:

Oxygenate:

Not reported

Petroleum

Not reported

Not reported

Not reported

False

Tank Test:

 Facility ID:
 0511121

 DER Facility ID:
 225075

 Facility Type:
 ER

 Site ID:
 357210

 DEC Region:
 1

Spill Date: 12/22/2005

Spill Number/Closed Date: 0511121 / 1/1/2012

Spill Cause: Other

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.

Willing Responsible Party. Corrective action taken.

SWIS: 5220
Investigator: dhraymon
Referred To: Not reported
Reported to Dept: 12/22/2005
CID: 444
Water Affected: Not reported

Spill Source: Institutional, Educational, Gov., Other

Spill Notifier: Other Cleanup Ceased: Not reported Cleanup Meets Std: False Last Inspection: Not reported Recommended Penalty: False **UST Trust:** True Remediation Phase: 0 Date Entered In Computer: 12/22/2005

Spill Record Last Update: 3/13/2012
Spiller Name: AMANDA VELLIA
Spiller Commonwell PARM ON PRIM CO.

Spiller Company: BABYLON DPW GARAGE
Spiller Address: 153 WEST MAIN STREET

Spiller City, St, Zip: BABYLON, NY

MAP FINDINGS Map ID Direction

Distance **EDR ID Number** Elevation **EPA ID Number** Site Database(s)

BABYLON VILLAGE HALL (Continued)

S105999052

Spiller Company: 001

AMANDA VELLIA Contact Name: Contact Phone: (631) 586-4900

DEC Memo: ***THIS FACILITY IS THE VILLAGE HALL; THE FIRE DEPARTMENT AND

> AMBULANCE SERVICE ARE ON THE NORTHEAST SIDE OF THE BUILDING AND THE DEPARTMENT OF PUBLIC WORKS IS ON THE NORTH/NORTHWEST SIDE*** DR***THERE IS A POND A FEW HUNDRED FEET DUE WEST*** DR***KY HAD 9500219 ON THIS SIDE AND DR HAD 0511121 (BOTH TANK REMOVALS) ON THE EAST SIDE OF THIS FACILITY*** DR12/21/05 0849 Hrs (A): BOB FERGUSON (F&N) LEFT MESSAGE- HE HAD JUST FOUND OUT THAT THIS TANK 'HAD BEEN REMOVED THE OTHER DAY.'12/21/05 0849 Hrs (B): HE SAID A NEW TANK WAS BEING INSTALLED IN THE SAME TANK BED.12/21/05 0849 Hrs (C): HE SAID HE WOULD TAKE ENDPOINT (SOIL AND/OR WATER) SAMPLES FOR ANALYSES.

DR12/21/05 0850 Hrs: Called Ferguson to discuss the matter.

DR12/21/05 0915 Hrs (A): DEC THEN CALLED JANET GREMLE (SUFFOLK COUNTY HEALTH DEPARTMENT), WHO SAID SHE HAD INSPECTED THE SITE AND CONFIRMED THE PRESENCE OF CONTAMINATED SOIL. WHICH SHE THOUGHT SMELLED LIKE

GASOLINE. DR12/21/05 1002 Hrs: Amanda left message- confirming F&N

will take WATER sample(s). DR12/22/05 1030 Hrs (A): DR called

Ferguson & Amanda- they had removed approximately 40cy of soil. THEY

COULD NOT REMOVE ANY MORE SOIL AS THEY ARE USING SHEETING TO HOLD UP

THE SIDEWALLS AND ARE PERFORMING DEWATERING IN ORDER TO INSTALL THE

NEW TANK, WHICH THEY PLAN TO DO TODAY, 12/22/05 am (B): He said they would take endpoint (soil and/or water?) samples. DR12/22/05: WG

inspected the site- PHOTOS INDICATED A SLIGHT SHEEN ON THE WATER

TABLE. DR12/23/05 1030 Hrs (A): Called Amanda- SHE SAID THE TANK HAD

NOT YET BEEN INSTALLED.12/23/05 1030 Hrs (B): They had taken WATER samples for analyses. DR12/27/05 0815 Hrs: Amanda left message- plan

to install the tank later this week. DR12/27/05 0855 Hrs: Called

Amanda- INFORMED HER DEC WOULD BE ON VACATION, DIRECTED HER TO DOCUMENT THE SITE AND THE CONDITIONS WITH PHOTOGRAPHS, ETC, AND

DIRECTED HER TO CALL NA IF THERE WERE ANY ISSUES/PROBLEMS, DR12/27/05 REASSIGNED01/10/06 1340-1350 Hrs (A): DEC inspected the site- THE NEW TANK HAD BEEN INSTALLED, AND F&N WAS COMPLETING THE REST OF THE

INSTALLATION.01/10/06 1340-1350 Hrs (B): F&N WAS STILL PERFORMING DEWATERING, AND THE WATER WAS BEING TREATED WITH A PORTABLE AIR

STRIPPING TOWER.01/10/06 1340-1350 Hrs (C): DEC FOUND ONE PRE-EXISTING MONITORING WELL ON THE SOUTH (HYDRAULICALLY DOWNGRADIENT) SIDE OF THE TANK BED-THERE WAS NO SHEEN

PRESENT.01/10/06 1340-1350 Hrs (D): DEC estimated that perhaps 200cy

of soil had been stockpiled. DR01/20/06 (A): Received F&N's closure report- included summary of work performed; site map; photographs;

laboratory data; soil disposal receipts.01/20/06 (B): Groundwater flow appeared to be "west" [toward the lake].01/20/06 (C): NO

staining nor petroleum odors were noted in the soil, and PID

measurements were negative.01/20/06 (D): THEY DID COLLECT BOTH A

WATER SAMPLE AND A SOIL SAMPLE FOR ANALYSES FOR VOLATILE ORGANIC COMPOUNDS (VOCS) USING EPA METHOD 8021, AND SEMI-VOLATILE ORGANIC

COMPOUNDS (SVOCS) USING EPA METHOD 8270.01/20/06 (E): The SOIL samples were below either the method detection limits or DEC guidance FOR BOTH VOCS AND SVOCS.01/20/06 (F): The WATER sample had ONE

EXCEEDANCE OF DEC'S SVOC GUIDANCE.01/20/06 (G): The WATER sample had TWELVE EXCEEDANCES OF DEC'S VOC GUIDANCE. THEY SUSPECTED THIS IS RESIDUAL CONTAMINATION FROM SPILL 9500219, WHICH DEC CLOSED AFTER A

SENSITIVE RECEPTOR SURVEY AND EXPOSURE ASSESSMENT HAD BEEN PERFORMED.

4000 GALLON TANK HAD HOLES AND CONTAMINATION Remarks:

Direction Distance

Elevation Site Database(s) EPA ID Number

BABYLON VILLAGE HALL (Continued)

S105999052

EDR ID Number

Material:

Site ID: 357210 Operable Unit ID: 1114493 Operable Unit: 01 Material ID: 2104563 8000 Material Code: Material Name: Diesel Case No.: Not reported Material FA: Petroleum Quantity: Not reported Units: Gallons Recovered: No Not reported Resource Affected:

Oxygenate: False

Tank Test:

47 BERNARD GENCOGLE/SUNOCO ESE 455 MONTAUK HIGHWAY 1/4-1/2 WEST ISLIP, NY NY LTANKS \$102090738 NY MANIFEST N/A NY Spills

1/4-1/2 0.482 mi. 2543 ft.

Relative: LTANKS:

Higher Site ID: 68695

Spill Number/Closed Date: 8606913 / 3/25/1987

Actual: Spill Date: 2/10/1987 8 ft. Spill Cause: Tank Test Failure

Spill Cause: Gasoline Station
Spill Class: Not reported
Cleanup Ceased: 3/25/1987
Cleanup Meets Standard: True
SWIS: 5228

Investigator: JEAN-LOUIS Referred To: Not reported 2/10/1987 Reported to Dept: CID: Not reported Water Affected: Not reported Spill Notifier: Tank Tester Last Inspection: Not reported Recommended Penalty: False **UST Involvement:** True Remediation Phase: Date Entered In Computer: 2/11/1987 Spill Record Last Update: 8/16/2005

Spiller Name: Not reported Spiller Company: TEXACO

Spiller Address: 455 MONTAUK HIGHWAY

Spiller City, St, Zip: WEST ISLIP, NY

Spiller County: 001

Spiller Contact: Not reported
Spiller Phone: Not reported
Spiller Extention: Not reported
DEC Region: 1

DER Facility ID: 298418

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

BERNARD GENCOGLE/SUNOCO (Continued)

S102090738

"JEAN-LOUIS FD" //: FAILED 1ST TEST. VENT LINE REPLACED. RETESTED

AND PASSED 3/12/87.FILE HAS BEEN DESTROYED ACCORDING TO STATE ARCHIVE

AND RECORD ADMINISTRATOR RETENTION/DISPOSAL PROCEDURES

Remarks: NO RATE, BAD VENT LINE.

Material:

Site ID: 68695 Operable Unit ID: 904515 Operable Unit: 01 Material ID: 472465 Material Code: 0009 Material Name: Gasoline Case No.: Not reported Material FA: Petroleum

Quantity: 0 Units: Gallons Recovered: No Resource Affected: Not reported

Oxygenate: False

Tank Test:

Site ID: 68695 Spill Tank Test: 1530568 Tank Number: Not reported

Tank Size: 0 Test Method: 00 Leak Rate:

Not reported Gross Fail: Spills Modified By: 10/1/2004 Last Modified: Test Method: Unknown

NY MANIFEST:

EPA ID: NYD986901445

Country: USA

NIS ENTERPRISE Mailing Name: Mailing Contact: NIS ENTERPRISE

Mailing Address: 455 MONTAUK HIGHWAY

Mailing Address 2: Not reported Mailing City: WEST ISLIP Mailing State: NY 11795 Mailing Zip: Mailing Zip4: Not reported

Mailing Country: USA

000-000-0000 Mailing Phone:

NY MANIFEST:

No Manifest Records Available

SPILLS:

Facility ID: 9002126 DER Facility ID: 298418 Facility Type: ER Site ID: 68696

Direction Distance

EDR ID Number Elevation Site Database(s) **EPA ID Number**

BERNARD GENCOGLE/SUNOCO (Continued)

S102090738

DEC Region:

Spill Date: 5/23/1990

Spill Number/Closed Date: 9002126 / Not Reported Spill Cause: Equipment Failure

Spill Class: Known release that creates potential for fire or hazard. DEC Response.

Willing Responsible Party. Corrective action taken.

SWIS: 5228 **KJGOMEZ** Investigator: Referred To: Not reported Reported to Dept: 5/23/1990 Not reported CID: Water Affected: Not reported Spill Source: Gasoline Station Spill Notifier: Health Department Cleanup Ceased: Not reported Cleanup Meets Std: False Last Inspection: Not reported Recommended Penalty: False **UST Trust:** True Remediation Phase: 4 Date Entered In Computer: 5/29/1990

Spill Record Last Update: 5/6/2011 Spiller Name: Not reported

Spiller Company: BERNARD GENCOGLE

Spiller Address: Not reported

Spiller City,St,Zip: ZZ Spiller Company: 001

Contact Name: Not reported

Contact Phone: Not reported

DEC Memo: Prior to Sept, 2004 data translation this spill Lead_DEC Field was

"GOMEZ WELL"

Remarks: ROUTINE TANK REMOVAL. FOUND FLOATING PRODUCT ON WATER TABLE.MORE

TANKS COMING OUT

Material:

Site ID: 68696 Operable Unit ID: 941973 Operable Unit: 01 Material ID: 436887 Material Code: 0009 Material Name: Gasoline Not reported Case No.: Material FA: Petroleum Quantity: Units: Gallons

Recovered: Nο Not reported Resource Affected:

Oxygenate: False

Tank Test:

City	EDR ID	Site Name	Site Address	Zip	Database(s)
BABYLON	1007808689	BABYLON 9 HOLE / PAR 3 GOLF COURSE	ST & LIRR MAIN LINE NORTHWEST		FINDS
BABYLON	S102136809	BUDGET RENT-A-CAR	RT 109		NY Spills
BABYLON	S103275631	OLD FAIRCHILD COMPLEX	RT 110		NY Spills
BABYLON	S111011426	DEPARTMENT OF TRANSPORTATION	325TH EAST MAIN ST & RT 109		NY Spills
BABYLON	U003960957	SUBARU DEALERSHIP	COOPER ST	11702	NY UST
BABYLON	S102568035	UNK	EXIT RAMP		NY Spills
BABYLON	S105056259	GILGO STATE PARK	GILGO STATE PARK		NY Spills
BABYLON	S105055517		GILGO STATE PARK		NY Spills
BABYLON	U003961060	UNITED METHODIST CHRUCH	JAMES ST	11702	NY UST
BABYLON	S102136640		W JOHN ST		NY Spills
BABYLON	1007205549	BELL ATLANTIC-NY	JOHN ST & HIGBIE LN		RCRA NonGen / NLR, NY MANIFEST
BABYLON	S104783777	UNK	MONTAUK HWY		NY Spills
BABYLON	S103683883	SANTAPOGUE CREEK	MONTAUK HWY		NY Spills
BABYLON	S104784112	UNK	MONTAUK HWY		NY Spills
BABYLON	S107658429	UNKNOWN	MONTAUK HWY & RT 27A		NY Spills
BABYLON	U003961175	BABYLON VILLAGE FIRE DEPT	153 MONTAUK HWY W	11702	NY UST
BABYLON	U003843481	L & B LINCOLN MERCURY	95 MONTAUK HWY E	11702	NY UST
BABYLON	U003960864	LONG ISLAND SAVINGS BANK	180 MONTAUK HWY E	11702	NY UST
BABYLON	A100195722	ATLANTIC BOATS	218 MONTAUK HWY E	11702	NY AST
BABYLON	S102670231	MEENAN OIL	PARKING FLD		NY LTANKS
BABYLON	S106343243	BABYLON LEAF TRANSFER STATION	PATTON AVE	11704	NY SWF/LF
BABYLON	S104498844	EASTERN COASTAL CORP	SUNRISE HWY		NY Spills
BABYLON	S111835504	ROADWAY/DRAIN	SUNRISE HWY SERV N & LARAMIE		NY Spills
BABYLON	S105972395	SUFFOLK COUNTY TEST WELL #43818	SUNRISE HIGHWAY AND LITTLE NEC		NY DEL SHWS
BABYLON	S109061678	UNKNOWN	SUNRISE HWY		NY Spills
BABYLON	S110540710	STREAM	SUNRISE HWY BETWEEN 39TH &	11702	NY Spills
BABYLON	S105842508	GERALD WRIGHT	UNKNOWN		NY SWF/LF
BAY SHORE	1001223815	NYSDOT	SOUTHERN STATE PKWY E	11702	RCRA NonGen / NLR, FINDS, NY MANIFEST
OYSTER BAY	U003377243	PLANTING FIELDS	PLANTING FIELDS RD	11702	NY SWF/LF, NY UST
RIVERHEAD		OK PETROLEUM	1212 RT 25		NY UST
W BABYLON		QUALITY CAR CARE INC	270 RT 109	11704	NY MANIFEST
WEST BABYLON	U003960910	ANG GAS & SERVICE INC	328 RT 109	11704	NY UST
WEST BABYLON	1009234045		RT 109 & ROGER CT		NY MANIFEST
WEST BABYLON		VICON INDUSTRIES INCORPORATED	385 RT 109		NY MANIFEST
WEST BABYLON	1000428709		300 RT 109		RCRA NonGen / NLR, FINDS, NY
					MANIFEST
WEST BABYLON	1000333899	TYROLIT CO INC	355 RT 109	11704	RCRA NonGen / NLR, FINDS, NY
+					MANIFEST
WEST BABYLON	1000127009	J & P COLLISION INC	280 RT 109	11704	RCRA NonGen / NLR, FINDS, NY MANIFEST
WEST BABYLON	1001482802	PHOTO REFLECTIONS	142 RT 109	11704	RCRA NonGen / NLR, FINDS, NY MANIFEST

Count: 46 records. ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
WEST BABYLON	S108758419	ST. CHARLES CEMETARY	CONKLIN ST & NEW HWY	11704	NY SWF/LF
WEST BABYLON	S105842024	BABYLON SLF	EDISON & GLEAM ST	11704	NY SWF/LF
WEST BABYLON	S106075907	CAYA MATERIALS OF BABYLON	PATTON BLVD	11704	NY SWF/LF
WEST ISLIP	S110047317	STOP & SHOP PLAZA	400 UN BOULEVARD PARKING LOT	11795	NY MANIFEST
WEST ISLIP	U003844071	B P OIL CO S/S	MONTAUK HWY	11795	NY UST
WEST ISLIP	U003844129	COMMERCIAL REALTY BLDG	MONTAUK HWY & MC	11795	NY UST
WEST ISLIP	U003844318	DESIMONE REALTY	54 MONTAUK HWY	11795	NY UST
WEST ISLIP	A100197392	SCWA WELLFIELD SUNRISE HWY	SUNRISE HWY	11795	NY AST

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

STANDARD ENVIRONMENTAL RECORDS

Federal NPL site list

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 04/26/2013 Source: EPA
Date Data Arrived at EDR: 05/09/2013 Telephone: N/A

Date Made Active in Reports: 07/10/2013 Last EDR Contact: 05/09/2013

Number of Days to Update: 62 Next Scheduled EDR Contact: 07/22/2013
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources

EPA's Environmental Photographic Interpretation Center (EPIC)

Telephone: 202-564-7333

EPA Region 1 EPA Region 6

Telephone 617-918-1143 Telephone: 214-655-6659

EPA Region 3 EPA Region 7

Telephone 215-814-5418 Telephone: 913-551-7247

EPA Region 4 EPA Region 8

Telephone 404-562-8033 Telephone: 303-312-6774

EPA Region 5 EPA Region 9

Telephone 312-886-6686 Telephone: 415-947-4246

EPA Region 10

Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 04/26/2013 Source: EPA
Date Data Arrived at EDR: 05/09/2013 Telephone: N/A

Number of Days to Update: 62 Next Scheduled EDR Contact: 07/22/2013
Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991 Date Data Arrived at EDR: 02/02/1994 Date Made Active in Reports: 03/30/1994

Number of Days to Update: 56

Source: EPA Telephone: 202-564-4267 Last EDR Contact: 08/15/2011

Next Scheduled EDR Contact: 11/28/2011 Data Release Frequency: No Update Planned

Federal Delisted NPL site list

DELISTED NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 04/26/2013 Date Data Arrived at EDR: 05/09/2013 Date Made Active in Reports: 07/10/2013

Number of Days to Update: 62

Source: EPA Telephone: N/A

Last EDR Contact: 05/09/2013 Next Scheduled EDR Contact: 07/22/2013

Next Scheduled EDR Contact: 07/22/201
Data Release Frequency: Quarterly

Federal CERCLIS list

CERCLIS: Comprehensive Environmental Response, Compensation, and Liability Information System

CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 04/26/2013 Date Data Arrived at EDR: 05/29/2013 Date Made Active in Reports: 08/09/2013

Number of Days to Update: 72

Source: EPA Telephone: 703-412-9810

Last EDR Contact: 05/29/2013

Next Scheduled EDR Contact: 09/09/2013 Data Release Frequency: Quarterly

FEDERAL FACILITY: Federal Facility Site Information listing

A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 07/31/2012 Date Data Arrived at EDR: 10/09/2012 Date Made Active in Reports: 12/20/2012

Number of Days to Update: 72

Source: Environmental Protection Agency

Telephone: 703-603-8704 Last EDR Contact: 07/08/2013

Next Scheduled EDR Contact: 10/21/2013 Data Release Frequency: Varies

Federal CERCLIS NFRAP site List

CERCLIS-NFRAP: CERCLIS No Further Remedial Action Planned

Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Date of Government Version: 04/26/2013 Date Data Arrived at EDR: 05/29/2013 Date Made Active in Reports: 08/09/2013

Number of Days to Update: 72

Source: EPA Telephone: 703-412

Telephone: 703-412-9810 Last EDR Contact: 05/29/2013

Next Scheduled EDR Contact: 05/09/2013
Data Release Frequency: Quarterly

Federal RCRA CORRACTS facilities list

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 02/12/2013 Date Data Arrived at EDR: 02/21/2013 Date Made Active in Reports: 02/27/2013

Number of Days to Update: 6

Source: EPA

Telephone: 800-424-9346 Last EDR Contact: 08/08/2013

Next Scheduled EDR Contact: 10/14/2013 Data Release Frequency: Quarterly

Federal RCRA non-CORRACTS TSD facilities list

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 06/18/2013 Date Data Arrived at EDR: 07/01/2013 Date Made Active in Reports: 08/09/2013 Number of Days to Update: 39

Source: Environmental Protection Agency Telephone: (212) 637-3660 Last EDR Contact: 08/08/2013

Next Scheduled EDR Contact: 10/14/2013 Data Release Frequency: Quarterly

Federal RCRA generators list

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 06/18/2013 Date Data Arrived at EDR: 07/01/2013 Date Made Active in Reports: 08/09/2013

Number of Days to Update: 39

Source: Environmental Protection Agency

Telephone: (212) 637-3660 Last EDR Contact: 08/08/2013

Next Scheduled EDR Contact: 10/14/2013 Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 06/18/2013 Date Data Arrived at EDR: 07/01/2013 Date Made Active in Reports: 08/09/2013 Number of Days to Update: 39

Source: Environmental Protection Agency Telephone: (212) 637-3660

Last EDR Contact: 08/08/2013

Next Scheduled EDR Contact: 10/14/2013 Data Release Frequency: Quarterly

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 06/18/2013 Date Data Arrived at EDR: 07/01/2013 Date Made Active in Reports: 08/09/2013

Number of Days to Update: 39

Source: Environmental Protection Agency Telephone: (212) 637-3660

Last EDR Contact: 08/08/2013

Next Scheduled EDR Contact: 10/14/2013 Data Release Frequency: Varies

Federal institutional controls / engineering controls registries

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 03/14/2013 Date Data Arrived at EDR: 03/29/2013 Date Made Active in Reports: 05/10/2013

Number of Days to Update: 42

Source: Environmental Protection Agency

Telephone: 703-603-0695 Last EDR Contact: 06/10/2013

Next Scheduled EDR Contact: 09/23/2013 Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 03/14/2013 Date Data Arrived at EDR: 03/29/2013 Date Made Active in Reports: 05/10/2013

Number of Days to Update: 42

Source: Environmental Protection Agency

Telephone: 703-603-0695 Last EDR Contact: 06/10/2013

Next Scheduled EDR Contact: 09/23/2013 Data Release Frequency: Varies

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 12/09/2005 Date Data Arrived at EDR: 12/11/2006 Date Made Active in Reports: 01/11/2007

Number of Days to Update: 31

Source: Department of the Navy Telephone: 843-820-7326 Last EDR Contact: 05/20/2013

Next Scheduled EDR Contact: 09/02/2013
Data Release Frequency: Varies

Federal ERNS list

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 12/31/2012 Date Data Arrived at EDR: 01/17/2013 Date Made Active in Reports: 02/15/2013

Number of Days to Update: 29

Source: National Response Center, United States Coast Guard

Telephone: 202-267-2180 Last EDR Contact: 07/01/2013

Next Scheduled EDR Contact: 10/14/2013 Data Release Frequency: Annually

State- and tribal - equivalent CERCLIS

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Referred to as the State Superfund Program, the Inactive Hazardous Waste Disposal Site Remedial Program is the cleanup program for inactive hazardous waste sites and now includes hazardous substance sites

Date of Government Version: 05/21/2013 Date Data Arrived at EDR: 05/23/2013 Date Made Active in Reports: 07/10/2013

Number of Days to Update: 48

Source: Department of Environmental Conservation

Telephone: 518-402-9622 Last EDR Contact: 05/23/2013

Next Scheduled EDR Contact: 09/02/2013 Data Release Frequency: Annually

VAPOR REOPENED: Vapor Intrustion Legacy Site List

New York is currently re-evaluating previous assumptions and decisions regarding the potential for soil vapor intrusion exposures at sites. As a result, all past, current, and future contaminated sites will be evaluated to determine whether these sites have the potential for exposures related to soil vapor intrusion.

Date of Government Version: 01/01/2013 Date Data Arrived at EDR: 02/20/2013 Date Made Active in Reports: 03/15/2013

Number of Days to Update: 23

Source: Department of Environmenal Conservation

Telephone: 518-402-9814 Last EDR Contact: 05/24/2013

Next Scheduled EDR Contact: 09/02/2013 Data Release Frequency: Varies

State and tribal landfill and/or solid waste disposal site lists

SWF/LF: Facility Register

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 04/22/2013 Date Data Arrived at EDR: 04/23/2013 Date Made Active in Reports: 07/10/2013

Number of Days to Update: 78

Source: Department of Environmental Conservation

Telephone: 518-457-2051 Last EDR Contact: 07/03/2013

Next Scheduled EDR Contact: 10/21/2013 Data Release Frequency: Semi-Annually

State and tribal leaking storage tank lists

LTANKS: Spills Information Database

Leaking Storage Tank Incident Reports. These records contain an inventory of reported leaking storage tank incidents reported from 4/1/86 through the most recent update. They can be either leaking underground storage tanks or leaking aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills.

Date of Government Version: 05/21/2013 Date Data Arrived at EDR: 05/23/2013 Date Made Active in Reports: 07/10/2013

Number of Days to Update: 48

Source: Department of Environmental Conservation

Telephone: 518-402-9549 Last EDR Contact: 05/23/2013

Next Scheduled EDR Contact: 09/02/2013 Data Release Frequency: Varies

HIST LTANKS: Listing of Leaking Storage Tanks

A listing of leaking underground and aboveground storage tanks. The causes of the incidents are tank test failures, tank failures or tank overfills. In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY LTANKS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002 Date Data Arrived at EDR: 07/08/2005 Date Made Active in Reports: 07/14/2005

Number of Days to Update: 6

Source: Department of Environmental Conservation

Telephone: 518-402-9549 Last EDR Contact: 07/07/2005 Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 02/05/2013 Date Data Arrived at EDR: 02/06/2013 Date Made Active in Reports: 04/12/2013

Number of Days to Update: 65

Source: EPA Region 10 Telephone: 206-553-2857 Last EDR Contact: 07/24/2013

Next Scheduled EDR Contact: 11/11/2013 Data Release Frequency: Quarterly

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 08/27/2012 Date Data Arrived at EDR: 08/28/2012 Date Made Active in Reports: 10/16/2012

Number of Days to Update: 49

Source: EPA Region 8 Telephone: 303-312-6271 Last EDR Contact: 07/24/2013

Next Scheduled EDR Contact: 11/11/2013 Data Release Frequency: Quarterly

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in New Mexico and Oklahoma.

LOSTS OF ITICIAIT IATIC IT NEW MEXICO AND ONATION

Date of Government Version: 09/12/2011
Date Data Arrived at EDR: 09/13/2011
Date Made Active in Reports: 11/11/2011

Number of Days to Update: 59

Source: EPA Region 6 Telephone: 214-665-6597 Last EDR Contact: 07/24/2013

Next Scheduled EDR Contact: 11/11/2013 Data Release Frequency: Varies

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 12/31/2012 Date Data Arrived at EDR: 02/28/2013 Date Made Active in Reports: 04/12/2013

Number of Days to Update: 43

Source: EPA Region 7 Telephone: 913-551-7003 Last EDR Contact: 07/24/2013

Next Scheduled EDR Contact: 11/11/2013 Data Release Frequency: Varies

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 09/28/2012 Date Data Arrived at EDR: 11/01/2012 Date Made Active in Reports: 04/12/2013 Number of Days to Update: 162 Source: EPA Region 1 Telephone: 617-918-1313 Last EDR Contact: 08/02/2013

Next Scheduled EDR Contact: 11/11/2013 Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 02/06/2013 Date Data Arrived at EDR: 02/08/2013 Date Made Active in Reports: 04/12/2013

Number of Days to Update: 63

Source: EPA Region 4 Telephone: 404-562-8677 Last EDR Contact: 07/24/2013

Next Scheduled EDR Contact: 11/11/2013 Data Release Frequency: Semi-Annually

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 03/01/2013 Date Data Arrived at EDR: 03/01/2013 Date Made Active in Reports: 04/12/2013

Number of Days to Update: 42

Source: Environmental Protection Agency

Telephone: 415-972-3372 Last EDR Contact: 07/24/2013

Next Scheduled EDR Contact: 11/11/2013
Data Release Frequency: Quarterly

State and tribal registered storage tank lists

TANKS: Storage Tank Faciliy Listing

This database contains records of facilities that are or have been regulated under Bulk Storage Program. Tank information for these facilities may not be releasable by the state agency.

Date of Government Version: 04/02/2013 Date Data Arrived at EDR: 04/03/2013 Date Made Active in Reports: 05/03/2013

Number of Days to Update: 30

Source: Department of Environmental Conservation

Telephone: 518-402-9543 Last EDR Contact: 08/08/2013

Next Scheduled EDR Contact: 07/15/2013 Data Release Frequency: Quarterly

UST: Petroleum Bulk Storage (PBS) Database

Facilities that have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons.

Date of Government Version: 04/02/2013 Date Data Arrived at EDR: 04/03/2013 Date Made Active in Reports: 05/03/2013

Number of Days to Update: 30

Source: Department of Environmental Conservation

Telephone: 518-402-9549 Last EDR Contact: 08/08/2013

Next Scheduled EDR Contact: 07/15/2013
Data Release Frequency: No Update Planned

CBS UST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in underground tanks of any size

Date of Government Version: 01/01/2002 Date Data Arrived at EDR: 02/20/2002 Date Made Active in Reports: 03/22/2002

Number of Days to Update: 30

Source: NYSDEC Telephone: 518-402-9549 Last EDR Contact: 10/24/2005

Next Scheduled EDR Contact: 01/23/2006 Data Release Frequency: No Update Planned

MOSF UST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or

greater.

Date of Government Version: 01/01/2002 Date Data Arrived at EDR: 02/20/2002 Date Made Active in Reports: 03/22/2002

Number of Days to Update: 30

Source: NYSDEC Telephone: 518-402-9549 Last EDR Contact: 07/25/2005

Next Scheduled EDR Contact: 10/24/2005 Data Release Frequency: Varies

AST: Petroleum Bulk Storage

Registered Aboveground Storage Tanks.

Date of Government Version: 04/02/2013 Date Data Arrived at EDR: 04/03/2013 Date Made Active in Reports: 05/03/2013

Number of Days to Update: 30

Source: Department of Environmental Conservation

Telephone: 518-402-9549 Last EDR Contact: 08/08/2013

Next Scheduled EDR Contact: 07/15/2013 Data Release Frequency: No Update Planned

CBS AST: Chemical Bulk Storage Database

Facilities that store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size.

Date of Government Version: 01/01/2002 Date Data Arrived at EDR: 02/20/2002 Date Made Active in Reports: 03/22/2002

Number of Days to Update: 30

Source: NYSDEC Telephone: 518-402-9549 Last EDR Contact: 07/25/2005

Next Scheduled EDR Contact: 10/24/2005 Data Release Frequency: No Update Planned

MOSF AST: Major Oil Storage Facilities Database

Facilities that may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 01/01/2002 Date Data Arrived at EDR: 02/20/2002 Date Made Active in Reports: 03/22/2002

Number of Days to Update: 30

Source: NYSDEC Telephone: 518-402-9549 Last EDR Contact: 07/25/2005

Next Scheduled EDR Contact: 10/24/2005 Data Release Frequency: No Update Planned

CBS: Chemical Bulk Storage Site Listing

These facilities store regulated hazardous substances in aboveground tanks with capacities of 185 gallons or greater, and/or in underground tanks of any size

Date of Government Version: 04/02/2013 Date Data Arrived at EDR: 04/03/2013 Date Made Active in Reports: 05/03/2013

Number of Days to Update: 30

Source: Department of Environmental Conservation

Telephone: 518-402-9549 Last EDR Contact: 08/08/2013

Next Scheduled EDR Contact: 07/15/2013 Data Release Frequency: Quarterly

MOSF: Major Oil Storage Facility Site Listing

These facilities may be onshore facilities or vessels, with petroleum storage capacities of 400,000 gallons or greater.

Date of Government Version: 04/02/2013 Date Data Arrived at EDR: 04/03/2013 Date Made Active in Reports: 05/03/2013

Number of Days to Update: 30

Source: Department of Environmental Conservation

Telephone: 518-402-9549 Last EDR Contact: 08/08/2013

Next Scheduled EDR Contact: 07/15/2013
Data Release Frequency: Quarterly

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 02/06/2013 Date Data Arrived at EDR: 02/08/2013 Date Made Active in Reports: 04/12/2013

Number of Days to Update: 63

Source: EPA Region 4 Telephone: 404-562-9424 Last EDR Contact: 07/24/2013

Next Scheduled EDR Contact: 11/11/2013 Data Release Frequency: Semi-Annually

INDIAN UST R1: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 09/28/2012 Date Data Arrived at EDR: 11/07/2012 Date Made Active in Reports: 04/12/2013

Number of Days to Update: 156

Source: EPA, Region 1 Telephone: 617-918-1313 Last EDR Contact: 08/02/2013

Next Scheduled EDR Contact: 11/11/2013 Data Release Frequency: Varies

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 08/02/2012 Date Data Arrived at EDR: 08/03/2012 Date Made Active in Reports: 11/05/2012

Number of Days to Update: 94

Source: EPA Region 5 Telephone: 312-886-6136 Last EDR Contact: 07/24/2013

Next Scheduled EDR Contact: 11/11/2013 Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 05/10/2011 Date Data Arrived at EDR: 05/11/2011 Date Made Active in Reports: 06/14/2011

Number of Days to Update: 34

Source: EPA Region 6 Telephone: 214-665-7591 Last EDR Contact: 07/24/2013

Next Scheduled EDR Contact: 11/11/2013 Data Release Frequency: Semi-Annually

INDIAN UST R7: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 12/31/2012 Date Data Arrived at EDR: 02/28/2013 Date Made Active in Reports: 04/12/2013

Number of Days to Update: 43

Source: EPA Region 7 Telephone: 913-551-7003 Last EDR Contact: 07/24/2013

Next Scheduled EDR Contact: 11/11/2013 Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 08/27/2012 Date Data Arrived at EDR: 08/28/2012 Date Made Active in Reports: 10/16/2012

Number of Days to Update: 49

Source: EPA Region 8 Telephone: 303-312-6137 Last EDR Contact: 07/24/2013

Next Scheduled EDR Contact: 11/11/2013
Data Release Frequency: Quarterly

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 02/05/2013 Date Data Arrived at EDR: 02/06/2013 Date Made Active in Reports: 04/12/2013

Number of Days to Update: 65

Source: EPA Region 10 Telephone: 206-553-2857 Last EDR Contact: 07/24/2013

Next Scheduled EDR Contact: 11/11/2013 Data Release Frequency: Quarterly

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 02/21/2013 Date Data Arrived at EDR: 02/26/2013 Date Made Active in Reports: 04/12/2013

Number of Days to Update: 45

Source: EPA Region 9 Telephone: 415-972-3368 Last EDR Contact: 07/24/2013

Next Scheduled EDR Contact: 11/11/2013 Data Release Frequency: Quarterly

FEMA UST: Underground Storage Tank Listing

A listing of all FEMA owned underground storage tanks.

Date of Government Version: 01/01/2010 Date Data Arrived at EDR: 02/16/2010 Date Made Active in Reports: 04/12/2010

Number of Days to Update: 55

Source: FEMA

Telephone: 202-646-5797 Last EDR Contact: 07/19/2013

Next Scheduled EDR Contact: 10/28/2013 Data Release Frequency: Varies

State and tribal institutional control / engineering control registries

ENG CONTROLS: Registry of Engineering Controls

Environmental Remediation sites that have engineering controls in place.

Date of Government Version: 05/21/2013 Date Data Arrived at EDR: 05/23/2013 Date Made Active in Reports: 07/10/2013

Number of Days to Update: 48

Source: Department of Environmental Conservation

Telephone: 518-402-9553 Last EDR Contact: 05/23/2013

Next Scheduled EDR Contact: 09/02/2013 Data Release Frequency: Quarterly

INST CONTROL: Registry of Institutional Controls

Environmental Remediation sites that have institutional controls in place.

Date of Government Version: 05/21/2013 Date Data Arrived at EDR: 05/23/2013 Date Made Active in Reports: 07/10/2013

Number of Days to Update: 48

Source: Department of Environmental Conservation

Telephone: 518-402-9553 Last EDR Contact: 05/23/2013

Next Scheduled EDR Contact: 09/02/2013 Data Release Frequency: Quarterly

RES DECL: Restrictive Declarations Listing

A restrictive declaration is a covenant running with the land which binds the present and future owners of the property. As a condition of certain special permits, the City Planning Commission may require an applicant to sign and record a restrictive declaration that places specified conditions on the future use and development of the property. Certain restrictive declarations are indicated by a D on zoning maps.

Date of Government Version: 11/18/2010 Date Data Arrived at EDR: 12/23/2010 Date Made Active in Reports: 02/11/2011

Number of Days to Update: 50

Source: NYC Department of City Planning

Telephone: 212-720-3401 Last EDR Contact: 06/28/2013

Next Scheduled EDR Contact: 10/07/2013

Data Release Frequency: No Update Planned

State and tribal voluntary cleanup sites

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008 Date Data Arrived at EDR: 04/22/2008 Date Made Active in Reports: 05/19/2008

Number of Days to Update: 27

Source: EPA, Region 7 Telephone: 913-551-7365 Last EDR Contact: 04/20/2009

Next Scheduled EDR Contact: 07/20/2009

Data Release Frequency: Varies

INDIAN VCP R1: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 09/28/2012 Date Data Arrived at EDR: 10/02/2012 Date Made Active in Reports: 10/16/2012

Number of Days to Update: 14

Source: EPA, Region 1 Telephone: 617-918-1102 Last EDR Contact: 07/02/2013

Next Scheduled EDR Contact: 10/14/2013 Data Release Frequency: Varies

VCP: Voluntary Cleanup Agreements

New York established its Voluntary Cleanup Program (VCP) to address the environmental, legal and financial barriers that often hinder the redevelopment and reuse of contaminated properties. The Voluntary Cleanup Program was developed to enhance private sector cleanup of brownfields by enabling parties to remediate sites using private rather than public funds and to reduce the development pressures on "greenfield" sites.

Date of Government Version: 05/21/2013 Date Data Arrived at EDR: 05/23/2013 Date Made Active in Reports: 07/10/2013

Number of Days to Update: 48

Source: Department of Environmental Conservation

Telephone: 518-402-9711 Last EDR Contact: 05/23/2013

Next Scheduled EDR Contact: 09/02/2013 Data Release Frequency: Semi-Annually

State and tribal Brownfields sites

ERP: Environmental Restoration Program Listing

In an effort to spur the cleanup and redevelopment of brownfields, New Yorkers approved a \$200 million Environmental Restoration or Brownfields Fund as part of the \$1.75 billion Clean Water/Clean Air Bond Act of 1996 (1996 Bond Act). Enhancements to the program were enacted on October 7, 2003. Under the Environmental Restoration Program, the State provides grants to municipalities to reimburse up to 90 percent of on-site eligible costs and 100% of off-site eligible costs for site investigation and remediation activities. Once remediated, the property may then be reused for commercial, industrial, residential or public use.

Date of Government Version: 05/21/2013 Date Data Arrived at EDR: 05/23/2013 Date Made Active in Reports: 07/10/2013

Number of Days to Update: 48

Source: Department of Environmental Conservation

Telephone: 518-402-9622 Last EDR Contact: 05/23/2013

Next Scheduled EDR Contact: 09/02/2013 Data Release Frequency: Quarterly

BROWNFIELDS: Brownfields Site List

A Brownfield is any real property where redevelopment or re-use may be complicated by the presence or potential presence of a hazardous waste, petroleum, pollutant, or contaminant.

Date of Government Version: 05/21/2013
Date Data Arrived at EDR: 05/23/2013
Date Made Active in Reports: 07/10/2013

Number of Days to Update: 48

Source: Department of Environmental Conservation

Telephone: 518-402-9764 Last EDR Contact: 05/23/2013

Next Scheduled EDR Contact: 09/02/2013 Data Release Frequency: Semi-Annually

ADDITIONAL ENVIRONMENTAL RECORDS

Local Brownfield lists

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 06/24/2013 Date Data Arrived at EDR: 06/25/2013 Date Made Active in Reports: 08/09/2013

Number of Days to Update: 45

Source: Environmental Protection Agency

Telephone: 202-566-2777 Last EDR Contact: 08/05/2013

Next Scheduled EDR Contact: 10/07/2013 Data Release Frequency: Semi-Annually

Local Lists of Landfill / Solid Waste Disposal Sites

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985 Date Data Arrived at EDR: 08/09/2004 Date Made Active in Reports: 09/17/2004

Number of Days to Update: 39

Source: Environmental Protection Agency

Telephone: 800-424-9346 Last EDR Contact: 06/09/2004 Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009 Date Data Arrived at EDR: 05/07/2009 Date Made Active in Reports: 09/21/2009

Number of Days to Update: 137

Source: EPA, Region 9 Telephone: 415-947-4219 Last EDR Contact: 07/26/2013

Next Scheduled EDR Contact: 11/11/2013
Data Release Frequency: No Update Planned

SWRCY: Registered Recycling Facility List A listing of recycling facilities.

Date of Government Version: 04/22/2013 Date Data Arrived at EDR: 04/23/2013 Date Made Active in Reports: 07/10/2013

Number of Days to Update: 78

Source: Department of Environmental Conservation

Telephone: 518-402-8705 Last EDR Contact: 07/03/2013

Next Scheduled EDR Contact: 10/21/2013 Data Release Frequency: Semi-Annually

SWTIRE: Registered Waste Tire Storage & Facility List A listing of facilities registered to accept waste tires.

Date of Government Version: 08/01/2006 Date Data Arrived at EDR: 11/15/2006 Date Made Active in Reports: 11/30/2006

Number of Days to Update: 15

Source: Department of Environmental Conservation

Telephone: 518-402-8694 Last EDR Contact: 07/26/2013

Next Scheduled EDR Contact: 11/04/2013 Data Release Frequency: Annually

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands

Location of open dumps on Indian land.

Date of Government Version: 12/31/1998 Date Data Arrived at EDR: 12/03/2007 Date Made Active in Reports: 01/24/2008

Number of Days to Update: 52

Source: Environmental Protection Agency

Telephone: 703-308-8245 Last EDR Contact: 07/31/2013

Next Scheduled EDR Contact: 11/18/2013 Data Release Frequency: Varies

Local Lists of Hazardous waste / Contaminated Sites

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 03/04/2013 Date Data Arrived at EDR: 03/12/2013 Date Made Active in Reports: 05/10/2013

Number of Days to Update: 59

Source: Drug Enforcement Administration

Telephone: 202-307-1000 Last EDR Contact: 06/03/2013

Next Scheduled EDR Contact: 09/16/2013 Data Release Frequency: Quarterly

DEL SHWS: Delisted Registry Sites

A database listing of sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites.

Date of Government Version: 05/21/2013 Date Data Arrived at EDR: 05/23/2013 Date Made Active in Reports: 07/10/2013

Number of Days to Update: 48

Source: Department of Environmental Conservation

Telephone: 518-402-9622 Last EDR Contact: 05/23/2013

Next Scheduled EDR Contact: 09/02/2013 Data Release Frequency: Annually

US HIST CDL: National Clandestine Laboratory Register

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 09/01/2007 Date Data Arrived at EDR: 11/19/2008 Date Made Active in Reports: 03/30/2009

Number of Days to Update: 131

Source: Drug Enforcement Administration

Telephone: 202-307-1000 Last EDR Contact: 03/23/2009

Next Scheduled EDR Contact: 06/22/2009 Data Release Frequency: No Update Planned

Local Lists of Registered Storage Tanks

HIST UST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capacities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. It is no longer updated due to the sensitive nature of the information involved. See UST for more current data.

Date of Government Version: 01/01/2002 Date Data Arrived at EDR: 06/02/2006 Date Made Active in Reports: 07/20/2006

Number of Days to Update: 48

Source: Department of Environmental Conservation

Telephone: 518-402-9549 Last EDR Contact: 10/23/2006

Next Scheduled EDR Contact: 01/22/2007 Data Release Frequency: Varies

HIST AST: Historical Petroleum Bulk Storage Database

These facilities have petroleum storage capabilities in excess of 1,100 gallons and less than 400,000 gallons. This database contains detailed information per site. No longer updated due to the sensitive nature of the information involved. See AST for more current data.

Date of Government Version: 01/01/2002 Date Data Arrived at EDR: 06/02/2006 Date Made Active in Reports: 07/20/2006

Number of Days to Update: 48

Source: Department of Environmental Conservation

Telephone: 518-402-9549 Last EDR Contact: 10/23/2006

Next Scheduled EDR Contact: 01/22/2007 Data Release Frequency: No Update Planned

Local Land Records

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 02/06/2013 Date Data Arrived at EDR: 04/25/2013 Date Made Active in Reports: 05/10/2013

Number of Days to Update: 15

Source: Environmental Protection Agency

Telephone: 202-564-6023 Last EDR Contact: 07/24/2013

Next Scheduled EDR Contact: 11/11/2013 Data Release Frequency: Varies

LIENS: Spill Liens Information

Lien information from the Oil Spill Fund.

Date of Government Version: 05/21/2013 Date Data Arrived at EDR: 05/23/2013 Date Made Active in Reports: 07/10/2013

Number of Days to Update: 48

Source: Office of the State Comptroller

Telephone: 518-474-9034 Last EDR Contact: 08/09/2013

Next Scheduled EDR Contact: 11/25/2013 Data Release Frequency: Varies

Records of Emergency Release Reports

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 12/31/2012 Date Data Arrived at EDR: 01/03/2013 Date Made Active in Reports: 02/27/2013

Number of Days to Update: 55

Source: U.S. Department of Transportation

Telephone: 202-366-4555 Last EDR Contact: 07/01/2013

Next Scheduled EDR Contact: 10/14/2013 Data Release Frequency: Annually

SPILLS: Spills Information Database

Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 05/21/2013 Date Data Arrived at EDR: 05/23/2013 Date Made Active in Reports: 07/10/2013

Number of Days to Update: 48

Source: Department of Environmental Conservation

Telephone: 518-402-9549 Last EDR Contact: 05/23/2013

Next Scheduled EDR Contact: 09/02/2013 Data Release Frequency: Varies

HIST SPILLS: SPILLS Database

This database contains records of chemical and petroleum spill incidents. Under State law, petroleum and hazardous chemical spills that can impact the waters of the state must be reported by the spiller (and, in some cases, by anyone who has knowledge of the spills). In 2002, the Department of Environmental Conservation stopped providing updates to its original Spills Information Database. This database includes fields that are no longer available from the NYDEC as of January 1, 2002. Current information may be found in the NY SPILLS database. Department of Environmental Conservation.

Date of Government Version: 01/01/2002 Date Data Arrived at EDR: 07/08/2005 Date Made Active in Reports: 07/14/2005

Number of Days to Update: 6

Source: Department of Environmental Conservation

Telephone: 518-402-9549 Last EDR Contact: 07/07/2005 Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

SPILLS 80: SPILLS80 data from FirstSearch

Spills 80 includes those spill and release records available from FirstSearch databases prior to 1990. Typically, they may include chemical, oil and/or hazardous substance spills recorded before 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 80.

Date of Government Version: 11/02/2010 Date Data Arrived at EDR: 01/03/2013 Date Made Active in Reports: 03/07/2013

Number of Days to Update: 63

Source: FirstSearch Telephone: N/A

Last EDR Contact: 01/03/2013 Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

SPILLS 90: SPILLS90 data from FirstSearch

Spills 90 includes those spill and release records available exclusively from FirstSearch databases. Typically, they may include chemical, oil and/or hazardous substance spills recorded after 1990. Duplicate records that are already included in EDR incident and release records are not included in Spills 90.

Date of Government Version: 12/14/2012 Date Data Arrived at EDR: 01/03/2013 Date Made Active in Reports: 02/12/2013

Number of Days to Update: 40

Source: FirstSearch Telephone: N/A

Last EDR Contact: 01/03/2013 Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

Other Ascertainable Records

RCRA NonGen / NLR: RCRA - Non Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous

Date of Government Version: 06/18/2013 Date Data Arrived at EDR: 07/01/2013 Date Made Active in Reports: 08/09/2013

Number of Days to Update: 39

Source: Environmental Protection Agency

Telephone: (212) 637-3660 Last EDR Contact: 08/08/2013

Next Scheduled EDR Contact: 10/14/2013 Data Release Frequency: Varies

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 07/31/2012 Date Data Arrived at EDR: 08/07/2012 Date Made Active in Reports: 09/18/2012

Number of Days to Update: 42

Source: Department of Transporation, Office of Pipeline Safety

Telephone: 202-366-4595 Last EDR Contact: 08/05/2013

Next Scheduled EDR Contact: 11/18/2013 Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 11/10/2006 Date Made Active in Reports: 01/11/2007

Number of Days to Update: 62

Source: USGS Telephone: 888-275-8747 Last EDR Contact: 07/19/2013

Next Scheduled EDR Contact: 10/28/2013 Data Release Frequency: Semi-Annually

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 12/31/2011 Date Data Arrived at EDR: 02/26/2013 Date Made Active in Reports: 03/13/2013

Number of Days to Update: 15

Source: U.S. Army Corps of Engineers

Telephone: 202-528-4285 Last EDR Contact: 06/10/2013

Next Scheduled EDR Contact: 09/23/2013 Data Release Frequency: Varies

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 12/31/2011 Date Data Arrived at EDR: 01/15/2013 Date Made Active in Reports: 03/13/2013

Number of Days to Update: 57

Source: Department of Justice, Consent Decree Library

Telephone: Varies

Last EDR Contact: 06/25/2013

Next Scheduled EDR Contact: 10/14/2013
Data Release Frequency: Varies

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 12/18/2012 Date Data Arrived at EDR: 03/13/2013 Date Made Active in Reports: 04/12/2013

Number of Days to Update: 30

Source: EPA

Telephone: 703-416-0223 Last EDR Contact: 06/11/2013

Next Scheduled EDR Contact: 09/23/2013 Data Release Frequency: Annually

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 09/14/2010 Date Data Arrived at EDR: 10/07/2011 Date Made Active in Reports: 03/01/2012

Number of Days to Update: 146

Source: Department of Energy Telephone: 505-845-0011 Last EDR Contact: 05/28/2013

Next Scheduled EDR Contact: 09/09/2013 Data Release Frequency: Varies

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 02/05/2013 Date Data Arrived at EDR: 04/18/2013 Date Made Active in Reports: 05/10/2013

Number of Days to Update: 22

Source: Department of Labor, Mine Safety and Health Administration

Telephone: 303-231-5959 Last EDR Contact: 06/04/2013

Next Scheduled EDR Contact: 09/16/2013 Data Release Frequency: Semi-Annually

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2009 Date Data Arrived at EDR: 09/01/2011 Date Made Active in Reports: 01/10/2012

Number of Days to Update: 131

Source: EPA

Telephone: 202-566-0250 Last EDR Contact: 05/29/2013

Next Scheduled EDR Contact: 09/09/2013 Data Release Frequency: Annually

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant

site.

Date of Government Version: 12/31/2006 Date Data Arrived at EDR: 09/29/2010 Date Made Active in Reports: 12/02/2010

Number of Days to Update: 64

Source: EPA

Telephone: 202-260-5521 Last EDR Contact: 06/25/2013

Next Scheduled EDR Contact: 10/07/2013 Data Release Frequency: Every 4 Years

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009 Date Data Arrived at EDR: 04/16/2009 Date Made Active in Reports: 05/11/2009

Number of Days to Update: 25

Source: EPA/Office of Prevention, Pesticides and Toxic Substances

Telephone: 202-566-1667 Last EDR Contact: 05/28/2013

Next Scheduled EDR Contact: 09/09/2013 Data Release Frequency: Quarterly

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009 Date Data Arrived at EDR: 04/16/2009 Date Made Active in Reports: 05/11/2009

Number of Days to Update: 25

Source: EPA

Telephone: 202-566-1667 Last EDR Contact: 05/28/2013

Next Scheduled EDR Contact: 09/09/2013 Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006 Date Data Arrived at EDR: 03/01/2007 Date Made Active in Reports: 04/10/2007

Number of Days to Update: 40

Source: Environmental Protection Agency

Telephone: 202-564-2501 Last EDR Contact: 12/17/2007

Next Scheduled EDR Contact: 03/17/2008 Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006 Date Data Arrived at EDR: 03/01/2007 Date Made Active in Reports: 04/10/2007

Number of Days to Update: 40

Source: Environmental Protection Agency

Telephone: 202-564-2501 Last EDR Contact: 12/17/2008

Next Scheduled EDR Contact: 03/17/2008 Data Release Frequency: No Update Planned

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2009 Date Data Arrived at EDR: 12/10/2010 Date Made Active in Reports: 02/25/2011

Number of Days to Update: 77

Source: EPA

Telephone: 202-564-4203 Last EDR Contact: 07/24/2013

Next Scheduled EDR Contact: 11/11/2013 Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 07/20/2011 Date Data Arrived at EDR: 11/10/2011 Date Made Active in Reports: 01/10/2012

Number of Days to Update: 61

Source: Environmental Protection Agency

Telephone: 202-564-5088 Last EDR Contact: 07/01/2013

Next Scheduled EDR Contact: 10/28/2013 Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 11/01/2012 Date Data Arrived at EDR: 01/16/2013 Date Made Active in Reports: 05/10/2013

Number of Days to Update: 114

Source: EPA

Telephone: 202-566-0500 Last EDR Contact: 07/17/2013

Next Scheduled EDR Contact: 10/28/2013 Data Release Frequency: Annually

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 03/14/2013
Date Data Arrived at EDR: 03/20/2013
Date Made Active in Reports: 07/10/2013

Number of Days to Update: 112

Source: Nuclear Regulatory Commission

Telephone: 301-415-7169 Last EDR Contact: 07/10/2013

Next Scheduled EDR Contact: 09/23/2013 Data Release Frequency: Quarterly

RADINFO: Radiation Information Database

The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 04/09/2013 Date Data Arrived at EDR: 04/11/2013 Date Made Active in Reports: 05/10/2013

Number of Days to Update: 29

Source: Environmental Protection Agency

Telephone: 202-343-9775 Last EDR Contact: 07/12/2013

Next Scheduled EDR Contact: 10/21/2013 Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 03/08/2013 Date Data Arrived at EDR: 03/21/2013 Date Made Active in Reports: 07/10/2013

Number of Days to Update: 111

Source: EPA

Telephone: (212) 637-3000 Last EDR Contact: 08/02/2013

Next Scheduled EDR Contact: 09/23/2013 Data Release Frequency: Quarterly

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995 Date Data Arrived at EDR: 07/03/1995 Date Made Active in Reports: 08/07/1995

Number of Days to Update: 35

Source: EPA

Telephone: 202-564-4104 Last EDR Contact: 06/02/2008

Next Scheduled EDR Contact: 09/01/2008 Data Release Frequency: No Update Planned

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 05/08/2012 Date Data Arrived at EDR: 05/25/2012 Date Made Active in Reports: 07/10/2012

Number of Days to Update: 46

Source: Environmental Protection Agency

Telephone: 202-564-8600 Last EDR Contact: 07/24/2013

Next Scheduled EDR Contact: 11/11/2013 Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2011
Date Data Arrived at EDR: 02/26/2013
Date Made Active in Reports: 04/19/2013

Number of Days to Update: 52

Source: EPA/NTIS Telephone: 800-424-9346 Last EDR Contact: 05/30/2013

Next Scheduled EDR Contact: 09/09/2013 Data Release Frequency: Biennially

HSWDS: Hazardous Substance Waste Disposal Site Inventory

The list includes any known or suspected hazardous substance waste disposal sites. Also included are sites delisted from the Registry of Inactive Hazardous Waste Disposal Sites and non-Registry sites that U.S. EPA Preliminary Assessment (PA) reports or Site Investigation (SI) reports were prepared. Hazardous Substance Waste Disposal Sites are eligible to be Superfund sites now that the New York State Superfund has been refinanced and changed. This means that the study inventory has served its purpose and will no longer be maintained as a separate entity. The last version of the study inventory is frozen in time. The sites on the study will not automatically be made Superfund sites, rather each site will be further evaluated for listing on the Registry. So overtime they will be added to the registry or not.

Date of Government Version: 01/01/2003 Date Data Arrived at EDR: 10/20/2006 Date Made Active in Reports: 11/30/2006

Number of Days to Update: 41

Source: Department of Environmental Conservation

Telephone: 518-402-9564 Last EDR Contact: 05/26/2009

Next Scheduled EDR Contact: 08/24/2009 Data Release Frequency: No Update Planned

UIC: Underground Injection Control Wells

A listing of enhanced oil recovery underground injection wells.

Date of Government Version: 06/07/2013 Date Data Arrived at EDR: 06/11/2013 Date Made Active in Reports: 07/10/2013

Number of Days to Update: 29

Source: Department of Environmental Conservation

Telephone: 518-402-8056 Last EDR Contact: 06/11/2013

Next Scheduled EDR Contact: 09/23/2013 Data Release Frequency: Quarterly

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

facility.

Date of Government Version: 05/01/2013 Date Data Arrived at EDR: 05/09/2013 Date Made Active in Reports: 07/10/2013

Number of Days to Update: 62

Source: Department of Environmental Conservation

Telephone: 518-402-8651 Last EDR Contact: 08/07/2013

Next Scheduled EDR Contact: 11/18/2013 Data Release Frequency: Annually

DRYCLEANERS: Registered Drycleaners

A listing of all registered drycleaning facilities.

Date of Government Version: 04/19/2013 Date Data Arrived at EDR: 04/19/2013 Date Made Active in Reports: 05/03/2013

Number of Days to Update: 14

Source: Department of Environmental Conservation

Telephone: 518-402-8403 Last EDR Contact: 06/14/2013

Next Scheduled EDR Contact: 09/30/2013

Data Release Frequency: Varies

SPDES: State Pollutant Discharge Elimination System

New York State has a state program which has been approved by the United States Environmental Protection Agency for the control of wastewater and stormwater discharges in accordance with the Clean Water Act. Under New York State law the program is known as the State Pollutant Discharge Elimination System (SPDES) and is broader in scope than that required by the Clean Water Act in that it controls point source discharges to groundwaters as well as surface waters.

Date of Government Version: 05/01/2013 Date Data Arrived at EDR: 05/02/2013 Date Made Active in Reports: 07/10/2013

Number of Days to Update: 69

Source: Department of Environmental Conservation

Telephone: 518-402-8233 Last EDR Contact: 07/15/2013

Next Scheduled EDR Contact: 10/28/2013 Data Release Frequency: No Update Planned

AIRS: Air Emissions Data

Point source emissions inventory data.

Date of Government Version: 12/31/2011 Date Data Arrived at EDR: 08/02/2012 Date Made Active in Reports: 10/03/2012

Number of Days to Update: 62

Source: Department of Environmental Conservation

Telephone: 518-402-8452 Last EDR Contact: 07/24/2013

Next Scheduled EDR Contact: 11/11/2013
Data Release Frequency: Annually

E DESIGNATION: E DESIGNATION SITE LISTING

The (E (Environmental)) designation would ensure that sampling and remediation take place on the subject properties, and would avoid any significant impacts related to hazardous materials at these locations. The (E) designations would require that the fee owner of the sites conduct a testing and sampling protocol, and remediation where appropriate, to the satisfaction of the NYCDEP before the issuance of a building permit by the Department of Buildings pursuant to the provisions of Section 11-15 of the Zoning Resolution (Environmental Requirements). The (E) designations also include a mandatory construction-related health and safety plan which must be approved by NYCDEP.

Date of Government Version: 06/17/2013 Date Data Arrived at EDR: 06/24/2013 Date Made Active in Reports: 07/10/2013

Number of Days to Update: 16

Source: New York City Department of City Planning

Telephone: 718-595-6658 Last EDR Contact: 06/21/2013

Next Scheduled EDR Contact: 10/07/2013

Data Release Frequency: Varies

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 12/08/2006 Date Made Active in Reports: 01/11/2007

Number of Days to Update: 34

Source: USGS Telephone: 202-208-3710 Last EDR Contact: 07/19/2013

Next Scheduled EDR Contact: 10/28/2013 Data Release Frequency: Semi-Annually

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing

The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 03/07/2011 Date Data Arrived at EDR: 03/09/2011 Date Made Active in Reports: 05/02/2011

Number of Days to Update: 54

Source: Environmental Protection Agency

Telephone: 615-532-8599 Last EDR Contact: 08/01/2013

Next Scheduled EDR Contact: 11/04/2013 Data Release Frequency: Varies

US AIRS MINOR: Air Facility System Data A listing of minor source facilities.

Date of Government Version: 01/23/2013 Date Data Arrived at EDR: 01/30/2013 Date Made Active in Reports: 05/10/2013

Number of Days to Update: 100

Source: EPA

Telephone: 202-564-5962 Last EDR Contact: 06/25/2013

Next Scheduled EDR Contact: 10/14/2013 Data Release Frequency: Annually

FEDLAND: Federal and Indian Lands

Federally and Indian administrated lands of the United States. Lands included are administrated by: Army Corps of Engineers, Bureau of Reclamation, National Wild and Scenic River, National Wildlife Refuge, Public Domain Land, Wilderness, Wilderness Study Area, Wildlife Management Area, Bureau of Indian Affairs, Bureau of Land Management, Department of Justice, Forest Service, Fish and Wildlife Service, National Park Service.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 02/06/2006 Date Made Active in Reports: 01/11/2007

Number of Days to Update: 339

Source: U.S. Geological Survey Telephone: 888-275-8747 Last EDR Contact: 07/19/2013

Next Scheduled EDR Contact: 10/28/2013

Data Release Frequency: N/A

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 12/31/2012 Date Data Arrived at EDR: 02/18/2013 Date Made Active in Reports: 05/10/2013

Number of Days to Update: 81

Source: Environmental Protection Agency

Telephone: 617-520-3000 Last EDR Contact: 08/07/2013

Next Scheduled EDR Contact: 11/25/2013 Data Release Frequency: Quarterly

US FIN ASSUR: Financial Assurance Information

All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 03/04/2013 Date Data Arrived at EDR: 03/15/2013 Date Made Active in Reports: 05/10/2013

Number of Days to Update: 56

Source: Environmental Protection Agency

Telephone: 202-566-1917 Last EDR Contact: 05/20/2013

Next Scheduled EDR Contact: 09/02/2013 Data Release Frequency: Quarterly

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 11/11/2011 Date Data Arrived at EDR: 05/18/2012 Date Made Active in Reports: 05/25/2012

Number of Days to Update: 7

Source: Environmental Protection Agency

Telephone: 703-308-4044 Last EDR Contact: 05/17/2013

Next Scheduled EDR Contact: 08/26/2013 Data Release Frequency: Varies

COAL ASH: Coal Ash Disposal Site Listing
A listing of coal ash disposal site locations.

Date of Government Version: 04/22/2013 Date Data Arrived at EDR: 04/23/2013 Date Made Active in Reports: 07/10/2013

Number of Days to Update: 78

Source: Department of Environmental Conservation

Telephone: 518-402-8660 Last EDR Contact: 07/03/2013

Next Scheduled EDR Contact: 10/21/2013 Data Release Frequency: Varies

COAL ASH DOE: Sleam-Electric Plan Operation Data

A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 08/07/2009 Date Made Active in Reports: 10/22/2009

Number of Days to Update: 76

Source: Department of Energy Telephone: 202-586-8719 Last EDR Contact: 07/19/2013

Next Scheduled EDR Contact: 10/28/2013 Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List

A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 08/17/2010 Date Data Arrived at EDR: 01/03/2011 Date Made Active in Reports: 03/21/2011

Number of Days to Update: 77

Source: Environmental Protection Agency

Telephone: N/A

Last EDR Contact: 06/14/2013

Next Scheduled EDR Contact: 09/23/2013 Data Release Frequency: Varies

Financial Assurance 2: Financial Assurance Information Listing

A listing of financial assurance information for hazardous waste facilities. Financial assurance is intended to ensure that resources are available to pay for the cost of closure, post-closure care, and corrective measures if the owner or operator of a regulated facility is unable or unwilling to pay.

Date of Government Version: 10/31/2008 Date Data Arrived at EDR: 11/25/2008 Date Made Active in Reports: 12/11/2008

Number of Days to Update: 16

Source: Department of Environmental Conservation

Telephone: 518-402-8712 Last EDR Contact: 07/03/2013

Next Scheduled EDR Contact: 10/21/2013 Data Release Frequency: Varies

Financial Assurance 1: Financial Assurance Information Listing

Financial assurance information.

Date of Government Version: 04/11/2013 Date Data Arrived at EDR: 04/11/2013 Date Made Active in Reports: 05/03/2013

Number of Days to Update: 22

Source: Department of Environmental Conservation

Telephone: 518-402-8660 Last EDR Contact: 07/03/2013

Next Scheduled EDR Contact: 10/21/2013 Data Release Frequency: Quarterly

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 01/29/2013 Date Data Arrived at EDR: 02/14/2013 Date Made Active in Reports: 02/27/2013

Number of Days to Update: 13

Source: Environmental Protection Agency

Telephone: 703-603-8787 Last EDR Contact: 07/03/2013

Next Scheduled EDR Contact: 10/21/2013 Data Release Frequency: Varies

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001 Date Data Arrived at EDR: 10/27/2010 Date Made Active in Reports: 12/02/2010

Number of Days to Update: 36

Source: American Journal of Public Health

Telephone: 703-305-6451 Last EDR Contact: 12/02/2009 Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)

The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 01/23/2013 Date Data Arrived at EDR: 01/30/2013 Date Made Active in Reports: 05/10/2013

Number of Days to Update: 100

Source: EPA

Telephone: 202-564-5962 Last EDR Contact: 06/25/2013

Next Scheduled EDR Contact: 10/14/2013 Data Release Frequency: Annually

PRP: Potentially Responsible Parties

A listing of verified Potentially Responsible Parties

Date of Government Version: 12/18/2012 Date Data Arrived at EDR: 04/04/2013 Date Made Active in Reports: 07/10/2013

Number of Days to Update: 97

Source: EPA

Telephone: 202-564-6023 Last EDR Contact: 07/03/2013

Next Scheduled EDR Contact: 10/14/2013 Data Release Frequency: Quarterly

PCB TRANSFORMER: PCB Transformer Registration Database

The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 02/01/2011 Date Data Arrived at EDR: 10/19/2011 Date Made Active in Reports: 01/10/2012

Number of Days to Update: 83

Source: Environmental Protection Agency

Telephone: 202-566-0517 Last EDR Contact: 08/02/2013

Next Scheduled EDR Contact: 11/11/2013

Data Release Frequency: Varies

EDR HIGH RISK HISTORICAL RECORDS

EDR Exclusive Records

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A Date Data Arrived at EDR: N/A Date Made Active in Reports: N/A

Number of Days to Update: N/A

Source: EDR, Inc. Telephone: N/A Last EDR Contact: N/A

Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

EDR US Hist Auto Stat: EDR Exclusive Historic Gas Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A Date Data Arrived at EDR: N/A Date Made Active in Reports: N/A

Number of Days to Update: N/A

Source: EDR, Inc. Telephone: N/A Last EDR Contact: N/A

Next Scheduled EDR Contact: N/A Data Release Frequency: Varies

EDR US Hist Cleaners: EDR Exclusive Historic Dry Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A

Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A

Next Scheduled EDR Contact: N/A Data Release Frequency: Varies

EDR US Hist Cleaners: EDR Proprietary Historic Dry Cleaners - Cole

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A

Number of Days to Update: N/A

Source: N/A Telephone: N/A Last EDR Contact: N/A

Next Scheduled EDR Contact: N/A Data Release Frequency: Varies

EDR US Hist Auto Stat: EDR Proprietary Historic Gas Stations - Cole

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A

Number of Days to Update: N/A

Source: N/A
Telephone: N/A
Last EDR Contact: N/A

Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

COUNTY RECORDS

CORTLAND COUNTY:

Cortland County Storage Tank Listing

A listing of aboveground storage tank sites located in Cortland County.

Date of Government Version: 06/03/2013 Date Data Arrived at EDR: 06/05/2013 Date Made Active in Reports: 07/10/2013

Number of Days to Update: 35

Source: Cortland County Health Department

Telephone: 607-753-5035 Last EDR Contact: 08/01/2013

Next Scheduled EDR Contact: 11/18/2013 Data Release Frequency: Quarterly

Cortland County Storage Tank Listing

A listing of underground storage tank sites located in Cortland County.

Date of Government Version: 06/03/2013 Date Data Arrived at EDR: 06/05/2013 Date Made Active in Reports: 07/10/2013

Number of Days to Update: 35

Source: Cortland County Health Department

Telephone: 607-753-5035 Last EDR Contact: 08/01/2013

Next Scheduled EDR Contact: 11/18/2013 Data Release Frequency: Quarterly

NASSAU COUNTY:

Registered Tank Database

A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 05/21/2003 Date Data Arrived at EDR: 05/27/2003 Date Made Active in Reports: 06/09/2003

Number of Days to Update: 13

Source: Nassau County Health Department

Telephone: 516-571-3314 Last EDR Contact: 07/30/2013

Next Scheduled EDR Contact: 10/21/2013
Data Release Frequency: No Update Planned

Storage Tank Database

A listing of aboveground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011 Date Data Arrived at EDR: 02/23/2011 Date Made Active in Reports: 03/29/2011

Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal

Telephone: 516-572-1000 Last EDR Contact: 08/01/2013

Next Scheduled EDR Contact: 11/18/2013 Data Release Frequency: Varies

Registered Tank Database

A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 05/21/2003 Date Data Arrived at EDR: 05/27/2003 Date Made Active in Reports: 06/09/2003

Number of Days to Update: 13

Source: Nassau County Health Department

Telephone: 516-571-3314 Last EDR Contact: 07/30/2013

Next Scheduled EDR Contact: 10/21/2013 Data Release Frequency: No Update Planned

Storage Tank Database

A listing of underground storage tank sites located in Nassau County.

Date of Government Version: 02/15/2011 Date Data Arrived at EDR: 02/23/2011 Date Made Active in Reports: 03/29/2011

Number of Days to Update: 34

Source: Nassau County Office of the Fire Marshal

Telephone: 516-572-1000 Last EDR Contact: 08/01/2013

Next Scheduled EDR Contact: 11/18/2013 Data Release Frequency: Varies

ROCKLAND COUNTY:

Petroleum Bulk Storage Database

A listing of aboveground storage tank sites located in Rockland County.

Date of Government Version: 06/24/2013 Date Data Arrived at EDR: 06/24/2013 Date Made Active in Reports: 07/10/2013

Number of Days to Update: 16

Source: Rockland County Health Department

Telephone: 914-364-2605 Last EDR Contact: 06/10/2013

Next Scheduled EDR Contact: 09/23/2013 Data Release Frequency: Quarterly

Petroleum Bulk Storage Database

A listing of underground storage tank sites located in Rockland County.

Date of Government Version: 06/24/2013 Date Data Arrived at EDR: 06/24/2013 Date Made Active in Reports: 07/10/2013

Number of Days to Update: 16

Source: Rockland County Health Department

Telephone: 914-364-2605 Last EDR Contact: 06/10/2013

Next Scheduled EDR Contact: 09/23/2013 Data Release Frequency: Quarterly

SUFFOLK COUNTY:

Storage Tank Database

A listing of aboveground storage tank sites located in Suffolk County.

Date of Government Version: 09/13/2006 Date Data Arrived at EDR: 01/11/2007 Date Made Active in Reports: 02/07/2007

Number of Days to Update: 27

Source: Suffolk County Department of Health Services

Telephone: 631-854-2521 Last EDR Contact: 08/01/2013

Next Scheduled EDR Contact: 11/18/2013 Data Release Frequency: Annually

Storage Tank Database

A listing of underground storage tank sites located in Suffolk County.

Date of Government Version: 09/13/2006 Date Data Arrived at EDR: 01/11/2007 Date Made Active in Reports: 02/07/2007

Number of Days to Update: 27

Source: Suffolk County Department of Health Services

Telephone: 631-854-2521 Last EDR Contact: 08/01/2013

Next Scheduled EDR Contact: 11/18/2013 Data Release Frequency: Annually

WESTCHESTER COUNTY:

Listing of Storage Tanks

A listing of aboveground storage tank sites located in Westchester County.

Date of Government Version: 06/06/2013 Date Data Arrived at EDR: 06/07/2013 Date Made Active in Reports: 07/10/2013

Number of Days to Update: 33

Source: Westchester County Department of Health

Telephone: 914-813-5161 Last EDR Contact: 08/01/2013

Next Scheduled EDR Contact: 11/18/2013

Data Release Frequency: Varies

Listing of Storage Tanks

A listing of underground storage tank sites located in Westchester County.

Date of Government Version: 06/06/2013 Date Data Arrived at EDR: 06/07/2013 Date Made Active in Reports: 07/10/2013

Number of Days to Update: 33

Source: Westchester County Department of Health

Telephone: 914-813-5161 Last EDR Contact: 08/01/2013

Next Scheduled EDR Contact: 11/18/2013

Data Release Frequency: Varies

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 05/20/2013 Date Data Arrived at EDR: 05/21/2013 Date Made Active in Reports: 06/27/2013

Number of Days to Update: 37

Source: Department of Energy & Environmental Protection

Telephone: 860-424-3375 Last EDR Contact: 05/21/2013

Next Scheduled EDR Contact: 09/02/2013
Data Release Frequency: Annually

NJ MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2011 Date Data Arrived at EDR: 07/19/2012 Date Made Active in Reports: 08/28/2012

Number of Days to Update: 40

Source: Department of Environmental Protection

Telephone: N/A

Last EDR Contact: 07/19/2013

Next Scheduled EDR Contact: 10/28/2013 Data Release Frequency: Annually

PA MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2011 Date Data Arrived at EDR: 07/23/2012 Date Made Active in Reports: 09/18/2012

Number of Days to Update: 57

Source: Department of Environmental Protection

Telephone: 717-783-8990 Last EDR Contact: 07/18/2013

Next Scheduled EDR Contact: 11/04/2013 Data Release Frequency: Annually

RI MANIFEST: Manifest information

Hazardous waste manifest information

Date of Government Version: 12/31/2012 Date Data Arrived at EDR: 06/21/2013 Date Made Active in Reports: 08/05/2013

Number of Days to Update: 45

Source: Department of Environmental Management

Telephone: 401-222-2797 Last EDR Contact: 05/28/2013

Next Scheduled EDR Contact: 09/09/2013 Data Release Frequency: Annually

VT MANIFEST: Hazardous Waste Manifest Data Hazardous waste manifest information.

Date of Government Version: 03/26/2013 Date Data Arrived at EDR: 05/24/2013 Date Made Active in Reports: 07/22/2013

Number of Days to Update: 59

Source: Department of Environmental Conservation

Telephone: 802-241-3443 Last EDR Contact: 07/18/2013

Next Scheduled EDR Contact: 11/04/2013 Data Release Frequency: Annually

WI MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 12/31/2011 Date Data Arrived at EDR: 07/19/2012 Date Made Active in Reports: 09/27/2012

Number of Days to Update: 70

Source: Department of Natural Resources

Telephone: N/A

Last EDR Contact: 07/17/2013

Next Scheduled EDR Contact: 09/30/2013 Data Release Frequency: Annually

Oil/Gas Pipelines: This data was obtained by EDR from the USGS in 1994. It is referred to by USGS as GeoData Digital Line Graphs from 1:100,000-Scale Maps. It was extracted from the transportation category including some oil, but primarily gas pipelines.

Electric Power Transmission Line Data Source: Rextag Strategies Corp. Telephone: (281) 769-2247

U.S. Electric Transmission and Power Plants Systems Digital GIS Data

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:

Source: American Hospital Association, Inc.

Telephone: 312-280-5991

The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing

Source: Centers for Medicare & Medicaid Services

Telephone: 410-786-3000

A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services,

a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes

Source: National Institutes of Health

Telephone: 301-594-6248

Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools

Source: National Center for Education Statistics

Telephone: 202-502-7300

The National Center for Education Statistics' primary database on elementary

and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are

comparable across all states. Private Schools

Source: National Center for Education Statistics

Telephone: 202-502-7300

The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Providers Source: Department of Health Telephone: 212-676-2444

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 2003 & 2011 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 and 2005 from the U.S. Fish and Wildlife Service.

State Wetlands Data: Freshwater Wetlands Source: Department of Environmental Conservation

Telephone: 518-402-8961

Scanned Digital USGS 7.5' Topographic Map (DRG)

Source: United States Geologic Survey

A digital raster graphic (DRG) is a scanned image of a U.S. Geological Survey topographic map. The map images are made by scanning published paper maps on high-resolution scanners. The raster image is georeferenced and fit to the Universal Transverse Mercator (UTM) projection.

STREET AND ADDRESS INFORMATION

© 2010 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.

12.6 Historical Research Documentation (Fire Insurance Maps, City Directory Information, Aerial Photographs, etc)		

54 George Street

54 George Street Babylon, NY 11702

Inquiry Number: 4833900.1

January 23, 2017

The EDR-City Directory Image Report



TABLE OF CONTENTS

SECTION

Executive Summary

Findings

City Directory Images

Thank you for your business.Please contact EDR at 1-800-352-0050 with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING. WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction orforecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2016 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

DESCRIPTION

Environmental Data Resources, Inc.'s (EDR) City Directory Report is a screening tool designed to assist environmental professionals in evaluating potential liability on a target property resulting from past activities. EDR's City Directory Report includes a search of available city directory data at 5 year intervals.

RESEARCH SUMMARY

The following research sources were consulted in the preparation of this report. A check mark indicates where information was identified in the source and provided in this report.

<u>Year</u>	Target Street	Cross Street	<u>Source</u>
2013	$\overline{\checkmark}$	$\overline{\checkmark}$	Cole Information Services
2008	$\overline{\checkmark}$	$\overline{\checkmark}$	Cole Information Services
2003	$\overline{\checkmark}$	$\overline{\checkmark}$	Cole Information Services
1999	$\overline{\checkmark}$	$\overline{\checkmark}$	Cole Information Services
1995	$\overline{\checkmark}$	$\overline{\checkmark}$	Cole Information Services
1992	$\overline{\checkmark}$	$\overline{\checkmark}$	Cole Information Services
1970	$\overline{\checkmark}$	$\overline{\checkmark}$	Cole Criss-Cross Directory

RECORD SOURCES

EDR is licensed to reproduce certain City Directory works by the copyright holders of those works. The purchaser of this EDR City Directory Report may include it in report(s) delivered to a customer. Reproduction of City Directories without permission of the publisher or licensed vendor may be a violation of copyright.

FINDINGS

TARGET PROPERTY STREET

54 George Street Babylon, NY 11702

<u>Year</u>	<u>CD Image</u>	<u>Source</u>
GEORGE ST		
2013	pg A1	Cole Information Services
2008	pg A3	Cole Information Services
2003	pg A5	Cole Information Services
1999	pg A7	Cole Information Services
1995	pg A9	Cole Information Services
1992	pg A11	Cole Information Services
1970	pg A13	Cole Criss-Cross Directory

4833900-1 Page 2

FINDINGS

CROSS STREETS

<u>Year</u>	<u>CD Image</u>	<u>Source</u>
JAMES ST		
2013	pg. A2	Cole Information Services
2008	pg. A4	Cole Information Services
2003	pg. A6	Cole Information Services
1999	pg. A8	Cole Information Services
1995	pg. A10	Cole Information Services
1992	pg. A12	Cole Information Services
1970	pg. A14	Cole Criss-Cross Directory

4833900-1 Page 3



<u>Target Street</u> <u>Cross Street</u> <u>Source</u>

✓ - Cole Information Services

16	INTER COUNTY MOTOR
	JOHN BOSH BUS INCORPORATED
40	DIANA LOBOSCO
	DORA VAC
44	OCCUPANT UNKNOWN
50	BROOKE MCMULLEN
	PAUL BERTUGLIA
	RYAN HENRY
	SARA ORLANDO
54	GATEWAY LIFE CENTER
70	GARGIULO CHRISTOPHER E CPA
76	ROBERT GREGORY
77	JOHN MOTT
80	CROSS COUNTY FUEL OIL CO
	DAISY DELGADO
81	PETER LEVOCI
84	CHRISTOPHER BRANDER
	DOUG DALE
	GARY BURKHARDT
	THOMAS LIPERA
85	CARL ANDERSEN
97	SEAN MELOW

<u>Target Street</u> <u>Cross Street</u> <u>Source</u>
- Cole Information Services

10	CENTER FOR COMMUNICATION CARE
21	HOFFMAN LISA
	UNITED METHODIST CHURCH
22	ROBERT PAXTON
25	MICHAEL OCONNOR
	MICHELLE SARDELLI
27	FRED WISENHIMER
29	JOE BOB
31	OCCUPANT UNKNOWN
38	CARLIN ROBERT
39	CESAR BISCARR
51	COURTNEY KALETA
53	AUTOMATIC LAWN SPRINKLERS BY WATER K
	CHRISTIN MONTANI
	DAVID MACHOLZ
	JASON MCDERMOTT
57	SHERYL FEIG
60	EDWARD KING
61	JOSEPH LATERZA
	MEREDITH LUPION
62	STEVEN SAGANICK
64	LAUREN AMBROSIO
67	OCCUPANT UNKNOWN
68	L STEIN

<u>Target Street</u> <u>Cross Street</u> <u>Source</u>

✓ - Cole Information Services

16	ROBERTO GONDOLA
18	JUDY VARGAS
38	NAAVAH SCHNEIDER
40	SCOTT WEBB
44	STEPHEN KING
50	OCCUPANT UNKNOWN
	PAUL BERTUGLIA
	SUE VOLKMAN
	VALERIE BAUGH
54	BABYLON ASSEMBLY OF GOD CHURCH
	GATEWAY LIFE CENTER
76	ROBERT GREGORY
77	JOHN MOTT
	MOTT JOHN A PLUMBING & HEATING
80	RUSSELL BUCCINO
81	PETER LEVOCI
84	DOUG DALE
	GARY BURKHARDT
	RONALD SUNDIN
85	CARL ANDERSEN
97	JAN MELOW

<u>Target Street</u> <u>Cross Street</u> <u>Source</u>
- Cole Information Services

1	CHARLES CAVATICA
10	CENTER FOR COMMUNICATION CARE
21	LISA HOFFMAN CSW
	METHODIST CHURCH OF BABYLON
	NEW YRK ANNUAL CNF UN MTH C
	UMC NURSERY SCHOOL
22	ROBERT PAXTON
25	MICHAEL OCONNOR
	RICHARD WITTHOHN
27	SEGUNDO ZAMBRANO
29	PEDRO LEMOS
31	OCCUPANT UNKNOWN
35	CRAIG CONDRA
38	BABYLON MEDICAL LASER PC
	ROBERT L CARLIN MD PC
39	CESAR BISCARR
	LINDA SHAY
51	RICK KALETA
53	CHRISTIN MONTANI
57	SHERYL FEIG
60	CHARIOT LIMOUSINE
	EDWARD KING
61	JAMES CALDERARO
	MEREDITH LUPION
	SHAWN MCGARVEY
62	STEVEN SAGANICK
64	DIANA KOLLMEIER
67	ANTHEA ANTHROS
68	L STEIN

<u>Target Street</u> <u>Cross Street</u> <u>Source</u>

✓ - Cole Information Services

10	NEW BABYLON SERVICE CTR
	OCCUPANT UNKNOWN
16	ROBERTO GONDOLA
18	OCCUPANT UNKNOWN
34	ROBERT PHILLIPS
	SUSAN PHILLIPS
38	CHRIS DALLESSANDRO
	SHAWN RICHTER
	TODD WALLACE
40	CHARLES BOVE
44	DOROTHY PULLIS
50	BARRY CRONIN
	OCCUPANT UNKNOWN
	PAUL BERTUGLIA
	VICTORIA BRAIDOTTI
54	BABYLON ASSEMBLY OF GOD CHURCH
00	OCCUPANT UNKNOWN
60	ANDREW BELLO
70	PLANET NET MEDIA
70	CHRISTOPHER GARGIULO
70	GARGIULO CHRISTOPHER E CPA
72 70	BRIAN PHAIR
76	ROBERT GREGORY
77	JOHN MOTT
00	MOTT JOHN A PLUMBING & HEATING NINA VILLAFANE
80 81	DANIEL PEREZ
84	ANDREW CATHEART
04	CECELIA BRANDER
	DOUG DALE
	RONALD SUNDIN
	WILLIAM KESSINGER
85	CARL ANDERSEN
97	JAN MELOW
31	OAIN WILLOW

<u>Target Street</u> <u>Cross Street</u> <u>Source</u>
- Cole Information Services

10	CTR FOR COMMUNICATION CARE
	MICHAEL TONN
	OCCUPANT UNKNOWN
21	HOFFMAN C LISA
	OCCUPANT UNKNOWN
	UNITED MTHDST CHRCH NRSRY SCHL
	UNITED MTHDST CHRCH OF BBYLN
25	JOHN DILLON
	WILLIAM OCONNOR
27	CHARLOTTE BRUSHETT
29	TERENCE BENNETT
31	CLAUDIO ARIAS
35	GERALDINE CONDRA
38	LAN SOLUTIONS INC
	OCCUPANT UNKNOWN
39	LINDA SHAY
43	ROBERT LINEKIN
	ROLIN PRODUCTIONS LIMITED
51	RICK KALETA
53	ATMTC LWNSPRNKLR BY WATER KI
	C MONTANI
	MARYBETH IMPAGLIAZZO
57	SHERYL FEIG
60	STEVEN SAGANIC
62	STEVEN SAGANICK
64	DIANA KOLLMEIER
67	RAYMOND AUER
68	L STEIN
	WEST ISLIP TEACHERS ASSOC

<u>Target Street</u> <u>Cross Street</u> <u>Source</u>

✓ - Cole Information Services

10 16 18 54 70 97	NEW BABYLON SERVICE CENTER OCCUPANT UNKNOWN OCCUPANT UNKNOWN BABYLON ASSEMBLY OF GOD CHURCH GARGIULO & COMPANY CPA NY CPA OCCUPANT UNKNOWN

<u>Target Street</u> <u>Cross Street</u> <u>Source</u>
- Cole Information Services

	JAMES ST 1999
10 21	WITHERS ENGELKE & ASSOCIATES INCORPORATED HOFFMAN LISA CSW METHODIST CHURCH OF BABYLON
31 38	SAVAGE JACK E REV UNITED METHODIST CHURCH NURSERY SCHOOL UNITED METHODIST CHURCH OF BABYLN OCCUPANT UNKNOWN LAN ASSOCIATES
43 53	MAXMEDIA AUTOMATIC LAWN SPRINKLERS BY WATER KING WATER KING AUTOMATIC LAWN SPRINKLERS DEBORAH OCASIO
62	OCCUPANT UNKNOWN

<u>Target Street</u> <u>Cross Street</u> <u>Source</u>

✓ - Cole Information Services

10 54 70	NEW BABYLON SERVICE CENTER BABYLON ASSEMBLY OF GOD CHURCH GARGIULO & COMPANY, CPA

<u>Target Street</u> <u>Cross Street</u> <u>Source</u>
- Cole Information Services

	JAMES ST 1995
10	WITHERS ENGELKE & ASSOCS INC
21	METHODIST CHURCH OF BABYLON
	SAVAGE, JACK E
	UNITED METHODIST CHURCH OF BABYLN
38	LAN ASSOCIATES
43	MAXMEDIA
51	BABYLON BONSAI CO
53	AUTOMATIC LAWN SPRINKLERS BY WATER KING
	WATER KING AUTOMATIC LAWN SPRINKLERS

<u>Target Street</u> <u>Cross Street</u> <u>Source</u>

✓ - Cole Information Services

10	BABYLON SVCE CENTER
34	PHILLIPS, ROBERT B
38	IANNARONE, DOLORES
40	ANCONA, AGNES
44	PULLIS, J G
50	DOPP, MICHAEL
54	BABYLON ASSEMBLY OF GOD CHURCH
60	WINSTON, H
72	MCNANEY, CLEMENT M
76	MC GRANE, FRANCIS J
77	MOTT, JOHN & BARBARA
84	ALTENBURG, C
	DORMER, JAMES
	LENDIN, V
	RILEY, RONALD E
85	ANDERSEN, CARL
97	BRANDT, LEEANN
	MC LOUGHLIN, GLORIA

<u>Target Street</u> <u>Cross Street</u> <u>Source</u>
- Cole Information Services

10	EILEEN'S COLLECTIBLES
12	DYNAMAR OVERSEAS INC
	GEORGE ASPLAND ASSOCS INC
21	METHODIST CHURCH OF BABYLON
	SAVAGE, JACK E
	UNITED METHODIST CHURCH OF BABYLN
25	MCCULLAGH, MARY
	MCMENEMY, B
	SANDERS, CARLA
29	MONTERO, MARIA
31	FARIAS, JUANA
35	CONDRA, PAUL
	FRANCE, BILL
	GRAUER, DAVID
38	LAN ASSOCIATES
39	BISCARR, CESAR
	SHAY, EVELYN P
43	MAXMEDIA
45	SCHMIDT, GRETCHIN
51	BABYLON BONSAI CO
	KALETA, RICK & ELAINE
53	AUTOMATIC LAWN SPRINKLERS BY WATER KING
	WATER KING AUTOMATIC LAWN SPRINKLERS
	WISSING, ROBERT
60	REILLY, GERALD
61	PALAZZO, CHRISTINE
	RIVERA, C
62	CHESSMAN, EDWARD
64	MC NAMARA, J & L
67	AUER, RAYMOND
	GOLSONG, J
	WOOD, GWENDOLYN


<u>Target Street</u> <u>Cross Street</u> <u>Source</u>


✓ - Cole Criss-Cross Directory


		GEORGE 31 1970	
7	NO #	LEONARD W KEER -473279	5
7	140 %	3 RESIDENCE	
1	_	o weather	
6		GEORGE RD 1195	5 .
63574			
5		NEW SUFFOLK P 0	
7		1- END T 1700 SDU	3
4	200	JOHN H ASHER -734526	9
5	NO #	JOHN H ASHER -734526	8
5		2 RESIDENCE	
2			
-		GEORGE ST 1170:	2
		GEORGE ST 1170	
4		BABYLON P O	
		1- END T 124602 \$8 E	9
	18	THOMAS BAKER 5 669132	8
	19	JEANNE BEAUDET 2 JU7415	6
7	200	JEANNE BEAUDET 2 JU7415	3
	7-1-7	E RAHNER 7 587160	7
3	21	M MILLER 0 661594 E RAHNER 7 587160 M E DOWNS 3 JU7267	8
4		FRANK SCHIEBELHUTH	
		6 587699	8
	34	MRS C OSHAUGHNESSY	
4		5 MO9739	
•	38	ROBERT HIGGINS #669842	
	40	C SOPER MO9438	
3	43	JOHN GOTTSCH 0 587827	
3		ADOLPH STEIN MO9303	
8	10.0	V TAYLOR #669160	8
2	44	J G PULLIS M09226	2
	50	MRS A D KETCHAM SR M09216	
9		G E NUNAMAKER 0 669786	
7		*ST NICHOLAS GREEK JU7115	
1	60	JOHN N CODE SR 0 587382	2
4		L A DACEY 0 587737	3
9		L A DACEY 0 587737; R JAKOBI M09083 A ULRICH 9 661551	-
0	701	*F J GALLAGHER ATTY MO9303	4 .
2		CLEMENT M MCNANEYO 669236	
5	76	FRANCIS MCGRANE 8 587249	5 6
3		MABEL REINHOLZ 8 587081	
5	84		^
3 5 8		BPAUL ARENA 669642	9
_		CARNOLD PARENGKUANO 661663	
		D NP	
6	,	MRS M CAMPAGNOLI MO9060	5
		LOUIS MILAZZO JR #669531	
		28 RESIDENCE 2 BUSINES	
2			
1		GEORGE ST 1177	2
5			
4		EAST PATCHOGUE	
2		PATCHOGUE P 0	
2154210		1- END T 159202 SCN	6
0	12		
9	15	NP	
	28		
		4 AT6223	
1	43		
		DWAIN WHITE 8 286878	
	50	BARRY L ZIMMERMAN -286020	9


Target Street Cross Street Source
- Cole Criss-Cross Directory


	JAIVIES ST 1970	
	11 RESIDENCE 1 BUSINESS	
	JAMES RD 11701	
		4
1	AMITYVILLE P D	ш
2	4 R LE BOURDAIS 5 8423827	П
9	6*SMI THESONS BOAT TRE8429369	П
8	8 ROBERT SCHAVEL 0 8420707	
6	10 KENNETH J WYMAN SR 8423468	
6	12 JACOB A JACOBSEN 2 8422126	
637	14 C J CHARLEY JR 9 8421746 16 WILLIAM NICLAS 6 8420149	ľ
7	NO # JOHN F TRIHY AM42398 7 RESIDENCE 1 BUSINESS	
5	7 RESIDENCE 1 BUSINESS	
6	IAMES ST 11702	П
57032	JAMES ST 11702	
2	BABYLON P O	
	1- END T 124602 \$8E 9	
1	10*DOROTHEAS BTY SALN JU71174	
6	12*DR DAVIS POLLACK MO97777 13*CO HI SCH ATHL ASN-5877600	
7	21 METH CHR OF BABYLN 6615151	
67583	*METHODIST CHURCH #6619517	
8	*METH CHR OF BABYLN MO19698	
3	*REV JACK E SAVAGE 6615151	
	25 FRANK J PENNA M095606 MORRIS WOLF 6 6615645	
0	27 CATHERINE SIMONSON#5871418	
	31 CARLOS GONCALVES 6 5878409	
025	35 M GIARRATAMO 9 5872918 38*WEIGHT WATCHERS -5874500	
5	39 ARTHUR BROOKS 2 MD94102	Н
-	39 ARTHUR BROOKS 2 M094102 1 THORSEN 5 6694333	
9	45 MRS EDNA A WEEKS MO90834	Г
•	51 C MCCREERY 8 6697015 53 DONALD CAVNA 9 5871609	
	53 DONALD CAVNA 9 5871609 H HEMENDINGER MO10473	
4	57 MARION M BAXTER 0 M094481	
3	60 IGNACIO COTTO 5 6695473	ľ
9	61 NP	
651	62 PAULA HANCE -6694669 64 JACK LEVY 2 6691335	
1	CARLOS NEIRA 8 5873821	
1	67 D ROCCO #5878876	
5	68 NP	
8	19 RESIDENCE 8 BUSINESS	
5	JAMES ST 11706	
5		
0	BAY SHORE P 0	
5	*** 1- END T 146003 \$DF 7 2 L MOSCHERA 7 6666027	
0555	2 L MOSCHERA 7 6666027 4 ROBERT P CORCORAN MOS1859	
	5 EDWARD T COLGAN MOS1691	
O	7 CLIFFORD LEWIS 6 6653078	
	4 RESIDENCE	
5	JAMES ST 11746	
	HUNTINGTON STA P 0	
7	1- END T 1114 \$AC 4	



















1947 Aerial Photograph



1962 Aerial Photograph



1978 Aerial Photograph



1984 Aerial Photograph



2001 Aerial Photograph



2013 Aerial Photograph

/ Undergr	round Storage	TAHK TESU	ng and Aba	<u>ndomnem 1</u>	mormau

PRO TEST ENVIRONMENTAL

PRECISION TIGHTNESS TESTING of UNDER & ABOVE GROUND PETROLEUM STDRAGE TANKS INSTALLATIONS & REMOVALS * ABANDONMENTS * SOIL SAMPLING & LABDRATORY ANALYSIS * CONSULTATION SERVICES

P.O. Box 1937 West Babylon, NY 11704 LI Telephone: (631) 321-4670 Fax: (631) 539-0822 NYC Telephone: (718) 815-6292

July 24, 2014

Middleton Environmental 50 Park Avenue Babylon, NY 11702

To Whom It May Concern:

Let this letter certify that on July 23, 2014 Pro Test Environmental legally abandoned in place one 550 gallon #2 fuel oil underground storage tank at 54 George Street, Babylon NY 11702 using sand.

All work was performed according to and in compliance with New York State Department of Environmental Conservation and County Health Department specifications. Any further requests for information may be directed to the main office at the phone number below. Thank you.

Respectfully

Patrick Glier

Operations Manager

Pro Test Environmental

Pro Test PRECISION TESTING OF UNDERGROUND TANKS P. O. Box 1937

West Babylon, N.Y. 11704 Tel: 631-321-4670 Fax: 631-539-0822

EZY 3 LOCATOR MANUFACTURED BY: E	The second second	77-368-7215	TIGHTNESS TEST REPORT
DATE 10	-28-2013	P	BS # (NEW YORK)
TOTAL TANK VOL	1,000	gal T	ANK # 001 (#2 F.O-UST 5/W)
PRODUCT VOL	72	gal L	OCATION 54 GEORGE STREET
ULLAGE VOL	928	gal	BABYLON - SUFFOLK CO
PRODUCT TYPE #	2 FUEL OIL		14-11702 -
Tight Tank THIS FUEL OF PASSES THE ULLAGE (DR. THIS FUEL OF FAILS THE COMPANDED THIS FUEL OF TH	CRITERIA SET FORT Y) PORTION LEAK	TANK & SY TH BY THE U.S. TANK & SY BY THE U.S. E PORTION LEAK TANK & SYS	TANK ONLY TEM TANK ONLY TANK ONLY
			NSOR INDICATES: K ONLY ONE)
NO WATER INTRUSION	WATER INT		NOT APPLICABLE (X)
OPERATOR NAME:	Print A. Lopez		SignSign
	Certification #82	-7683	Expiration Date May 11, 2015
<u>Equipment</u>	Serial Nu	mber	Calibration Expiration Date
Pressure Senso *New York State Requirer	Probe	2 / M0745002 1009 nk system must be	July 2014 March 2014 / Sept 20 October 2014 November 2014 submitted to the State with this report. hat Agency. If test is for NYS D.E.C. include your PBS #

EZY 3 LOCATOR PLUS

Date 10-28-2013

PRESSURE CALCULATIONS & WATER SENSOR CALIBRATIONS & Tank ID# 001 Location 54 GEORGE

STREET - BABYLON -SUPFOLE CO-MY-11702

Duore = # 2 Ever on (1,000 6/5 ust s/w)

PRESSURE SENSOR CALCULATION 0.186 0.031 PSI (1) WEIGHT OF PRODUCT INCHES OF PRODUCT 0.036 PSI (2) INCHES OF WATER IN TANK 0.222 PSI (3) Line 1 + Line 2 = Total Positive Head Pressure in tank O X 036 PSI (4) INCHES OF WATER OUTSIDE TANK 0.222 +/-PSI(5) Total Head Pressure Minus Outside Water Pressure 0.50 PSI (6) Always add .5 PSI NOTE: If line 6 is Less Than .5 PSI Line 7 Shall be .5 PSI 0.722 +/-PSI(7) TEST PRESSURE TIME PRESSURE Blower Started: 09:00 0.000 09:15 Depth of Groundwater Determined: Test Pressure Reached: 0.722 BY: SMART STICK PROBE 00:20 0.745 Blower Turned Off: Where: IN THE SAME 09:20 0.745 Test Began: EXCOUNTION TO THE TK .. 0.720 09:35 Test Ended:

WATER SENSOR CALIBRATION	1	_ ^ ^	
Added:		Height 18 "	
Average: Water Intrusion Test Period: Began:	Product in	Bottom	
Ended:	<u>6</u> "	to Grade	
Calculation for Test Period:	Water in	Diam.	Groun Water +80
$\frac{-}{\text{Avg. Cal.}} + 3780 = \frac{-}{\text{"A" Factor}} + .05 = \frac{-}{\text{Time of Test}}$	Tank	48	\leftarrow